**Adrenaline Diesel** 

13019 - 151 Street NW Edmonton, AB T5V 1A7, CA info@adrenalinediesel.ca (780) 907-1965 ADREN LINE

Invoice:

6653

Date:

1/15/2024

**Bill To** 

R BATKE OILFIELD LTD

P: 780-812-0211

| Pol  | I Dall |
|------|--------|
| PS 5 | 0186   |

| Service Order | Terms  | Due Date  | Authorizer  | Customer PO | Service Writer  | Unit#  |
|---------------|--------|-----------|-------------|-------------|-----------------|--------|
| 5852          | COD    | 1/15/2024 | RANDY BATKE |             | Lafond, Richard | 131    |
| Item Descr    | iption |           |             | Qua         | antity Rate     | Amount |
|               |        |           |             |             |                 |        |

| Inspection |   |          |        |
|------------|---|----------|--------|
| Labor      | UNDER HOOD CHECKLIST: Items to check BEFORE any unit leaves the shop Assigned tech(s): Lucas Hilliard | 00000    | \$0.00 |
|            |   | Subtotal | \$0.00 |

Complaint: DIAGNOSE FOR BAD KNOCKING FROM ENGINE

Cause: Towed truck into shop, remove air intake pipes to pull valve cover off, found a missing valve bridge on cylinder number 3 exhaust, removed rocker assemblies to find that exhaust valves for number 1 and 3 cylinder are sticking.

Labor

Correction:

3.00000

\$160.00

\$480.00

Engine / Top End / Removed valve cover to find missing exhaust bridge on cylinder 3, valves were sticking on cylinder 3 - Completed: 1/3/2024 - Assigned

tech(s): Lucas Hilliard

Subtotal

\$480.00

Complaint: remove and replace head

Cause: Customer request

(Inspection)

Labor

Correction:

35.00000

\$160.00

\$5,600.00

Engine / Top End / Pull intake pipes off to remove valve cover, next remove rockers then remove rad and fan hub to access the cams. remove front cover and pull cam gears off cams. remove turbo and split egr cooler from head, next pull ecm and wiring out of the way and remove the fuel pump from the side of the head, finally pull the coolant line off the back of the head and lift head off engine, upon inspection all pistons and cylinders look good. next remove the oil pan to inspect for metal filings or pieces that could have came from the missing valve bridge. - Assigned tech(s): Chase Denomme-McKibbin, Ethan Casault,

Lucas Hilliard

| ltem         | Description   | Quantity | Rate       | Amount      |
|--------------|---|----------|------------|-------------|
|              | found that oil was metallic in color and that there were a few small pieces of metal in the oil pan as well as stuck to the pickup tube. pulled number 1,4,7 main bearing caps to inspect mains, and oil pump. main bearings where in good condition for reuse, oil pump was scared up and grooved pretty bad Completed: 1/3/2024 |          |            |             |
| Parts        | Head - 5658283PXCUM   | 1.00000  | \$8,373.71 | \$8,373.71  |
| Parts        | Inherent Core for Head - 5658283PXCUM   | 1.00000  | \$198.00   | \$198.00    |
| Parts        | Dirty Core for Head - 5658283PXCUM  | -1.00000 | \$198.00   | -\$198.00   |
| Parts        | 4.00-4.31 T-BOLT CLAMP - 38-0371  | 1.00000  | \$25.16    | \$25.16     |
| Parts        | Injector cam gear hold down plate - 2869656CUM  | 1.00000  | \$121.98   | \$121.98    |
| Parts        | CAMSHAFT MODIFIED, VALVE CUMMINS (870, 871, 2250, 2350 & 2350X) - 3688242 MOD   | 1.00000  | \$2,800.00 | \$2,800.00  |
| Parts        | Head gasket kit - 4352145CUM  | 1.00000  | \$2,483.32 | \$2,483.32  |
| Parts        | Thermostat - 4318947CUM   | 1.00000  | \$156.17   | \$156.17    |
| Parts        | exhaust bridge - 4059329CUM   | 1.00000  | \$59.59    | \$59.59     |
| Parts        | front intake rocker - 5484230CUM  | 2.00000  | \$263.87   | \$527.73    |
| Parts        | Rear intake rocker - 5484231CUM   | 2.00000  | \$278.68   | \$557.36    |
| Parts        | CAC cooler - CAC61-1024TRP  | 1.00000  | \$1,199.85 | \$1,199.85  |
| Parts        | air filters - AF252547  | 2.00000  | \$130.91   | \$261.82    |
| Parts        | fan belt - D84-1000-3122295   | 1.00000  | \$181.73   | \$181.73    |
| Parts        | a/c belt - D84-1000-3061620   | 1.00000  | \$98.39    | \$98.39     |
| Parts        | oil pump - 5680039RXCUM   | 1.00000  | \$1,390.27 | \$1,390.27  |
| Parts        | Inherent Core for oil pump - 5680039RXCUM   | 1.00000  | \$198.00   | \$198.00    |
| Parts        | Dirty Core for oil pump - 5680039RXCUM  | -1.00000 | \$198.00   | -\$198.00   |
| Parts        | SEAL, O-RING - 3678756  | 1.00000  | \$15.66    | \$15.66     |
| Parts        | Oil Pan Gasket, Cummins - M-4026684   | 1.00000  | \$279.05   | \$279.05    |
| Parts        | LUBE FILTER - LF14000NN   | 1.00000  | \$85.30    | \$85.30     |
| Parts        | APEX RED PAINT, CUMMINS - 3163075   | 1.00000  | \$59.36    | \$59.36     |
|              |   |          | Subtotal   | \$24,276.45 |
| Complaint:   | CUT COUNTERBORES  |          |            |             |
| Cause: Cus   | stomer request  |          |            |             |
| (Inspection) |   |          |            |             |
| Labor        | Correction: Engine / Top End / Remove cooling jets to avoid damaging the jets, next remove the rod caps and pistons to install liner removal tool removing liners. then cut counterbores - Completed: 1/3/2024 - Assigned tech(s): Lucas Hilliard   | 9.37500  | \$160.00   | \$1,500.00  |
| Parts        | Piston rings - 5633496CUM   | 6.00000  | \$458.44   | \$2,750.64  |
| )            |   |          | Subtotal   | \$4,250.64  |

|  | Description   | Quantity                                 | Rate                                      | Amount   |
|--|---|--|---|--|
| Complaint  | : Remove/ install piston and liner for cutting counterbores   |  |   | //   |
| Cause: Co  | ustomer request   |  |   |  |
| (Inspection  |   |  |   |  |
| Labor  | Correction: Engine / Top End / Removed liners and pistons to find that the liner shelves were tapered causing the liner to sit to low on the exhaust side Completed: 1/3/2024 - Assigned tech(s): Christian Schram, Lucas Hilliard  | 4.00000                                  | \$160.00                                  | \$640.00   |
| Parts  | 0.030 liner shim - 5298565CUM   | 6.00000                                  | \$281.79                                  | \$1,690.74   |
| Parts  | captive liner shims - 4311637   | 6.00000                                  | \$167.04                                  | \$1,002.24   |
| Parts  | liner orings - 3678738CUM   | 2.00000                                  | \$35.17                                   | \$70.34  |
| Parts  | nozzle, piston cooling - 3687058  | 6.00000                                  | \$36.56                                   | \$219.36   |
| Parts  | SEAL, O-RING - 3678738  | 4.00000                                  | \$26.16                                   | \$104.64   |
|  |   |  | Subtotal                                  | \$3,727.32   |
| Complaint  | SUBLET FOR DYNO AT CUMMINS JAN 3RD  |  |   |  |
| Cause: Cu  | stomer request  |  |   |  |
| (Inspection  |   |  |   |  |
| Labor  | Correction: Chassis / Chassis / - Completed: 1/3/2024 - Assigned tech(s): Lucas Hilliard  | 0.00000                                  |   | \$0.00   |
|  |   |  |   |  |
| Labor  | DYNO  | 1.00000                                  | \$608.78                                  | \$608.78   |
| Labor  | DYNO  | 1.00000                                  | \$608.78<br>Subtotal                      | \$608.78<br>\$608.78                                   |
|  | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO  | 1.00000                                  | 169                                       |  |
| Complaint  |   | 1.00000                                  | 169                                       |  |
|  | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO  | 1.00000                                  | 169                                       |  |
| Complaint<br>Cause: Ըւ                                   | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO  | 2.50000                                  | 169                                       |  |
| Complaint Cause: Cu (Inspection Labor                    | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO stomer request  Correction: Engine / Exhaust / Removed all clamps from old exhaust, when i was removing the exhaust to remove the transmission 2 of the 5 inch flex pipes split, upon inspection, they where extremely corroded, which is most likely why the split. Using new flex pipe i fixed the damaged piping. removed pipe from turbo, found a damaged clamp and the flex pipe was splitting open, corroded as well. using new clamp and flex pipe, i repaired he damaged section and replaced the pipe on the engine Completed: 1/15/2024 - Assigned tech(s): Chase Denomme-   |  | Subtotal                                  | \$608.78   |
| Complaint Cause: Cu (Inspection Labor                    | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO stomer request  Correction: Engine / Exhaust / Removed all clamps from old exhaust, when i was removing the exhaust to remove the transmission 2 of the 5 inch flex pipes split, upon inspection, they where extremely corroded, which is most likely why the split. Using new flex pipe i fixed the damaged piping. removed pipe from turbo, found a damaged clamp and the flex pipe was splitting open, corroded as well. using new clamp and flex pipe, i repaired he damaged section and replaced the pipe on the engine Completed: 1/15/2024 - Assigned tech(s): Chase Denomme-McKibbin   | 2.50000                                  | \$160.00                                  | \$608.78<br>\$400.00                                   |
| Complaint Cause: Cu (Inspection Labor Parts              | Correction: Engine / Exhaust / Removed all clamps from old exhaust, when i was removing the exhaust to remove the transmission 2 of the 5 inch flex pipes split, upon inspection, they where extremely corroded, which is most likely why the split. Using new flex pipe i fixed the damaged piping. removed pipe from turbo, found a damaged clamp and the flex pipe was splitting open, corroded as well. using new clamp and flex pipe, i repaired he damaged section and replaced the pipe on the engine Completed: 1/15/2024 - Assigned tech(s): Chase Denomme-McKibbin  5" FLEX GALV. / FT - G15-5120   | 2.50000                                  | \$160.00<br>\$18.82                       | \$608.78<br>\$400.00                                   |
| Complaint Cause: Cu (Inspection _abor  Parts Parts Parts | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO stomer request  Correction: Engine / Exhaust / Removed all clamps from old exhaust, when i was removing the exhaust to remove the transmission 2 of the 5 inch flex pipes split, upon inspection, they where extremely corroded, which is most likely why the split. Using new flex pipe i fixed the damaged piping. removed pipe from turbo, found a damaged clamp and the flex pipe was splitting open, corroded as well. using new clamp and flex pipe, i repaired he damaged section and replaced the pipe on the engine Completed: 1/15/2024 - Assigned tech(s): Chase Denomme-McKibbin  5" FLEX GALV. / FT - G15-5120  4" FLEX PIPE / FT - SSH40025  | 2.50000<br>4.00000<br>2.00000            | \$160.00<br>\$18.82<br>\$82.94            | \$608.78<br>\$400.00<br>\$75.28<br>\$165.88            |
| Complaint Cause: Cu                                      | REPAIR FOR EXHAUST LEAKS AT FLEX PIPE BEHIND TURBO stomer request  Correction: Engine / Exhaust / Removed all clamps from old exhaust, when i was removing the exhaust to remove the transmission 2 of the 5 inch flex pipes split, upon inspection, they where extremely corroded, which is most likely why the split. Using new flex pipe i fixed the damaged piping. removed pipe from turbo, found a damaged clamp and the flex pipe was splitting open, corroded as well. using new clamp and flex pipe, i repaired he damaged section and replaced the pipe on the engine Completed: 1/15/2024 - Assigned tech(s): Chase Denomme-McKibbin  5" FLEX GALV. / FT - G15-5120  4" FLEX PIPE / FT - SSH40025  4" SS TORCTITE LAP CLAMP - NEL 90366B | 2.50000<br>4.00000<br>2.00000<br>1.00000 | \$160.00<br>\$18.82<br>\$82.94<br>\$21.69 | \$608.78<br>\$400.00<br>\$75.28<br>\$165.88<br>\$21.69 |

| Item       | Description   | Quantity | Rate       | Amount     |
|------------|---|----------|------------|------------|
| Complair   | nt: REPAIR FOR LEAKING REAR STRUCTURE   |          |            |            |
| Cause: (   | Customer request  |          |            |            |
| (Inspectio | on)   |          |            |            |
| Labor      | Correction: Engine / Lubrication / Removed shifter assembly, shifter cover and all air lines running to transmission. drained coolant, removed hoses to transmission cooler. removed exhaust and front and rear driveshafts. removed PTO from bottom of transmission. drained transmission oil and engine oil. removed all bellhousing bolts except two. took out bolts for inspection hole and removed clutch plate mounting bolts two at a time while turning engine over by hand. Installed transmission jack, strapped transmission to jack and then removed remaining bellhousing bolts Assigned tech(s): Chase Denomme-McKibbin, Quinlen Pederson unhooked positive battery cables and removed starter from flywheel housing. Removed oil pan and jacked up engine to remove rear engine mounts. removed flywheel housing and cleaned gasket surface. installed new gasket and torqued bolts to spec with torque pattern provided by cummings, lowered engine onto mounts and installed bolts, siliconed cracks for rear and front housings and installed oil pan with provided torque and pattern. installed starter back on flywheel housing.  and hooked up battery. cleaned transmission while the flywheel was sent out to be machined. put on new compression fittings for the air lines. Four of the ten mounting screws for the shifter cover had to be extracted as the heads were stripped. cleaned all mounting surfaces. installed new clutch brake and clutch plate on transmission and installed new transmission on unit. installed PTO on transmission using shims to set the backlash, greased all u-joints, installed driveshafts and torqued u-joint bolts to 159 ft lbs Installed exhaust, installed new transmission coolant hoses as old ones were worn out. installed shifter cover with new bolts. filled with old coolant and added 8 L, filled with new engine oil, and transmission oil. installed new block heater and oil heater cord. ran unit and checked over work Completed: 1/15/2024 | 20.00000 | \$160.00   | \$3,200.00 |
| Parts      | SYN 50 TRANS FLUID/ L - PPL SYN-50-208  | 13.00000 | \$13.39    | \$174.07   |
| Parts      | COOLANT CONCENTRATE, HD EXPERT RED - IM2-26-739-1000  | 8.00000  | \$5.17     | \$41.36    |
| Parts      | HDEO Mobil Delvac Oil 15W40 BW - 125152   | 38.00000 | \$6.75     | \$256.50   |
| Parts      | PTO Mounting Shim .010 8 Hole - 35P15-1   | 1.00000  | \$4.31     | \$4.31     |
| Parts      | GASKET, SHIFT TOWER - 4305294   | 1.00000  | \$26.66    | \$26.66    |
| Parts      | 2 PC CLUTCH BRAKE - CB200SB   | 1.00000  | \$65.24    | \$65.24    |
| Parts      | CLUTCH - 308925-25CA  | 1.00000  | \$1,755.52 | \$1,755.52 |
| Parts      | U-JOINT STRAP KIT - 170-70-18X  | 2.00000  | \$43.84    | \$87.68    |
| Parts      | REAR CRANK SEAL - 4965569CUM  | 1.00000  | \$213.76   | \$213.76   |
| Parts      | REAR STRUCTURE SEAL - 4393176CUM  | 1.00000  | \$191.06   | \$191.06   |
| Parts      | Cam position speed sensor - 5491994cum  | 1.00000  | \$150.38   | \$150.38   |
| Parts      | Y cord for block heater - 8608059   | 1.00000  | \$278.81   | \$278.81   |
| )          |   |          | Subtotal   | \$6,445.35 |

| Item                         | Description   | Quantity  | Rate              | Amount      |
|------------------------------|---|-----------|-------------------|-------------|
| Cause: Cus                   | stomer request  |           |                   |             |
| (Inspection)                 |   |           |                   |             |
| Labor                        | Correction: Engine / Bottom End / - Completed: 1/12/2024 - Assigned tech(s): Lucas Hilliard | 0.00000   |                   | \$0.00      |
| Labor                        | resurface flywheel  | 1.00000   | \$146.40          | \$146.40    |
|                              |   |           | Subtotal          | \$146.40    |
|                              | IN: 1NPFD40X57D678936   |           | Labor             | \$12,575.18 |
| 2007 Peterbi<br>Chassis: 1.5 | lt 378<br>560,258 Kilometers  |           | Parts             | \$28,147.71 |
| ,,,                          |   | Sho       | p Supplies        | \$500.00    |
|                              |   | Pre-Charg | e Subtotal        | \$41,222.89 |
|                              |   | (5% of \$ | GST<br>(41,222.89 | \$2,061.14  |
|                              |   |           | Total             | \$43,284.03 |
|                              |   | Payments  | & Credits         | \$0.00      |
|                              |   | Ва        | alance Due        | \$43,284.03 |

Adrenaline Diesel recommends that ALL engine projects be subject to Dyno prior to release. Dyno fees will be applied to all engine projects once completed. Customer acknowledged that by declining Dyno service, warranty may be forfeit.

Shop Supplies of up to \$700 are applicable to all service estimates even if not noted. Additional fees for fluids and testing may apply. ALL engine projects are subject to Dyno prior to release. Dyno fees may be over and above the estimate provided.

PARTS: Special Order parts may be subject to freight fees, may require a deposit and are final sale. Parts kits must be returned complete. Returns of partial kits will not be accepted. Kits must be in resalable condition. All Parts must be sent back in resalable, original packaging to qualify for credit. Cores must be returned within 30 days to be eligible for credit. Core charges will be refunded to the Customer only when the Supplier / Manufacturer accepts the core and issues credit.

Projects involving Customer supplied parts and components are subject to a 15% Parts Handling Fee that will be applied to the subtotal of the job.

Returns will not be accepted, nor processed, without a Returned Goods Authorization (RGA). Materials received without an authorized RGA will be returned to the sender at the sender's cost. Returns are subject to a minimum 15% restocking fee. Kits must be returned complete and unopened. Electronic components, used parts, and parts returned in non-saleable conditon will not be accepted. Please verify with your Representative prior to purchase and prior to return.

STORAGE: Units must be authorized for repair within 48 hours of notification. After 48 hours, storage fees of \$50 / day will apply. After 7 days, Adrenaline Diesel reserves the right to remove the unit and all associated parts from our shop. Adrenaline Diesel is not responsible for loss or damage to units that are removed from our premises. Units that have been left for more than 90 days will be considered abandoned. Adrenaline Diesel is not responsible for loss or damages to vehicles remaining after 48 hours of completion. Customer acknowledges that units left for more than 48 hours after completion will be subject to additional costs for any assistance required to get the unit started. Vehicles left for more than 48 hours after completion are subject to storage fees at a minimum fee of \$50 per day.

WARRANTY: Adrenaline Diesel honors manufacturer warranty. 1 year Parts & Labour warranty from original repair commencement date unless otherwise specified. Full Warranty details are available at www.adrenalinediesel.ca/warranty.

Adrenaline Diesel is not responsible to ensure compliance of regional regulations.

Account terms are Net 30 days. Interest of 2.4% per month may be accrued and on accounts over 30 days. Warranty is subject to suspension or termination on services that are not paid within 90 days of invoice date.

Acceptable payment methods include: Cash, Visa, Mastercard, EFT, wire transfer, certified cheque, bank draft, and Company cheque accompanied by Credit Card Number. Credit card transactions are subject to a processing fee of 2.5% of the amount processed. Returned payments are subject to processing and administration fees.

GST # 846835908 RT0001

R BATKE OILFIELD LTD

RBATKE@ME.COM

**UNDER HOOD CHECKLIST** 

Completed Date: 1/3/2024

Unit: 131 VIN: 1NPFD40X57D678936

Year/Make/Model: 2007 Peterbilt 378

Chassis Kilometers: 1,560,258 Kilometers (12/1/2023)

Engine Hours: No recorded. Service Order: 5852

**Adrenaline Diesel** 

13019 - 151 Street NW Edmonton, AB T5V 1A7, CA

info@adrenalinedlesel.ca

Engine: 79198444 ISX 14.9L L6 DIESEL

| Procedure   | Result    | Procedure   | Result    | Procedure  | Result    |
|---|-----------|---|-----------|--|-----------|
| 1. Oil Level Checked                              | Completed | 2. Coolant level acceptable                           | Completed | Power steering fluid level acceptable              | Completed |
| 4. Bolts checked (tight) & Wires tied up (pretty) | Completed | 5. Engine washed / truck clean                        | Completed | 6. Unused parts returned                           | Completed |
| 7. Mileage & truck info entered                   | Completed | Adrenaline Diesel decal placed on driver side window. | Completed | Truck parked and keys returned to Service Manager. | Completed |

Technician: Lucas Hilliard Digital Signature: Lucas Hilliard Date: 1/3/2024