

MECHANICAL FITNESS ASSESSMENT

As required by Vehicle Inspection Regulation (A/R 211/2006)

Dealer:	AMV	/IC License Number:	
Address:			
LUCKINGEL	VEHICLE INFORMATION		
Year: 7011 Make: Merce	des Model: 5 550 4 MATIC	Previous Province of Registration:	
	86 B6BN 3969150dorneter Reading:	Pulletin	(km/mi)
		-	[]
Truck Motorcycle Bus	Land Congression	Auto Motorized RV	Other
Please check mark (✓) ea	ich item as C = Complies N = Non-Comp	oliant N/A≃Not Applicable	
Powertrain C N Accelerator Fuel System	Brakes C N Parking/Emergency Brake Hydraulic System	Frame & Body Hood Latch Door Latches & Hinges	CN
Exhaust	Vacuum System	Bumpers 8 Worker	1
Transmission Front/Rear/Spindles Axles	Drum Brakes Disc Brakes	Windshield Wipers & Washer Rear Wiper & Washer	
Clutch	Shoes/Pads	Windshield	
Fluid Levels (power steering, brake)	Anti-Lock (if OEM equipped)	Windows	
CV Joints	Steering C N	Defrost/Heaters	1-2
Lamps C N	Steering Lash	Mirrors	
Head Lamp Hi Beam	Steering Linkage	Seat Belts/Airbags	
Head Lamp Lo Beam Head Lamp Location	Rack & Pinion	Mudguards	1
Daytime Running Lamps	Power Steering System King Pin	Window Glazing	
Tail Lamps	Ball Joints	Structural Integrity	
Brake Lamps	Suspension C N	Tires & Wheels	G N
Turn Signal Lamps	Leaf springs	Tread Depth Tread Section	1
Hazard Warning Lamps Licence Plate Lamp	Struts and Shocks	Sidewalls	
Back-up Lamps	Coll spring	Wheels	1
Instruments C N	Torsion Bar	Electrical	14 5
Speedometer/Odometer	Independent/Multilink Rear Computer Controlled	Wiring	
Indicator Lamps		Battery	
Horn	Diagnostic C N	Switches	
Ht Beam Indicator	Diagnostic Trouble Codes	Alternator	
Technician Comments	Name of the Control o		
Very Clean Car For	Yearl		
This is to certify that I have assessed the with the <i>Traffic Safety Act</i> , Vehicle Equipming this assessment, I verify the control of the con	vehicle described above in accordance ment Regulation (A/R 122/2009). By ents of this document are true and correct.	i, the buyer of this vehicle, ac receipt of this assessment.	:knowledge
Signature of Certified Journeyman Technicia	an: In	Signature of Buyer	
Technician Name (Print): AK id Manha		Buyer (Print)	
Technician Trade Certificate Number:	T-13-6411	Signature of Salesperson	
Date: June 12/15		Salesperson (Print)	
This assessment avnirus 120 days after the date it was issued		Date	

Minute Muffler and Brake

Advance Tire & Automotive 1357 32nd Avenue N.E. Calgary, Alberta T2E 7Z5

Phone: (403) 250-5010 ~ Fax: (403) 250-6852

Advancetire@telus.net Tax ID# 130570591

Invoice



'Invoice # 70001 Work Order # 80298 Service Advisor Jody Chandra Technician Ravi Chandra Plate AB NO PLATE
Description 2011 Mercedes-Benz S550 4Matic V8 5.5L
5461CC 333CID
VIN WDDNG8GB6BA396915
Odometer 147,032

Invoice Date 4/2/2025 2:27 PM Appointment 3/26/2025 11:54 AM Promised 3/26/2025 11:54 AM

Concern

Check Engine Light On

Diagnostic Findings:

Scanned vehicle and retrieved the following codes:

P0140 - O2 Sensor Circuit No Activity Detected (Bank 1 Sensor 2)

P2272 - O2 Sensor Signal Stuck Lean (Bank 1 Sensor 2)

P2270 - O2 Sensor Signal Stuck Lean (Bank 1 Sensor 2)

P0141 - O2 Sensor Heater Circuit Malfunction (Bank 1 Sensor 2)

P0038 - HO2S Heater Control Circuit High (Bank 1 Sensor 1)

P0160 - O2 Sensor Circuit No Activity Detected (Bank 2 Sensor 2)

P0562 - System Voltage Low

P0335 - Crankshaft Position Sensor 'A' Circuit Malfunction

Visual Inspection & Testing:

Found the passenger side downstream O2 sensor wires cut and hardwired.

Tested the driver's side heater circuit; found power at the sensor connector, but where PCM-controlled ground should be, there is approximately 3.5 volts present instead.

Recommended Repairs:

- 1. Replace both downstream O2 sensors.
- 2. Install a new pigtail to properly repair the passenger-side downstream O2 sensor wiring.
- 3. Recheck for codes after repairs.

Important Notes for the Customer:

There are additional unrelated codes present that may require further diagnosis.

Due to the improper wiring found, there's a possibility the PCM's internal driver may have sustained damage. If so, further repairs may be necessary.

The check engine light may return after initial repairs. Additional diagnostic time may be required to address other issues.

Labor 1 Hour \$145.00 *G

Sub \$145.00

Inspection

Notes
Description
Install Pigtail 1 Hours
" - Pigtail Wiring 1 Unit \$82.73

Unit \$82.72 / Unit \$82.72 G Sub \$227.72

\$145.00 *G

Service

Downstream Oxygen Sensor(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor 1.5 Hour \$217.50 *G

NGK - Oxygen Sensor	2 Unit	\$140.49 / Unit	\$280.98 G	
		Sub	\$498.48	
Total Parts Total Labor			\$363,70 \$507.50	
Total Before Taxes & Miscellaneous Charges			\$871,20	
(*) Shop Supplies		E 0/	\$25.38 G	
(G) Canadian Goods and Services Tax (GST) Grand Total		5 %	\$44.83 \$941.41	
DIAMOND EXOTIC AND TRUCK SALES paid \$941.41 by Direct Deposit				
We Appreciate your Business! I acknowledge receipt of the vehicle and the indebtedness indicated herein.				
Customer Signature:				