

HIGH TORQUE

mobile mechanics

AUCTION INSPECTION

Service Date: Feb / 1 / 23 Work Order No. 6990


Customer Name: Alta Auto Sales
Technician Name: Lance Transmission: Auto ☒ Manual ☐
Unit #: / Year: 2015 Make: Ford Model: F350
KM (in): 200313 KM (out): 200315 Not Driven ☐
VIN# 1FTBW3B63FEB57733

Service(s) Performed:

Auction inspection

PRE-SERVICE INSPECTION

Visible Damage: No ☒ Yes ☐



Dipstick Photo ☒ Unit Number Photo (Fleet) ☐ VIN Tag Photo ☒ Dash Mileage Photo ☒

UNDER THE HOOD

Engine Oil Level Upon Arrival
Engine Oil dirty Level ☒ Colour / Condition ☒
Engine Coolant low Level ☒ Colour / Condition ☒
Transmission Fluid overfull Level ☒ Colour / Condition ☒
Head Gasket Leaks ☒
Exhaust Manifold Leaks ☒
Exhaust or DEF Modification or Deletion ☒
Engine Overall Condition (30 second video) ☒
Engine Noise ☐ present Timing Chain Noise ☐ present ☒
Engine Misfires Cylinder: ☒

ROAD TEST

4X4 Operation / Differential Noise ☒
Transmission Shift ☒

Notes:

FULL VEHICLE SCAN

Dash Lights / Malfunction Indicator Lights

Check Engine: On ☐ Off ☒ Airbag: On ☐ Off ☒ ABS: On ☐ Off ☒

Airbag Tamper ☒

Technician Notes:

C0031 left front wheel speed sensor
U0184 lost communication with radio

Technician Signature:

By signing, the customer indicates that all requested services have been performed including this Multi-Point Inspection. With this signature, the customer assumes all liability related to services recommended by High Torque, that the customer has chosen not to have performed. High Torque is not legally liable for any such damages resulting from recommended services that the customer has chosen not to have performed. High Torque recommends the customer has their wheels retorqued to vehicles specification 100km after this appointment at the responsibility of the customer.

