HIGH TORQUE mobile mechanics

Customer Name: Stee	l works mag
Technician Name: Lance	Transmission: Auto Manual □
Unit#: _ Year: 2007	Make: Hummer Model: H2
KM (in): 216127	KM (out): 216129 Not Driven
	134974112901
Service(s) Performed:	
auction	inspliction
PRE - SERVICE II Visible Damage: No Yes	NSPECTION
Visite Bullinge. No 2 165	
Dipstick Photo Unit Number Photo	(Fleet) VIN Tag Photo Dash Mileage Photo
UNDER THE HO	OOD
Engine Oil Level Upon Arrival	
Engine Oil	Level Colour / Condition
Engine Coolant	Level Colour / Condition
Transmission Fluid	Level Colour / Condition
Head Gasket Leaks	
Exhaust Manifold Leaks	
Exhaust or DEF Modification	or Deletion
Engine Overall Condition (30	second video)
Engine Noise present Tim	ning Chain Noise present
Engine Misfires h, 5+6	Cylinder:
ROAD TEST	,
4X4 Operation / Differential I	Noise
Transmission Shift	

AUCTION INSPECTIO	N

Service Date: Feb / 1 / 23 Work Order No. 6990

FULL VEHICLE SCAN

Dash Lights / Malfunction Indicator Lights
Check Engine: On Off Airbag: On Off ABS: On Off
exhaust leak on driver side manifold to y pipe
POITI Fuel system too lean bank
possoo engine mistire desected
Boogo active Switch voltage
BO414 temperature control 1 Feedback
Boll9 recirculation position Feedback
B2440 right Front seat back hearer sensor
2000 misfires counted on cylinder #1 - not currently
misfiring
wipers mop
Technician Signature: Lance Dechie

By signing, the customer indicates that all requested services have been performed including this Multi-Point Inspection. With this signature, the customer assumes all liability related to services recommended by High Torque, that the customer has chosen not to have performed. High Torque is not legally liable for any such damages resulting from recommended services that the customer has chosen not to have performed. High Torque recommends the customer has their wheels retorqued to vehicles specification 100km after this appointment at the responsibility of the customer.

