

1997 Class A Diesel Freightliner

Report URL: <https://atxt.me/B182eoDG>

Customer Name James M

Phone No. (xxx)-xxx-x967

Submodel

Engine Size

2WD or 4WD

VIN 4UZ6XJBC1VC777372

License

Mileage 0

ABS

Transmission



Est/Invoice# 64625

Production Date


Notes

Quick Photos

✓ 3 Requires Urgent Attention

#	Insp Item	Notes
X	Tech Notes	Pressure held over night, next step would be to charge ac and install dye. Monitor. The poly bead line is not fully on the fitting. The poly bead is discontinued and has been replaced with pex line. Will need to move panel fully back and install a coupler to convert to pex line and then install a new fitting for a pex connection at valve. .
		
X	Tech Notes	Water flowing out from behind panel when trying fo fill tank
		
X	Tech Notes	Fridge coils covered in yellow residue. Water lines not hooked up to ice maker water valve. Has no water flow out of drinking tap and shutoff valve. for icemaker is seized and partly open. Has enough water flow that it's trickling out behind fridge at icemaker valve. There was napkins piled in corner by filter. Everything is dry at this point.

COPY



✓ 0 Requires Future Attention

#

Insp Item

Notes

Found None!

✓ 0 Good Items

#

Insp Item

Notes

Found None!

This report was signed off on 05/22/2024 03:59 pm

Technician: Admin User

COPY