Vehicle Repair Log

Last modified:

Year	2013
Make	HINO
Model	PICKER
Vehicle ID No. (VIN)	2AYNV8JT7D3S15428
License No.	K 61166

NEXT SERVICE

Date	Description of Work	SHOP INV#	KM	OTHER	Labor Cost	Parts Cost	GST	Total Cost
OCT 6/23	REPAIR HEADLIGHT PIGTAIL	C-MAC 1079522	385128		$84.77		4.24	$89.01
NOV 27/23	INSTALL NEW TOOL BOX	C-MAC 1079889	391464		$304.27		15.21	$319.48
JAN 29/24	RE TORQUE	DRB SO-8294	400007					$0.00
FEB 12/24	POT, REPLACE IAP SENSOR, ALIGNMENT,	DRB SO-8255	399545	148.00	$1,484.65	$999.03	131.61	$2,763.29
JAN 25/24	REPAIR TOO; BOX LATCH	C-MAC 1080471	399811		$252.63		12.63	$265.26
FEB 22/24	RETORQUE	DRB SO-8468	402038					$0.00
MAY 23/24	SERVICE CALL BRAKES OUT OF ADJUSTMENT	DRB SO-9241	414361	12.95	$347.00		18	$377.95
MAY 30/24	SHOCKS, REPLACE BRAKE STROK INDICATOR,	DRB SO-9278	414793	123.15	$1,231.49	$1,562.58	145.86	$3,063.08
JUNE 14/24	RETORQUE	TT 1255	415464					$0.00
JUNE 25/24	REPLACE RAD	TT 1287	415896	190.46	$2,380.80	$2,038.83	230.45	$4,840.54
JULY 2/24	RESEAL 2 HYDRAULIC CYLINDERS	FORCO SO-3202	476362	310.84	$4,144.50	$5,531.65	499.35	$10,486.34
JUNE 10/24	HYDRAULIC FLUID	C-MAC 1081870			$330.19		16.51	$346.70
JULY 26/24	HYDRAULIC LEAK WARRANTY	FORCO SO-3282	418464					$0.00
AUG 7/24	TOP UP TRANY FLUID	TT 1354	420417	5.38	$67.20	$78.00	7.53	$158.11
JULY 22/24	CLEAR TURBO OVER BOOST	DRB SO-9811	417644	19.43	$194.25		10.68	$224.36
AUG 14/24	REPAIR HYDRAULIC LEAK	FORCO 2203	420446	47.76	$597.00	$92.31	47.76	$773.92
AUG 16/24	TRANY OVER FILL	TT 10112	420520	32.38	$323.75		17.81	$373.94
AUG 27/24	REPLACE PRESSURE CONTROL SOLENOID	DRB SO-10100	420597	129.50	$1,295.00	$2,018.38	172.14	$3,615.02
AUG 29/24	REPAIR TRANY WARRANTY	DRB SO-10182	421372					$0.00
SEPT 9/24	REPAIR HYDRAULIC LEAK	FORCO 2246	422842	99.87	$736.50	$416.95	62.67	$1,315.99
SEPT 25/24	DIAGNOS ABS AND ENGINE LIGHT	FORCO 2256	423970	48.00	$600.00		32.4	$680.40
DEC 31/24	REPLACE TURBO	DRB SO-10985	424302	255.00	$2,559.50	$7,305.44	506.04	$10,625.98
								$0.00
								$0.00
								$0.00
								$0.00