



Unit # 219342 Invoice

RECEIVED

MAY 09 2018

## SOLD BY

Peterbilt Thunder Bay  
1145 Commerce St  
Thunder Bay, ON P7E 6E8  
Canada

Dealer ID: 3318

PACCAR Dealer Code: P011

Dealer Tax ID: 105278493

AVANTIS

GL Code: 2002-00-RD2-00

Subtotal: 15917.25

Approval:

PO #: 633699

WO# 446945

RD2 SK

SOLD TO

Trican Well Service Ltd.  
2900, 645 - 7th avenue SW  
Calgary, AB T2P 4G8  
Canada  
PACCAR Fleet Code: 8F98

\*ONTARIO TAX N/A IN AVANTIS

Remittance advice can be included with a check payment or emailed to  
remittance@paccarpartsfleetservices.com.

## Check

Multi Service Technology Solutions, Inc.  
PO Box 15501  
Station A  
Toronto, Ontario M5W1C1

## ACH

JP Morgan Chase Bank  
Routing Number: 27000012  
EFT  
Account Number: 4682650101  
To Benefit: Multi Service Technology  
Solutions, Inc.

## Wire

Intermediary Bank  
Royal Bank of Canada Toronto  
RBC Swift Code: ROYCCAT2XXX  
Beneficiary Bank  
JP Morgan Chase Bank  
Swift Code: CHASCATTCTS  
Account Number: 4682650101

Invoice/RO Number	W66829-1
Invoice Date	04/14/2018
Approval Code	427395
Site ID	Canada HQ
P.O. Number	633699
SR Number	
Unit Number	219342 - 249349
VIN	1XPTP4EX0DD162200
Odometer	209833

Quantity	Item SKU	Description	Item Type	Fleet Price	Dealer Price	Total Adjustment	Final Amount
1	4386009RXCUM	HEAD-CYLINDER	PACCAR Part	\$6,684.14	\$6,684.14	\$0.00	\$6,684.14
1	2872405PXCUM	INJECTOR-XPI	PACCAR Part	\$1,234.38	\$1,279.76	-\$45.38	\$1,234.38
1	D84-1000-6122180	BELT-POLY 12 RIBS X 2180 END/PLYSTR	PACCAR Part	\$77.15	\$104.24	-\$27.09	\$77.15
1	D84-1000-6061620	BELT-POLY 6 RIBS X 1620 END/PLYSTR	PACCAR Part	\$34.58	\$46.53	-\$11.95	\$34.58
1	4376104	KIT	PACCAR Part	\$1,768.70	\$1,768.70	\$0.00	\$1,768.70
1	4928594CUM	SENSOR-PRESSURE	PACCAR Part	\$138.24	\$140.06	-\$1.82	\$138.24
1	4298975CUM	NUT-LOCK	PACCAR Part	\$8.62	\$9.61	-\$0.99	\$8.62
1	LF14000NNFLG	FILTER	PACCAR Part	\$49.60	\$49.60	\$0.00	\$49.60
1	LF14000NNFLG	F.E.T.	Miscellaneous	\$1.19	\$1.19	\$0.00	\$1.19
45	15W40	15W40 OIL	Other Part	\$4.01	\$4.01	\$0.00	\$180.45
2	226821-437C	TEX AF/C 50/50 - EMBITTERED 6X1GA	PACCAR Part	\$9.99	\$9.99	\$0.00	\$19.98
2	226821-437C	F.E.T.	Miscellaneous	\$0.76	\$0.76	\$0.00	\$1.52
2	CN24600	TERMINAL-END	PACCAR Part	\$3.42	\$5.19	-\$3.54	\$6.84
1	3163075	DEUTSCH SOCKET					
1		PAINT	PACCAR Part	\$25.43	\$25.43	\$0.00	\$25.43
2	550042064	PZL DEX/MERC ATF	PACCAR Part	\$4.77	\$4.77	\$0.00	\$9.54
2	550042064	DEXRON-III MERCON					
2		F.E.T.	Miscellaneous	\$0.16	\$0.16	\$0.00	\$0.32
1	226821-437C	TEX AF/C 50/50 - EMBITTERED 6X1GA	PACCAR Part	\$9.99	\$9.99	\$0.00	\$9.99
1	226821-437C	F.E.T.	Miscellaneous	\$0.76	\$0.76	\$0.00	\$0.76
2	2894829CUM	CONNECTOR-FUEL	PACCAR Part	\$98.47	\$98.47	\$0.00	\$196.94
4	2894829	INJECTOR					
1		CONNEC	PACCAR Part	\$98.47	\$98.47	\$0.00	\$393.88
1	Labor	Labor	Labor	\$5,075.00	\$5,075.00	\$0.00	\$5,075.00
1	GoodsServicesTax	GoodsServicesTax	Harmonized Sales Tax	\$2,081.04	\$2,081.04	\$0.00	\$2,081.04

For PACCAR Customer Support call 1 (888) 977-2787

Send inquiries to PO Box 10922, Shawnee Mission, KS 66225-9022 or customer\_support@paccarpartsfleetservices.com

Confidential

© Multi Service Technology Solutions, Inc. 2018

Page 1 of 2

# Invoice

## Summary of Charges

Parts	\$10,748.78
Other Parts	\$180.45
Labor/Other	\$5,078.79
Freight	\$0.00
Tax	\$2,081.04
Total Adjustment	-\$90.77
Final Amount	\$17,998.29 *

### Service Notes

CAUSE: INTAKE VALVE FACE BROKEN OFF, #6 INJECTOR FAILED CAUSE: INTAKE VALVE FACE BROKEN OFF, #6 INJECTOR FAILED  
CORRECTION: DRAINED FLUIDS AND DISASSEMBLED, CLEAN DECK SURFACE. SPEC CYLINDER HEAD. INSTALL CYLINDER HEAD.  
TORQUE HEAD DOWN AND INSTALL ACCESORIES. SET TOP END. INSTALL RAD, REPLACE #6 INJECTOR AND PROGRAM. RAN  
ENGINE. ENGINE MAKING NOISE. REMOVE FRONT COVER AND ADJUSTED GEAR LASH AND REPLACE GASKET. RUN ENGINE. WASH  
OFF ENGINE AND ROAD TESTED. GOOD.

\* ONTARIO TAX OPTION  
NOT AVAILABLE IN  
AVANTIS

SK  
May 9/18

For PACCAR Customer Support call 1 (888) 977-2787

Send inquiries to PO Box 10922, Shawnee Mission, KS 66225-9022 or [customer\\_support@paccarpartsfleetservices.com](mailto:customer_support@paccarpartsfleetservices.com)