

First Fleet Maintenance LTD

140 MacLennan Crescent
Fort McMurray AB T9H 4E8
info@firstfleet.ca
www.firstfleet.ca
GST/HST Registration No.: 833031859RT0001



INVOICE

BILL TO
Laurence
Heavy Wrench Mechanical
6 Ireland
Guelph Ontario N1E7C2

INVOICE 21540
DATE 24/05/2022
TERMS Net 30
DUE DATE 23/06/2022

| | DESCRIPTION | QTY | RATE | AMOUNT |
|-----------|---|-------|--------|----------|
| | 2012 DODGE RAM 5500 6.7L 3C7WDNBL1CG164184 340,992 KMS 16,190 HOURS PERFORMED UNDERCARRIAGE WASH AT AN EARLIER DATE BUT WAS MISSED BILLING. | | | |
| 30 | SUBLET LABOUR | 1 | 600.00 | 600.00 |
| | REMOVED AND REPLACED WATER PUMP, BELT AND IDLER PULLEY. REPLACED FAN CLUTCH AND FRONT CRANK SEAL. REMOVED FRONT HEADLIGHTS, GRILL AND RAD, FOUND HOLE IN RAD, SENT FOR REPAIR. SUPPLIER WAS ABLE TO REPAIR RAD, REINSTALLED RAD AND FILLED WITH COOLANT. TESTED AND NO MORE LEAKS. | | | |
| | CHECKED UNIT FOR ABS LIGHT ON, SCANNED FOR CODES AND FOUND CODE FOR LEFT FRONT SENSOR, CHECKED WIRING AND ITS ALL GOOD. CHECKED WHEEL BEARING AND FOUND IT HAS A LOT OF PLAY, JACKED UNIT UP AND CONFIRMED, UNIT WILL NEED A NEW WHEEL BEARING, REMOVED AND REPLACED AS REQUIRED. | | | |
| | REMOVED OLD AC COMPRESSOR TOOK EXTRA TIME AS THE ENGINE WAS COVERED IN DIRT/OIL. INSTALLED GOOD/USED COMPRESSOR. INSTALLED NEW AC LINE AND CHARGED UNIT. | | | |
| | CLEANED MUD FROM AROUND TRANSMISSION, DRAINED FLUID AND REMOVED TRANSMISSION PAN. REPLACED FILTER, FLUID AND TRANSMISSION PAN GASKET. FILLED WITH NEW FLUID. TEST DROVE UNIT AND UNIT IS SHIFTING A LITTLE BETTER. ADVISED CUSTOMER AND WE ARE GOING TO HOLD OFF ON THE TRANSMISSION REPAIR FOR NOW. | | | |
| | REMOVED AND REPLACED STEERING SHOCK. | | | |
| 00 | LABOUR | 22.25 | 155.00 | 3,448.75 |
| 1-9272 | A/TRANS FILTER KIT | 1 | 186.60 | 186.60 |
| 5189966AD | ASRC ATF | 14 | 22.77 | 318.78 |

| | | | | |
|------------|-------------------------------------|------|--------|--------|
| 68426385AA | CRANKSHAFT SEAL | 1 | 70.00 | 70.00 |
| 42291 | WATER PUMP | 1 | 226.89 | 226.89 |
| A81735 | FAN CLUTCH | 1 | 396.31 | 396.31 |
| PBR930508 | WHEEL BEARING AND HUB | 1 | 594.75 | 594.75 |
| 68092250AD | AC LINE | 1 | 170.77 | 170.77 |
| 68086125AA | SEAL | 1 | 39.69 | 39.69 |
| SC-2966 | STEERING SHOCK | 1 | 93.32 | 93.32 |
| 30 | SUBLET RADIATOR REPAIR | 1 | 373.25 | 373.25 |
| 16-834 | COOLANT, 50/50 PREMIXED RED, 4L JUG | 12 | 3.99 | 47.88 |
| GDR134A | A/C, REFRIGERANT, 134A | 1.50 | 12.82 | 19.23 |
| 488100P | A/C PAG OIL- 250ML | 2 | 3.89 | 7.78 |
| 20 | SHOP SUPPLIES | 1 | 310.39 | 310.39 |

All Wheels Must be Torqued at 100 Km's by a Qualified Technician

| | |
|----------|----------|
| SUBTOTAL | 6,904.39 |
| GST @ 5% | 345.22 |
| TOTAL | 7,249.61 |

BALANCE DUE **\$7,249.61**

TAX SUMMARY

| | RATE | TAX | NET |
|----------|------|--------|----------|
| GST @ 5% | | 345.22 | 6,904.39 |