

**Back Country Mechanical Ltd.**

PO Box 6021 STN MAIN

Hinton AB T7V1X4

780-740-5969

backcountrymechanicalltd@gmail.com

GST/HST Registration No.: 837475631 RT 0001

INVOICE

BILL TO

Trican Well Service Ltd.

181 Kelley Road

Hinton AB T7V 1H2

INVOICE # 1731**DATE 07/22/2021**

DATE	ACTIVITY	DESCRIPTION	HOURS	RATE	AMOUNT
07/09/2021	Repair	Unit: 610562 Make: Kenworth VIN# -CJ950286 - Disassemble diff. Had to take fifth wheel off and torque arms to create room. Took passenger side #2 and 3 tires off to create room to work. While removing drive line, bolts were stuck and had to use heat to remove. Remove old diff. Used picker to remove. Install new diff into unit. Put fifth wheel and torque arms back on, clean shop. Done by: Keaton G.	12	110.00	1,320.00
07/10/2021	Repair	- Put new yolk on, installed drive line. Filled with oil. Put tires back on, told customer to re-torque. Done by: Keaton G.	2	110.00	220.00

SUBTOTAL	1,540.00
GST @ 5%	77.00
TOTAL	1,617.00
BALANCE DUE	\$1,617.00