



- [Close Window](#)
- [Print This Page](#)
- [Expand All](#) | [Collapse All](#)

Hydrovacs B Service - 127960 - WO-3839

Tracking Number	W-D54-CCA-69E7	EAM Service Location	CIS Interco Only - P&V Shop
Name	Hydrovacs B Service - 127960 - WO-3839	Assigned to Mechanic	Russell Barriage
Work Order ID	WO-3839	Parts Person	Shannah Danielle Humby
Description	700 Hour Service	Project	FMM SYNC PV 2020 - BMCS JV - R&M - In shop
IsCompleted	<input checked="" type="checkbox"/>	Equipment	Hydro Vac Tridrive
Past Due	<input type="checkbox"/>	Equipment PO	PO-0018829
		Equipment Unit Number	127960
Planned Start Date		Record Type	Preventative Maintenance
Planned Finish Date		Source PMS	
Due Date		Priority	
Actual Start Date	12/14/2020 1:29 PM	Status	Approved
Actual Finish Date	12/30/2020 9:44 AM		
Approver	Brandy Marie Hepditch	Total Duration	15 days 20 hours 15.07 mins
Hours	18,270.00	Work Order Duration	15.84
Mileage	101,259	WO Labor Cost	\$8,682.50
Next service due (hours)		WO Items Cost	\$5,697.47
AX Service Order ID	CIS1032579	WO 3rd Party Cost	\$2,165.84
ItemCount	54	Total WO Cost	\$16,545.81

General Notes

Note

System Information

Owner	Liquid Frameworks	Last Modified By	Boomi Security, 1/5/2021 9:35 AM
Created By	Brandy Hepditch, 11/16/2020 10:08 AM	IsTemplate	<input type="checkbox"/>
		Uncompleted WO Tasks	0

Work Order Tasks WT-26178

Task Category	Air Brakes
Title	
Description	JAL December 18, 2020

	-Adjusted air brakes
	Russell 12/18/20
	-came back from a test drive #2 p/s brakes were hotter then the rest checked it found that the slack were sticking from mud build up cleared up the mud and greased it try to purge the old grease out of it and set it
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 7:15 AM
Action Taken	
Expected Time to Complete	2.00
Time to Complete	3.50

WT-26179

Task Category	Body and Frame
Title	
Description	Russell 12/17/20 -removed mud and old d/s door seal and installed new one
	JAL December 17, 2020 -Cleaned air bag saddle and cleaned around work area and also cleaned my tools after few days.
Check Issue	<input type="checkbox"/>
Completed On	12/17/2020 11:00 AM
Action Taken	
Expected Time to Complete	3.00
Time to Complete	2.00

WT-26180

Task Category	Burner System
Title	
Description	Russell 12/18/20 -took apart the burner found that everything lose the electroids were cracked replaced them and the jets tighten everything back up, tighten the flange that mounts the burner
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 2:00 PM
Action Taken	
Expected Time to Complete	2.00
Time to Complete	2.00

WT-26182

Task Category	Engine
Title	Replace eng fan
Description	Russell 12/16/20 replaced eng fan
Check Issue	<input type="checkbox"/>
Completed On	12/16/2020 6:00 PM
Action Taken	
Expected Time to Complete	3.00
Time to Complete	4.00

WT-26183

Task Category	Heating and Defrosting
Title	
Description	Russell 12/14/20 -diag why heater not working found back of the heater control all burned up desided to remover the bower found the cage all bent and the bearings are starting to siezed in it also noticed the resistor pack burned replaced it

		Russell 12/16/20 -replaced plug going to control, put dash back together
Check Issue	<input type="checkbox"/>	
Completed On		12/14/2020 6:00 PM
Action Taken		
Expected Time to Complete		4.00
Time to Complete		8.00
WT-26184		
Task Category		Lamps and Reflectors
Title		replace head light holder, repair 1/4 fender light, repaired rear becon ligh
		Russell 12/17/20
Description		-replaced head light holder -repaired wiring to 1/4 fender light -replaced bulb in rear becon light
Check Issue	<input type="checkbox"/>	
Completed On		12/17/2020 3:00 PM
Action Taken		
Expected Time to Complete		3.00
Time to Complete		9.00
WT-26185		
Task Category		Power Train
Title		
		Russell 12/16/20 -removed drive shaft from trans to drop box to have sent out took longer then normal slip yoke was siezed solid
Description		-removed drive shaft from drop box to #1 drive replaced hanger bearing installed drive shaft
		Russell 12/17/20 -installed new drive shaft
Check Issue	<input type="checkbox"/>	
Completed On		12/16/2020 9:00 AM
Action Taken		
Expected Time to Complete		2.00
Time to Complete		4.00
WT-26188		
Task Category		Transmission
Title		
		Russell 12/14/20
Description		-oil was very foamy drained trans pulled the cooler lines off pressure tested coolant system make sure the cooler not leaking installed it refilled trans
Check Issue	<input type="checkbox"/>	
Completed On		12/14/2020 12:00 PM
Action Taken		
Expected Time to Complete		4.00
Time to Complete		3.00
WT-26189		
Task Category		Function Test
Title		Function Test
Description		Test Blower Operation Test Burner System Test Hydraulic System Operation Test and Adjust Un-loader Valve

Test Posi Ground System**JAL****December 18, 2020**

-Topped up water with Russel and took it outside. Extra time for moving truck around and also extreme cold outside. Function tested it but found couple minor problems. truck is not done but close. Greased the turret bearing with Russel. Also, I did my notes at this time. Sir Russel is going to finish the truck and I will be in different truck.

Russell 12/18/20

-had taking outside funtion tested unit found a few things repaired and funtion tested agin and winterized unit

Check Issue ☐Completed On **12/18/2020 11:30 AM**

Action Taken

Expected Time to Complete **0.50**Time to Complete **6.67****WT-26190**Task Category **Chassis**Title **Truck B Service and Inspection****Service Engine (Oil/Filter)****Check Fluid Levels (Coolant/Power steering/Etc.)****Inspect Exhaust****Inspect Heater/Defroster/Cooling System****Inspect Body/Bumpers/Mud Flaps****Inspect Airlines/Air tank/Air Compressor****Inspect Fifth Wheel/Release lever****Inspect Differential (Check Fluid Levels)**Description **Inspect Suspension****Inspect Springs (Front/Back)****Inspection Transmission (Check Fluid Levels)****Inspect Clutch and Driveline****Inspect Brakes/Park Brakes****Inspect Tires/Rims/Wheel Nuts****Inspect Windshield /Windows****Inspection Battery/Lights/Reflective Tape****Inspect Safety Equipment (Fire Ext, First Aid Kit)****Ensure Correct Paperwork is in Unit**Check Issue ☐Completed On **12/14/2020 8:00 AM**

Action Taken

Expected Time to Complete **4.00**Time to Complete **4.00****WT-27111**Task Category **Air Leak**Title **diag and repair air leak in dash**Description **Russell 12/14/20****-took dash apart found air line pulled right out of the switch repaired**Check Issue ☐Completed On **12/14/2020 9:00 AM**

Action Taken

Expected Time to Complete

Time to Complete **1.00****WT-27112**Task Category **Electrical System**Title **posi ground delete**

Description	Russell 12/15/20 -screen all messed up on posi ground did a posi ground delete
Check Issue	<input type="checkbox"/>
Completed On	12/15/2020 7:00 AM
Action Taken	
Expected Time to Complete	
Time to Complete	1.00

WT-27113

Task Category	Electrical System
Title	Diag and repair power windows
Description	Russell 12/15/20 both windows going up very slow and would stop checked for proper power to doors that was good checked the track that was good, took both doors apart put power right to the motor stil very slow both motors worn out replaced both window reg
Check Issue	<input type="checkbox"/>
Completed On	12/15/2020 3:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	8.00

WT-27179

Task Category	Wheel Hubs
Title	RH 2nd drive wheel seal is leaking and RH front steer wheel bearing is no oil (needs new wheel bearing)
Description	JAL Dec 16, 2020 -uninstalled wheel bearing races from RH front steer and waiting on parts. Uninstalled 2nd drive RH hub and replaced wheel seal with new updated wheel seal. Extra time for cleaning the excessive oil leak. Installed new brakes on drive because it is contaminated with oil and also replaced the steer due to worn pad close to 3/8 of a thick. didn't put new drums since this truck is only here for 3 months before disposal. Set the rh 2nd drive to .002" of endplay and torqued to spec. Made sure the locking tab is also crimped.
	JAL December 17, 2020 Installed wheel bearing to front steer and new wheel seal. Torqued it to spec and used dial indicator and got .002 of endplay.
Check Issue	<input type="checkbox"/>
Completed On	12/16/2020 3:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	13.00

WT-27180

Task Category	Steering Column/Box/Linkage
Title	LH and RH steering drag link has excessive play
Description	JAL Dec 16, 2020 -Replaced both draglink.
Check Issue	<input type="checkbox"/>
Completed On	12/16/2020 4:30 PM
Action Taken	
Expected Time to Complete	
Time to Complete	1.50

WT-27181

Task Category	Vacuum System
Title	Replaced torn 12" hose between RH of blower and silencer
	JAL
	December 16, 2020
Description	-extra time for picking up some parts for this truck. CUt the old hose in a half and also cut the new one into the same measurements. this task is not done this day.
	JAL
	December 17, 2020
	Installed new 12" hose. extra time for forklift training at 8 AM to around 10 AM
Check Issue	<input type="checkbox"/>
Completed On	12/16/2020 6:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	5.75

WT-27230

Task Category	Electrical System
Title	replace back light switch
Description	Russell 12/17/20 -removed floor pan and removed mud around switch and replaced
Check Issue	<input type="checkbox"/>
Completed On	12/17/2020 10:00 AM
Action Taken	
Expected Time to Complete	
Time to Complete	1.00

WT-27231

Task Category	Lamps and Reflectors
Title	diag d/s dog house inside light
Description	Russell 12/17/2020 -removed switch checked for power had power there replaced light
Check Issue	<input type="checkbox"/>
Completed On	12/17/2020 12:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	1.00

WT-27234

Task Category	Debris Tank
Title	torque turret bearing bolts replace rear gate vale
	Russell 12/17/2020 -torqued turret bearing bolts
Description	Russell 12/18/19 -replaced rear gate valve
	Russell 12/18/20 Greaded turret bearing outside wile spinning it
Check Issue	<input type="checkbox"/>
Completed On	12/17/2020 4:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	6.00

WT-27241

Task Category	Miscellaneous
Title	small work
Description	JAL December 18, 2020 -removed fire extinguisher and installed it inside the dog house. -secured winterizer tank.
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 8:20 AM
Action Taken	
Expected Time to Complete	
Time to Complete	1.08

WT-27246

Task Category	Water Tank
Title	install 3 inch valve
Description	Russell 12/18/20 -installed 3 inch valve on water tank
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 8:00 AM
Action Taken	
Expected Time to Complete	
Time to Complete	1.00

WT-27247

Task Category	Triplex Pump
Title	Replaced the prv
Description	Russell 12/18/20 replaced the prv and set it
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 3:00 PM
Action Taken	
Expected Time to Complete	
Time to Complete	1.00

WT-27258

Task Category	Road Test
Title	road test, ps a2 brk sticking
Description	AK Dec 18, 2020: Pre-trip, road test. Found binder needed to be updated, loose headlamp assembly. Also a headlamp fault came up briefly after stopping to check hubs/drums. Front end felt a little off. King pins are worn but within CVIP spec according to Russell. I suggested verifying the front end and wheel bearings in addition to addressing other items found.
Check Issue	<input type="checkbox"/>
Completed On	12/18/2020 4:30 PM
Action Taken	
Expected Time to Complete	
Time to Complete	2.00

Work Order Items

AX Item Id	1008701
Work Order Task	
Catalog Item	Chevron Delo 400 15W-40 SDE Semi Synthetic Engine Oil Bulk CHE-222290-01
Parts Item Status	Received
Cost	\$3.24

Planned Quantity **46.00**
Actual Quantity **46.00**
Quantity On Hand **12,534**
Warehouse **Fort McMurray 01**

AX Item Id **1007782**
Work Order Task
Catalog Item **Oil Sample Bottle Fluid Life MIS-OILAM-02**
Parts Item Status **Received**
Cost **\$13.95**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **279**
Warehouse **Fort McMurray 01**

AX Item Id **1004473**
Work Order Task
Catalog Item **Blower Resistor, P93CAA3100-01S**
Parts Item Status **Received**
Cost **\$49.94**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **4**
Warehouse **Fort McMurray 01**

AX Item Id **1008267**
Work Order Task
Catalog Item **Motor-Blower w/o Wheel, SR2000010**
Parts Item Status **Received**
Cost **\$128.79**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **5**
Warehouse **Fort McMurray 01**

AX Item Id **1008757**
Work Order Task
Catalog Item **HVAC Cab Control Assy, Q21-6012**
Parts Item Status **Received**
Cost **\$980.99**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **4**
Warehouse **Fort McMurray 01**

AX Item Id **1008488**
Work Order Task
Catalog Item **Brass Gate Valve Handle 4" & 6" S100-64**

Parts Item Status **Received**
Cost **\$18.08**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **2**
Warehouse **Fort McMurray 01**

AX Item Id **1005008**
Work Order Task
Catalog Item **6" Lever Style Brass Gate Valve**
Parts Item Status **Received**
Cost **\$310.36**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **3**
Warehouse **Fort McMurray 01**

AX Item Id **1003955**
Work Order Task
Catalog Item **Stainless Steel Camlock, Reducer, 6" Fem cam x 4" Male Cam**
Parts Item Status **Received**
Cost **\$453.86**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand
Warehouse **Fort McMurray 01**

AX Item Id **1008097**
Work Order Task
Catalog Item **Teflon Tape 1" X 540", TST6**
Parts Item Status **Received**
Cost **\$5.81**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **4**
Warehouse **Fort McMurray 01**

AX Item Id **1005738**
Work Order Task
Catalog Item **Heated Mirror SS Convex 8-1/2", TKL 97614**
Parts Item Status **Received**
Cost **\$57.13**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **8**
Warehouse **Fort McMurray 01**

AX Item Id **1004569**

Work Order Task
Catalog Item **LH Window Motor, WNR021000L**
Parts Item Status **Received**
Cost **\$171.83**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **7**
Warehouse **Fort McMurray 01**

AX Item Id **1004570**
Work Order Task
Catalog Item **RH Window Motor, WNR021000R**
Parts Item Status **Received**
Cost **\$171.83**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **6**
Warehouse **Fort McMurray 01**

AX Item Id **1004263**
Work Order Task
Catalog Item **Lube Filter, LF14001NNFLG**
Parts Item Status **Received**
Cost **\$29.54**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **77**
Warehouse **Fort McMurray 01**

AX Item Id **1005466**
Work Order Task
Catalog Item **Filter-Air Cab Interior B, CF19010**
Parts Item Status **Received**
Cost **\$27.48**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **45**
Warehouse **Fort McMurray 01**

AX Item Id **1003281**
Work Order Task
Catalog Item **Textured Disp PF Nitrile Glove 4mil Large (100/box) DSI GP2910-L**
Parts Item Status **Received**
Cost **\$16.75**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **97**
Warehouse **Fort McMurray 01**

AX Item Id	1004355
Work Order Task	
Catalog Item	Fuel/Water Separator Filter, FS36401FLG
Parts Item Status	Received
Cost	\$17.13
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	68
Warehouse	Fort McMurray 01

AX Item Id	1004348
Work Order Task	
Catalog Item	Fuel Filter, FF5825NNFLG
Parts Item Status	Received
Cost	\$36.41
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	87
Warehouse	Fort McMurray 01

AX Item Id	1004118
Work Order Task	
Catalog Item	Air Filter, AF4588MFLG
Parts Item Status	Received
Cost	\$53.88
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	49
Warehouse	Fort McMurray 01

AX Item Id	1008541
Work Order Task	
Catalog Item	Draglink, L24VU8422A11
Parts Item Status	Received
Cost	\$367.79
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	3
Warehouse	Fort McMurray 01

AX Item Id	1008542
Work Order Task	
Catalog Item	Draglink, L24VU8460A11
Parts Item Status	Received
Cost	\$381.48
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	5

Warehouse **Fort McMurray 01**

AX Item Id **1004023**
Work Order Task
Catalog Item **Kevlar Cut 5 Glove Size 9 SUP STAGXPU-9**
Parts Item Status **Received**
Cost **\$4.95**
Planned Quantity **5.00**
Actual Quantity **5.00**
Quantity On Hand **439**
Warehouse **Fort McMurray 01**

AX Item Id **1008097**
Work Order Task
Catalog Item **Teflon Tape 1" X 540", TST6**
Parts Item Status **Received**
Cost **\$5.81**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **4**
Warehouse **Fort McMurray 01**

AX Item Id **1005080**
Work Order Task
Catalog Item **4" SS Dust Cap, DC400SS**
Parts Item Status **Received**
Cost **\$173.73**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **14**
Warehouse **Fort McMurray 01**

AX Item Id **1003951**
Work Order Task
Catalog Item **8" SS Dust Cap, 80DC-Alum**
Parts Item Status **Received**
Cost **\$853.59**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **5**
Warehouse **Fort McMurray 01**

AX Item Id **1008297**
Work Order Task
Catalog Item **Balaclava FR KER J-58**
Parts Item Status **Received**
Cost **\$17.50**
Planned Quantity **1.00**

Actual Quantity **1.00**
Quantity On Hand **330**
Warehouse **Fort McMurray 01**

AX Item Id **1003559**
Work Order Task
Catalog Item **Wheel Seal, Drive, RM-D02 (392-9131, 47691)**
Parts Item Status **Received**
Cost **\$37.65**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **9**
Warehouse **Fort McMurray 01**

AX Item Id **1003555**
Work Order Task
Catalog Item **Wheel Seal, Steer, RM-S05 (383-8064, 43761)**
Parts Item Status **Received**
Cost **\$37.65**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **17**
Warehouse **Fort McMurray 01**

AX Item Id **1005497**
Work Order Task
Catalog Item **Hub Cap Gasket, STE 330-3009**
Parts Item Status **Received**
Cost **\$0.71**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **47**
Warehouse **Fort McMurray 01**

AX Item Id **1003403**
Work Order Task
Catalog Item **Rear Brake Shoe STMR4709ES2 Stemco 077E23-6R Eaton**
Parts Item Status **Received**
Cost **\$97.78**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **24**
Warehouse **Fort McMurray 01**

AX Item Id **1005566**
Work Order Task
Catalog Item **Drive Axle Flange Gasket, STE 330-3106**
Parts Item Status **Received**

Cost **\$2.33**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **57**
Warehouse **Fort McMurray 01**

AX Item Id **1003549**
Work Order Task
Catalog Item **Hub Cap + Gasket, STE 3434009**
Parts Item Status **Received**
Cost **\$12.25**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **9**
Warehouse **Fort McMurray 01**

AX Item Id **1003235**
Work Order Task
Catalog Item **Brake Shoe Hardware Kit, BHK078**
Parts Item Status **Received**
Cost **\$19.99**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **9**
Warehouse **Fort McMurray 01**

AX Item Id **1006174**
Work Order Task
Catalog Item **1/2" Bypass Valve , 60040065**
Parts Item Status **Received**
Cost **\$206.15**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **13**
Warehouse **Fort McMurray 01**

AX Item Id **1008108**
Work Order Task
Catalog Item **3.00 Burner Fuel Nozzle, 80 degrees, 87173540**
Parts Item Status **Received**
Cost **\$11.79**
Planned Quantity **2.00**
Actual Quantity **2.00**
Quantity On Hand **6**
Warehouse **Fort McMurray 01**

AX Item Id **1003368**
Work Order Task

Catalog Item	Brake Clean, KLF 313
Parts Item Status	Received
Cost	\$2.99
Planned Quantity	6.00
Actual Quantity	6.00
Quantity On Hand	1,666
Warehouse	Fort McMurray 01

AX Item Id	1003549
Work Order Task	
Catalog Item	Hub Cap + Gasket, STE 3434009
Parts Item Status	Received
Cost	\$12.25
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	9
Warehouse	Fort McMurray 01

AX Item Id	1002872
Work Order Task	
Catalog Item	Ball Switch N.C, POL 21465
Parts Item Status	Received
Cost	\$18.19
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	12
Warehouse	Fort McMurray 01

AX Item Id	1008070
Work Order Task	
Catalog Item	20 lb Fire Extinguisher Recharge
Parts Item Status	Received
Cost	\$62.00
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	48
Warehouse	Fort McMurray 01

AX Item Id	1008265
Work Order Task	
Catalog Item	Hood Hold-Down Hook, L03-0001
Parts Item Status	Received
Cost	\$20.48
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	14
Warehouse	Fort McMurray 01

AX Item Id **1004827**
Work Order Task
Catalog Item **Hood Safety Latch, L55-6003**
Parts Item Status **Received**
Cost **\$23.48**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **16**
Warehouse **Fort McMurray 01**

AX Item Id **1008647**
Work Order Task
Catalog Item **Folding T-Handle FT-1100A-SET-34 Ryadon**
Parts Item Status **Received**
Cost **\$46.02**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **5**
Warehouse **Fort McMurray 01**

AX Item Id **1004713**
Work Order Task
Catalog Item **LED Work Lamp, GRO BZ1015EA**
Parts Item Status **Received**
Cost **\$38.32**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **23**
Warehouse **Fort McMurray 01**

AX Item Id **1004673**
Work Order Task
Catalog Item **Replacment Flash Tube, TAR 8107230A95**
Parts Item Status **Received**
Cost **\$53.35**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **11**
Warehouse **Fort McMurray 01**

AX Item Id **1003368**
Work Order Task
Catalog Item **Brake Clean, KLF 313**
Parts Item Status **Received**
Cost **\$2.99**
Planned Quantity **12.00**
Actual Quantity **12.00**
Quantity On Hand **1,666**
Warehouse **Fort McMurray 01**

AX Item Id	1008452
Work Order Task	
Catalog Item	Mid Sole Ice Cleat GLN K1MID
Parts Item Status	Received
Cost	\$22.95
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	573
Warehouse	Fort McMurray 01

AX Item Id	1008700
Work Order Task	
Catalog Item	Pumps and Pressure Burner Electrode (Pair) BP-21789
Parts Item Status	Received
Cost	\$57.00
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	
Warehouse	Fort McMurray 01

AX Item Id	1003805
Work Order Task	
Catalog Item	3IN BALL VALVE 600WOG FULL PORT BV-48
Parts Item Status	Received
Cost	\$114.72
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	7
Warehouse	Fort McMurray 01

AX Item Id	1003604
Work Order Task	
Catalog Item	Bearing Retainer Kit, 250-70-18X
Parts Item Status	Received
Cost	\$17.89
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	33
Warehouse	Fort McMurray 01

AX Item Id	1007463
Work Order Task	
Catalog Item	Centre Bearing Assembly, 10094142
Parts Item Status	Received
Cost	\$99.14
Planned Quantity	1.00
Actual Quantity	1.00
Quantity On Hand	6

Warehouse **Fort McMurray 01**

AX Item Id **1004507**
Work Order Task
Catalog Item **Windshield Washer,Cap,Non-Vented, C5720S**
Parts Item Status **Received**
Cost **\$2.50**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **14**
Warehouse **Fort McMurray 01**

AX Item Id **1005124**
Work Order Task
Catalog Item **3" Male ADPTR x 3" Male NPT Camlock, G300-F-SS**
Parts Item Status **Received**
Cost **\$55.48**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **7**
Warehouse **Fort McMurray 01**

AX Item Id **1005460**
Work Order Task
Catalog Item **Wire Brush, 04NT608**
Parts Item Status **Received**
Cost **\$2.95**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **30**
Warehouse **Fort McMurray 01**

AX Item Id **1008796**
Work Order Task
Catalog Item **Coupling Grease Tube CHE23000310 Chevron**
Parts Item Status **Received**
Cost **\$5.51**
Planned Quantity **1.00**
Actual Quantity **1.00**
Quantity On Hand **15**
Warehouse **Fort McMurray 01**

AX Item Id **1003368**
Work Order Task
Catalog Item **Brake Clean, KLF 313**
Parts Item Status **Received**
Cost **\$2.99**
Planned Quantity **12.00**

Actual Quantity **12.00**
Quantity On Hand
Warehouse **Fort McMurray 01**

Work Order Third Parties

WO3P-0007453

Account
Date **12/18/2020**
Description **SS Wash Hose Door Latch**
Total Cost **\$96.27**
Quantity **1**
Part# **100-FT-1200-SS**
ETA **12/18/2020**

WO3P-0007451

Account **Pats Driveline**
Date **12/16/2020**
Description **Driveshaft/ Inspect/ Repair/ Re-Balance**
Total Cost **\$1,380.95**
Quantity **1**
Part#
ETA **12/16/2020**

WO3P-0007452

Account **Stahl Peterbilt-Edmonton**
Date **12/16/2020**
Description **OB/IB Front Wheel Bearings**
Total Cost **\$172.47**
Quantity **1**
Part# **2 Parts**
ETA **12/16/2020**

WO3P-0007436

Account **Stahl Peterbilt-Edmonton**
Date
Description **FAN, DOOR SEAL, RETAINER, TERMINALS**
Total Cost **\$516.15**
Quantity **1**
Part# **MULTIPLE**
ETA