

GUARANTEE RV CENTRE INC. 34 COMMERCIAL DR NW CALGARY AB T3Z 2A7 (PH) 403-273-1000



Stock No: 0324C

Stock Desc: 0324C 2003 CITATION-S

30RLDS

Model: 30RLDS

Seria#: 2GLBC54J437014487

Chassis#: Miles/Hrs: Tag#: 520K

Purchased Date: 16 SEP 04

Promised Date:

Completed Date: 28 NOV 22

Date In: 18 APR 22 Author: ATESFAI

Location: PICKUP DRAWER

ExtW Co: ExtW No:

INVENTORY APPROVED BUY/CONSIGN/TRADE

Job #1 - External

COMPLAINT: PLEASE DO EXTERIOR BODY WORK AS PER DAVE'S ESTIMATE CONTACT DESIGNERS FOR WHEN FILON IS AVAILABLE

CORRECTION: COMPLETED

Parts —— Part # 310-1	Description BLACK VINYL INSERT / FT.	Qty 10.00	Price 1.25	Total 12.50
Sublet Description DRIVERS SIDE OUTSIDE WALLS				Total 7,930.00
Other Service Code PF SSE	Description PARTS FREIGHT SHOP SUPPLIES - EXT	Qty 1.00 1.00	Price 0.00 0.00	Total 0.00 0.00
		Subtotal for Job #1:		7,942.50

Job #2 - External

COMPLAINT: PLEASE QUOTE AWNING REPLACEMENTS, FABRIC TAGGED IN SHIPPING **RH TORSION ASSEMBLY ON PO#89308**HERE

CAUSE: replace awning fabric

CORRECTION: remove old awning fabric and install new fabric NOTE; FRONT ROLLER DRIVE LOCK WILL NOT HOLD NEEDS TO BE REPLACED GAVE PICS TO PAT SO SHE COULD QOUTE CUSTOMER replace front roller drive and test working well now

Labour – Code SP364820 SP003100 SP003100 Z990	Description QUOTE AWNING FABRIC R&R SPADERAWNINGS AWNING FABRIC R&R SPADERAWNINGS CHANGE AWNING ROLLER		Mechanic MW1 MW1 MW1 MW1	Total 19.00 180.50 180.50 285.00
Part # 2755-3 37-0009	Description FABRIC ONLY 16' SANDSTONE TORSION SPRING ASSEMBLY WHT	Qty 1.00 1.00	Price 493.50 296.75	Total 493.50 296.75
Other Serv Code FRT	Description FREIGHT	Qty 1.00	Price 31.66	Total 31.66

Printed On: 2022-11-28 10:11:16AM © 2022 Integrated Dealer Systems



Subtotal for Job #2:

1,553.56

 Parts Total:
 802.75

 Labour Total:
 665.00

 Sublet Total:
 7,930.00

 Extras Total:
 98.31

Tax Total: 474.82
WORK ORDER TOTAL: 9,970.88

Extended Service Plan: Accepted Offered Refused (please initial)

I hereby authorize the repair work herin set forth to be done by you, together with the furnishing by you ofthe necessary parts and other material for such repair, and agree: that you are not responsible for any delays caused by unavailability or delayed availability of parts or materials for any reason; that you neither assume nor authorize any other person to assume for you any liability in connection with such repair; that you should not be responsible for loss of or damage to the above vehicle, or articles left therein, in case of fire, theft or other cause beyond your control; that an Express Mechanic's Lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto; that your employees may operate the above vehicle on streets highways or elsewhere for the purposes of testing and /or inspecting such vehicle.

I understand I will receive acall when the work is completed and I have 10 business days to pick up my vehicle before it becomes subject to atorage fees of \$35.00/day.

Guarantee RV is not responsible for hatteries or any damage to units that is attributable to freezing at any time.

Guarantee RV does not dump holding tanks.

Customer Signature :

Date: 28 Nov 2022






GUARANTEE RV CENTRE INC. 34 COMMERCIAL DR NW CALGARY AB T3Z 2A7

(PH) 403-273-1000





Stock No: 0324C

Stock Desc: 0324C 2003 CITATION-S

30RLDS

Model: 30RLDS

Serial#: 2GLBC54J437014487

Chassis#: Miles/Hrs: Tag#: 520K

Purchased Date: 16 SEP 04 Promised Date: 24 MAY 23 Completed Date: 16 MAY 23 Date In: 10 MAY 23 Author: JKRAUSERT Location: NICK COLLINS

ExtW Co: ExtW No:

Job #1147 - External

COMPLAINT: SPRING PACKAGE TRAILER BASIC

- ..GAS TEST AND CHECK APPLIANCES
- ..LOAD TEST AND INSPECT BATTERY
- ..FLUSH FRESH AND WASTE TANKS
- ..FLUSH ALL WATER LINES AND FAUCETS
- .. CHECK EXTERIOR LIGHTS
- ..ADJUST TIRE PRESSURE
- ..INSPECT ROOF SEAL

CAUSE: SPRING PACKAGE TRAILER BASIC ..

- 1. GAS TEST AND CHECK.
- 2. LOAD TEST AND INSPECT BATTERIES.
- 3. FLUSH FRESH WATER LINES, FAUCETS AND ALL HOLDING TANKS.
- 4. CHECK EXTERIOR LIGHTS.
- 5. ADJUST TIRE PRESSURE + WHEEL INSPECTION.
- 6. INSPECT ROOF SEAL.


PLEASE NOTE: Both smoke and C/O-L/P detectors are OOD and expiried. Waiting for owners aproval for replacement. Part cost and rough labour time given to Nick @ Service.

CORRECTION: 1. L/P systems inspected - Both L/P tanks have expiried dates so replaced with owners consent. L/P running test all good (Regulator set to 11 w/c). L/P leak test completed and all good.

- 2. Load tsted both 29-series batteries Please see battery job for further info.
- 3. Loaded 2/3 H2O onto unit. Noted water pump is split and leaking from it's middle. Replaced with new water pump with owners consent. De-wionterized unit and checked all plumbing systems. All check out good.
- 4. All exterior lights work as should.
- 5. Inspected wheels condition All breaking systems work as should. All tiures in good condition and have decent tread - Tread dpths are: Front R-side - 6.32mm. Rear R-side - 8.08mm. Front L-side - 6.26mm. Rear L-side - 7.68mm. Wheels and tires all check out good,.
- 6. Roof surfaces and seals checked. Noted some dicore degridation/cracking on top of kitchen slide. Owner consented to fix, so will apply new dicore to ensure sealed as should be. New dicore added to top of kitchen slide and now sealed as should be.

Estimated Amount: 440.00

Labour			
Code	Description	Mechanic	Total
SP373500	SPRING CHECK RV	JD1	100.00
SP373500	SPRING CHECK RV	JD1	0.00
SP373500	SPRING CHECK RV	JD1	192.50
SP373500	SPRING CHECK RV	JD1	195.00
SP373500	SPRING CHECK RV	JD1	0.00





Z990 MISC LABOUR CODE (EXTERNAL)			JD1	
Parts Part # 4588 645-7 1042-13 85-741-BL-TR	Description RECERTIFIED LP TANK30 SHURFLO PUMP REVOLUTION SMOKE ALARM 9V DUAL LP/CO ALARM-BLK.	Qty 2.00 1.00 1.00 1.00	Price 97.30 212.95 30.85 134.96	Total 194.60 212.95 30.85 134.96
Other Service Code SSE	Description SHOP SUPPLIES - EXT	Qty 1.00 Subtotal for Jol	Price 50.00 b #1147;	Total 50.00

Job #2 - External

COMPLAINT: BATTERIES HAVE BEEN IN THE TRAILER FOR THE LAST YEAR AND NOT REMOVED OVER THE WINTER. ASSUMMING THEY WILL NEED REPLACING. IF SO, PLEASE REPLACE WITH **NEW BATTERIES**

CAUSE: 1. BATTERIES HAVE BEEN IN THE TRAILER FOR THE LAST YEAR AND NOT RENOVED OVER THE WINTER. ASSUMING THEY WILL NEED REPLACING. IF SO PLEASE REPLACE WITH NEW BATTERIES.

CORRECTION: 1. Both 29-series batteries failed load/charge test. Replaced with 2 x new 27-series batteries. Now working as should.


Labour Code Z990 Z990	Description MISC LABOUR CODE (EXTERNAL) MISC LABOUR CODE (EXTERNAL)	10/4	Mechanic JD1 JD1	Total 7.60 87.40
Part # 27DC600	Description 27 SERIES DEEP CYCLE BATTERY	Qty 2.00	Price 180,60	Total 361.20
Other Serv Code SSE	Description SHOP SUPPLIES - EXT	Qty 1.00	Price 9.50	Total 9.50
	\$ 1 m	Subtotal fo	or Job #2:	465.70

Job #3 - External

COMPLAINT: INTERIOR DETAIL (DEB TO QUOTE BEFORE PROCEEDING) 05/15/2023 CUSTOMER APPROVED. \$100/HR. FLOORS, SURFACES, SHOWER, TOILET.

CORRECTION: INTERIOR CLEAN/DETAIL BEING DONE 05/16/2023

Labour Code Z990	Description MISC LABOUR CODE (EXTERN		Mechanic ZZ	
Other Servic Code SSE	Description SHOP SUPPLIES - EXT	Qty 1.00	Price 40.00	Total 40.00
41	3	Subtotal for	r Job #3:	440.00





Parts Total: 934.56 Labour Total: 1,039,50 **Sublet Total:** 0.00 Extras Total: 99.50 Tax Total: 103.69 **WORK ORDER TOTAL:** 2,177.25

Accepted Offered (please initial)

I hereby authorize the repair work herin set forth to be done by you, together with the furnishing by you ofthe necessary parts and other material for such repair, and agree: that you are not reaponsible for any delays caused by unavailability or delayed availability of parts or materials for any reason; that you neither assume nor authorize any other person to assume for you any liability in connection with such repair; that you should not be responsible for loss of or damage to the above vehicle, or articles left therein, in case of fire, theft or other cause beyond your control; that an Express Mechanic's Lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto; that your employees may operate the above vehicle on streets highways or elsewhere for the purposes of testing and /or inspecting such vehicle.

I understand I will receive acall when the work is completed and I have 10 business days to pick up my vehicle before it becomes subject to storage fees of \$35.00/day.

Guarantee RV is not responsible for batteries or any damage to units that is attributable to freezing at any time.

Guarantee RV does not dump holding tanks.

Customer Signature:

Date: 16 May 2023

