



4504 Roper Road Edmonton AB T6B 3T8 Phone:780.413.9422 Fax: 780.413.9428 DTNA: KDCD

Invoice No.	R002085293:01	
Invoice Date	07/28/2023	
Arrival Date	07/26/2023	
P.O. No	49-072623	
Customer No	11438	
Terms	NET30	
Unit No.	189560	
Customer Unit	49	
GST No.	11940 1776 RT0001	

Service Invoice





Take our Survey



Year: Colour: WHITE Advisor: 53526

Make:

Reviewer: 0960

License: MSE 084

Model:

Engine Hrs:

M2106 **Odometer In: 580,590** 5,979

Vin:

1FVACXDU18DZ94913

In Service Date: 04/10/2008 ESN/Make: 57787293-

Job# 1 QSP

SR.

FREE QUALITY SERVICE PLUS TRUCK INSPECTION - \$75.00 VALUE

CONDITION

FREE QUALITY SERVICE PLUS TRUCK INSPECTION - \$75.00 VALUE **

02/24

WAYNE 403-9993-4423

QTY ITEM DESCRIPTION

UNIT PRICE

EXTD PRICE

LABOR

0.00

Job# 1 QSP ---- PARTS: 0.00 -- LABOR: 0.00 -- TOTAL 0.00

Job# 2 EXPRESS

CUSTOMER COMPLAINT CHECK AND ADVISE

CONDITION

DRIVER SAID CAN'T SHIFT INTO 3RD GEAR-WAYNE DROVE UNIT HERE AND DID NOT HAVE AN ISSUE-SEE PREVIOUS INVOICE FROM CALGARY-MAY NEED TO SEND TO WAJAX-ALLISON TRANSMISSION-WAYNE APPROVED SUBLET TO WAJAX

CORRECTION

DECLINED REPAIR

LABOR

Job# 3 EXPRESS

SR

CUSTOMER COMPLAINT CHECK AND ADVISE

CONDITION

CEL

CORRECTION

CONFIRMED CEL ON AND ENGINE RUNNING ROUGH. 0555 (CC PRESSURE - ABOVE NORMAL OPERATING RANGE -MODERATELY SEVERE LEVEL) ACTIVE AND 0556 (CC PRESSURE - ABOVE NORMAL OPERATING RANGE - MOST SEVERE LEVEL) STORED. ENGINE OIL AT LEAST 5L LOW, ENGINE COVERED IN OIL. REMOVED TURBO INTAKE PIPE - FULL OF OIL. REMOVED LH BOOST PIPE - OIL. REMOVED CRANKCASE BREATHER COVER - THE BOLTS WERE SEIZED INTO THE ROCKER COVER SO ROCKER COVER AN BREATHER HOUSING REQUIRE REPLACING. REASSEMBLED COMPONENTS AND CHECKED CRANKCASE PRESSURE WITH ENGINE RUNNING - 28.9 INHG. DISCONNECTED TURBO DRAIN LINE AND CAPPED DRAIN LINE. TOPPED UP ENGINE OIL, RAN AND CHECKED - STILL 28.9. REASSEMBLED AND DISCONNECTED AIR COMPRESSOR LINES AND RECHECKED - 28.9. REASSEMBLED. REMOVED OIL FILTER, OPENED UP AND CHECKED FOR DEBRIS - NONE FOUND. INSTALLED NEW OIL FILTER AND WASHED OFF ENGINE.







- QII	Fig.(v)	DESCRIPTION	UNIT PRICE	EXTD PRICE
				1
		LABOR		827.40
1	002C/5255740	TUBE,LUB OIL DRAIN	58.35	58.35
1	002C/4936347	COVER, BREATHER	327.01	327.01
1	002F/FG CV52001	FILTER, CRANKCASE		
1	ABEF2	* - ENVIRO CHARGE FILTER OVER 200MM	129.27	129.27
1	002C/5311734	COVER,VALVE	1.00	1.00
			362.93	362,93
1	002C/5367847	GASKET,INTEGRATED WIRING	284.41	284.41
1	002C/5264568	GASKET,OIL DRAIN	6,46	6.46
		NON RETURNABLE PART	A	
1	002F/FG LF3970	' & : ' / as a ELEMENT-OIL FILTER		1,
1	ABEF1	* - ENVIRO CHARGE FILTER UNDER 200MM	22.04	22.04
1	002X/GLH G234-075		0.50	0.50
		ORTAC HOSE 3/4" - PER FT	5.45	5.45
(1)	002C/5255740	TUBE,LUB OIL DRAIN	58.35	-58.35
(1)	002C/4936347	COVER,BREATHER	327.01	-327.01
(1)	002C/5311734	COVER,VALVE		
(1)	002C/5367847	GASKET,INTEGRATED WIRING	362.93	-362.93
5	002F/ESO 105816	MOBIL DELVAĆ 15W40 CK-4(BULK)	284.41	-284.41
			5.64	28.20
5	ABE03	* - ENVIRO CHARGE BULK OIL	0.05	0.25
3	002F/FUL 83001	1/8 COMPRESSION SLEEVE	1,25	3.75
1	002F/FUL 85001	5/32 TUBE TO 1/8 NPT ELBOW	7.53	
				7.53
		Job# 3 EXPRESS PARTS: 204.45 LABOR: 827.40 TOTAL 1,0	31.85	

Job# 4 #00-00	SR	MISCELLANEOUS REPAIR
CONDITION	REPLACE TRANSMISSION DIPSTICK	
CORRECTION	DECLINED REPAIR	
	LABOR	







** Should your wheels be removed for any reason, please have them re-torqued after 150 kilometres **

As an Elite Support dealer, we inspect every job for quality of workmanship. A Quality Inspection Report is completed by a factory trained technician at the end of your repair.

Your QI report for RO# R002085293

was completed by staff ID#-

Please Remit Payment to:
First Truck Centre Edmonton West Inc
11313-170th Street
Edmonton, AB TSM 3PS

Total	\$ 1,152.94
GST	\$ 54.90
Subtotal	\$ 1,098.04
Misc Supplies	\$ 66.19
Sublet	\$ 0.00
Body Shop Supplies	\$ 0.00
Labor	\$ 827.40
Parts	\$ 202.70
Misc Charges	\$ 1.75
Deposits	\$ 0.00

I, the undersigned owner, or duly authorized representative, authorize the repair and service work as detailed on this repair order. Permission is also granted to your employees to operate the vehicle herein described on the streets, highways, or elsewhere for the purpose of testing and/or inspection. It is understood that First Truck Centre Inc. does not assume any responsibility whatsoever to vehicles or contents while in their possession.

****Disclaimer of Warranty****

Any warrantles on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and First Truck Centre neither assumes nor authorizes any other person to assume any liability in connection with the sale of the said products.

First Truck Centre shall not be liable for special, indirect or consequential damages, e.g.: down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc.

Falled parts return requests must be made when the unit is checked in.

Please be aware that any aftermarket modifications to OEM components are customer responsibility.

First Truck Centre assumes no responsibility for damage to any aftermarket component as a result of our diagnostics or repairs.

Workmanship is warranted for 90 Days from date of invoice. If a possible warrantable situation arises at a location other than First Truck Centre then First Truck Centre must be contacted to be involved in the repair decision.

I/we hereby acknowledge this invoice and an express garageman's lien thereon to secure full amount of indebtedness.

I/We agree to pay Interest at the rate of 2% per month (24% per annum), if the balance due is not paid within the credit terms of First Truck Centre. I/We also agree to pay storage fees of fifty dollars (\$50.00) per day, both before and after judgment plus all costs incurred in the collection of the balance owing, legal fees and disbursements on a solicitor client basis.

Authorized by:	Released by:		
Printed Name:	Date:	Time:	





