



Sandy Lane Automotive South
8105 - Argyll Road
Edmonton, Alberta T6C 4B2
Phone: 780-469-0075 ~ Fax: 780-465-4958
www.sandylaneauto.com

Invoice

Bill To: [REDACTED]
Canada

Home: [REDACTED]
Email: [REDACTED]

Invoice # 71505
Work Order # 88974
Service Advisor Cassandra Carey
Technician Ivan Francetic

Plate AB CRW-1189
Description 2006 Audi A8 Quattro L V8 4.2L 4172CC
VIN WAUML44E16N019722
Odometer 233,313

Invoice Date 3/4/2024 12:54 PM
Appointment 2/28/2024 8:00 AM
Promised 2/28/2024 5:00 PM

Inspection

Engine System / Network Scan and Minor Diagnostic Inspection - SUSPENSION LIGHT ON THE DASH - CUST HAS NO SUSPENSION

Drivability issue can be reproduced consistently during a basic road test or at idle. Interrogate the relevant vehicle network computer along with companion modules. Research any relevant Technical Bulletins that may relate to the issue. Perform minor diagnostic processes to determine diagnostic direction or to qualify the failure.

Labor	\$192.00 *G
Sub	\$192.00

85 Point Inspection

Labor - With Alignment Check	\$59.99 *G
Sub	\$59.99

Service

Air Conditioning Compressor

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Suspension Compressor	1 Unit	\$1,597.44 / Unit	\$276.12 *G
		Sub	\$1,873.56

Total Parts	\$1,597.44
Total Labor	\$528.11
Total Before Taxes & Miscellaneous Charges	\$2,125.55

(*) Shop Supplies		\$36.97 G
(B) Canadian Goods and Services Tax (GST)	5 %	\$108.13
Grand Total		\$2,270.65

Harbiwchuk, John paid \$2,270.65 by Debit

3/4/2024 12:56 PM Card #: XXXXXXXXXXXX1547 Entry Method: Chip Type: Sale Amount: 2270.65

Terminal: 70430 Transaction: bffa42be-7382-4a98-88a5-89d6df3ab527 Authorization: 165674 Result: Approved

MD: 00000000000000000000000000000000 TC: ARQC: F976D0485C8BBC17 TVR: 0000008000 TSI: E800

COPY

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

We thank you for your business!

*ALSO REMINDER, THAT WHEN WHEELS ARE REMOVED DURING SERVICE THEY MUST BE RETOURQUED AFTER 100KM OF DRIVING. Were your wheels removed today? YES / NO.

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Authorized Signature

3/4/2024 12:57 PM \$283.11

Engine System / Network Scan and Minor Diagnostic Inspection - SUSPENSION LIGHT ON THE DASH - CUST HAS NO SUSPENSION
85 Point Inspection
Authorized by Harbiwchuk, John

3/4/2024 12:57 PM

Invoice #71505

Page 1 of 7



Sandy Lane Automotive South
8105 - Argyll Road
Edmonton, Alberta T6C 4B2
Phone: 780-469-0075 ~ Fax: 780-465-4958
www.sandylaneauto.com

Invoice

Bill To [REDACTED]
[REDACTED]
Home [REDACTED]
Email [REDACTED]

Plate AB CRW-1189
Description 2006 Audi A8 Quattro L V8 4.2L 4172CC
VIN WAUML44E16N019722
Odometer 233,313

Invoice # 71505
Work Order # 88974
Service Advisor Cassandra Carey
Technician Ivan Francetic

Invoice Date 3/4/2024 12:54 PM
Appointment 2/28/2024 8:00 AM
Promised 2/28/2024 5:00 PM

Inspection

Engine System / Network Scan and Minor Diagnostic Inspection - SUSPENSION LIGHT ON THE DASH - CUST HAS NO SUSPENSION

Drivability issue can be reproduced consistently during a basic road test or at idle. Interrogate the relevant vehicle network computer along with companion modules. Research any relevant Technical Bulletins that may relate to the issue. Perform minor diagnostic processes to determine diagnostic direction or to qualify the failure.

Labor

\$192.00 *G

Sub \$192.00

35 Point Inspection

Labor - With Alignment Check

\$59.99 *G

Sub \$59.99

Service

Air Suspension Compressor

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor

\$276.12 *G

Suspension Compressor

1 Unit

\$1,597.44 / Unit

\$1,597.44 G

Sub \$1,873.56

Total Parts

\$1,597.44

Total Labor

\$528.11

Total Before Taxes & Miscellaneous Charges

\$2,125.55

(*) Shop Supplies

\$36.97 G

(G) Canadian Goods and Services Tax (GST)

5 %

\$108.13

Grand Total

\$2,270.65

Harbiwchuk, John paid \$2,270.65 by Debit

3/4/2024 12:56 PM Card #: XXXXXXXXXXXX1547 Entry Method: Chip Type: Sale Amount: 2270.65

Terminal: 30430 Transaction: bffa42be-7382-4a98-88a5-89d6df3ab527 Authorization: 165674 Result: Approved

AC: 000002771010 TC: ARQC: F976D0485C8BBC17 TVR: 0000008000 TSI: E800

Buyer Agrees to pay total amount above according to cardholder's agreement with issuer.

COPY

We would like to thank you for your business!

**ALSO REMINDER, THAT WHEN WHEELS ARE REMOVED DURING SERVICE THEY MUST BE RETOURQUED AFTER 100KM OF DRIVING. Were your wheels removed today? YES / NO.

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Authorized Signature

3/4/2024 12:57 PM \$283.11

Engine System / Network Scan and Minor Diagnostic Inspection - SUSPENSION LIGHT ON THE DASH - CUST HAS NO SUSPENSION
85 Point Inspection
Authorized by Harbiwchuk, John

3/4/2024 12:57 PM

Invoice #71505

Page 1 of 7

Specialty(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Spark Plugs BKR6E NGK	8 Unit	\$8.50 / Unit	\$294.98 *G
			\$68.00 G
		Sub	\$362.98

Drive Belt(s), Drive Belt Tensioner(s) and Idler Assembly(s)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

			\$238.38 *G
Drive Belt-Primary	1 Unit	\$73.10 / Unit	\$73.10 G
Drive Belt Tensioner - cust to prepay for part before going ahead	1 Unit	\$394.65 / Unit	\$394.65 G
Idler Pulley	1 Unit	\$94.73 / Unit	\$94.73 G
Idler Pulley	1 Unit	\$81.84 / Unit	\$81.84 G
		Sub	\$882.70

\$2,278.97

\$3,083.81

Taxes & Miscellaneous Charges

\$5,362.78

Supplies

\$125.00 G

Material Disposal

\$5.00 Each

\$20.00 G

Goods and Services Tax (GST)

5 %

\$275.39

\$5,783.17

COPY