

DEFINE MOTORS 15830 111 Ave NW Edmonton, AB T5M 2R8

587-521-8197 definemotors@gmail.com

Tax ID#

Invoice



Invoice # 2120 Work Order # 242 Service Advisor Levar Bennett Technician 11

Plate AB CDS-4812 Description Blue 2010 Subaru Impreza WRX STI H4 2.5L 2458CC VIN JF1GR8H68AL813099

Odometer 270,383

Invoice Date 8/2/2024 3:26 PM Appointment 7/29/2024 11:03 AM Promised 7/29/2024 5:00 PM

Concern

Reason for Today's Visit / Additional Notes

Enter Notes here

1- clutch inoperative

3-

Add Notes Here...

Inspection

A - Complimentary Visual Inspection

(Includes Section "C")

Service

Tech Notes:

add notes here

Clutch Master Cylinder

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor

Clutch Master Cylinder

Brake Fluid

Clutch Slave Cylinder-ALTROM

Total Before Taxes & Miscellaneous Charges

DOT-3

1 Unit

\$246.50 G \$249.23 G

\$249.23 / Unit

\$44.45 G

1 Unit

\$44.45 / Unit

Sub

Sub

\$540.18

Clutch Slave Cylinder

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor

1 Unit

\$203.00 G \$114.21 / Unit

1 Unit

\$44.95 / Unit

\$114.21 G \$44.95 G

\$362.16

Brake Fluid DOT-3

Total Parts

Total Labor

\$452.84 \$449.50

\$902.34



HURST AUTOMOTIVE LTD

16617-111 AVE

EDMONTON, AB. T5M-2S2

Phone: 780-487-7846 Fax: 780-487-7894

hurstautomotiveltd.com

INVOICE

53033

Org. Est. # 061441 GST 870640505

INVOICE

Printed Date: 05/02/2024

Work Completed: 04/30/2024

2010 Subaru - Impreza WRX STi - 2.5L, H4 (150CI) VIN(8)

Lic #: CRP-8512

Odometer In: 267504

Cellular OTHER

VIN #: JF1GR8H68 AL813099

Part Description

Qty Sale Ext. Labor Description

Ext

[Payments -]

Hurst Auto doesn't assume any responsibility whatsoever, under any circumstances, for vehicles left for repairs, storage, other purposes, for articles left in vehicles or while Company is doing test drives. This is at owner's risk. An expressed mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. Parts/Labor coverage is 90 Days, Parts Only 1yr. Terms Net 30 Days, 2% on all overdue accounts. No warranty is given on used/customer supplied parts this includes out of pocket expenses.

Labor: 449.60 Parts: 91.17 Sublet: 508.80 HazMat: 0.67 Sub: 1,050.24

Tax: 52.52 Total: \$1,102.76 Bal Due: \$1,102.76

Customer Number: 219

Vehicle Received: 4/30/2024 Signature

Visit us on the web: www.hurstautomotive.com

Date_

Email Address: hurst.auto@hotmail.com

HURST AUTOMOTIVE LTD

16617-111 AVE

EDMONTON, AB. T5M-2S2

Phone: 780-487-7846 Fax: 780-487-7894

hurstautomotiveltd.com

INVOICE

53033

Org. Est. # 061441 GST 870640505

INVOICE

Printed Date: 05/02/2024

Work Completed: 04/30/2024

2010 Subaru - Impreza WRX STi - 2.5L, H4 (150CI) VIN(8) Lic #: CRP-8512

Odometer In: 267504

Cellular @@@

VIN #: JF1GR8H68 AL813099

OTHER CONTROL OF STREET					VIIV # . 3F 1GROFIGO ALC 13039	
Part Description	13*05	Qty	Sale	Ext	Labor Description	Ext
OIL FILTER 5W30 API SP/GF-6 cert premium SYTH BLEND / BULK OIL DRAIN PLUG GASKET	3 8	1.00 4.00	6.37 6.25	6.37 25.00	ADVISE IF ANY WORK IS NEEDED . ADVISE IF THERE IS	99.95 DRM . ANY
X2/Engine Oil Drain Plug Gasket Shop Supplies ENVIRONMENTAL FEE	ia .	1.00	2.30	2.30 57.50 0.67	DISMOUNT WHEEL FOR REPAIR / RIGHT FRONT DISMOUNT WHEEL	31.00
×.					GET COLOR MATCH CODE FOR TOUCH UP PAINT REPAIR AND MACHINE FRONT AND BACK SIDE OF WHEEL / PREP AND BLEND IN FINISH REPAIR AND MACHINE FRONT AND BACK SIDE OF WHE PREP AND BLEND IN FINISH / INV# 46396	n/c 270.00 EL /
					NEW REMOTE PHOEBE OR NEW INSTALL FOR ALARM ????	n/c
er er	,			2	install new windshield install new windshield inv# 2694	238.80
- X-	-		200		Change Motor Oil Lube Chassis / SYNTHETIC OIL Changed Motor Oil & Replaced Filter, Added Synthetic Moto Lube Chassis, Check all Fluid Levels	46.50 r Oil,
,			e		Air conditioning service with or without leak detection dye Service air conditioner. Check condition of all belts and lines Evacuate and recharge with reclaimed R-134. Test system performance./ INSTALL LEAK DETECTION DYE AND OIL	193.75
					INSTALL WIRING FOR RADAR DETECTOR / CUSTOMER SUPPLIED INSTALL WIRING FOR RADAR DETECTOR / CUSTOMER SUPPLIED	46.50
	on:				Mount and balance on performance tire. / REPAIRED WHEEL RIGHT FRONT Mount and balance using tape weights and high speed balant torqued wheel nuts or studs to spec.	31.90 ce.
#1 	\$7°		91		, i	

[Payments -]

Hurst Auto doesn't assume any responsibility whatsoever, under any circumstances, for vehicles left for repairs, storage, other purposes, for articles left in vehicles or while Company is doing test drives. This is at owner's risk. An expressed mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. Parts/Labor coverage is 90 Days, Parts Only 1yr. Terms Net 30 Days, 2% on all overdue accounts. No warranty is given on used/customer supplied parts this includes out of pocket expenses.

Labor: 449.60 Parts: 91.17 Sublet: 508.80 HazMat: 0.67 Sub: 1,050.24 Tax: 52.52 Total: \$1,102.76 Bal Due: \$1,102.76

Customer Number: 219

Vehicle Received: 4/30/2024

Signature,

Visit us on the web: www.hurstautomotive.com

Date_

Email Address: hurst.auto@hotmail.com

MECHANICAL FITNESS ASSESSMENT

As required by Vehicle Inspection Regulation (A/R 211/2006)

each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column C N Parking/Emergency Brake Hydraulic Systerm Drum Brakes Disc Brakes Disc Brakes Shoes/Pads Anti-Lock (if 0EM equipped) C N Steering C N Steering Linkage Rack & Pinion Power Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struct and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Trouble Codes Diagnostic Trouble Codes Alternator	Dealer:			AMV	IC Licence Number:	
Make: SUBARU Model: AMPRETA Wax Stepension: AMALES HESS ALS 13 09 7 Odometer Reading: 26 7 5 5 4	Address:		n n			
each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column C N Parking/Emergency Brake Hydraulic System Vacuum System Vacuum System Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Linkage Rack & Pinion Power Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Diagnostic Touble Codes Atternator Othe Motorized RV Othe Aution Frame & Body Hood Latch Door Latches & Hinges Bumpers Windshield Wipers & Washer Rear Wiper & Washer Windshield Windows Defrost/Heaters Milrors Seats S	and the second s		VEHICLE INFORMATI	ON		
each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column C N Parking/Emergency Brake Hydraulic System Vacuum System Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Linkage Rack & Pinion Power Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Struts and Shocks Coil spring C N Leaf springs Struts and Shocks Coil spring C N Leaf springs Struts and Shocks Coil spring C N Diagnostic C N Diagnostic C N Diagnostic Trouble Codes Alternator Othe Motorized RV Auto Motorized RV Othe Motorized RV Othe Motorized RV Othe Auto Applicable indicate as N/A in the C column Frame & Body. C N Hood Latch Door Latches & Hinges Bumpers Windshield Windows Windshield Windows Defrost/Heaters Mirrors Seats	Year: 2010 Make:	Subpl	U Model: IMPREZA	WRXS	TPrevious Province of Registration:	
each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column C N Parking/Emergency Brake Hydraulic System Vacuum System Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Linkage Rack & Pinion Power Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Light Truck Notation Motorized RV Auto Motorized RV Motorized RV Motod Applicable indicate as N/A in the C column Frame & Body Hood Latch Door Latches & Hinges Bumpers Windshield Wipers & Washer Rear Wiper & Washer Windshield Windows Defrost/Heaters Mirrors Seats Seats Seats Belts/Alrbags Mudquards Window Glazing Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Diagnostic Trouble Codes Alternator	National Identification Number TE	11.084	1811812099 Adames	or Poading:	267 504	A (km/mi)
each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column C N Parking/Emergency Brake Hydraulic System Vacuum System Drum Brakes Disc Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering C N Steering Linkage Rack & Pinlon Power Steering System King Pin Ball Joints Suspension C N Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic C N Diagnostic C N Diagnostic C N Diagnostic C N Diagnostic Trouble Codes Parking/Emergency Brake C N Parking/Emergency Brake Phood Latch Door Latches & Hinges Bumpers Windshield Wipers & Washer Windshield Windows Defrost/Heaters Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structual Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	venicie identification Number: 7.7					47
C N Parking/Emergency Brake Hydraulic System Vacuum System Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Structs and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Parking/Emergency Brake Hood Latch Door Latches & Hinges Bumpers Windshield Wipers & Washer Windshield Wipers & Washer Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tirea & Wheels Tread Depth Tread Section Sidewalls Wheels Pisagnostic C N Wiring Battery Switches Aiternator	Truck Motorcycle	Bus	Van Light Trud	X	Auto Motorized RV	Othe
Parking/Emergency Brake Hydraulic System Vacuum System Drum Brakes Disc Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Rack & Pinion Power Steering System King Pin Ball Joints Suspension C N Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Diagnostic Trouble Codes Hood Latch Door Latches & Hinges Bumpers Windshield Windshield Wipers & Washer Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tiread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Please check mark (✓) each it	em as C=Co	mplies or N=Non-Compliant. If it	em is Not A	pplicable indicate as N/A in 1	he C column
Hydraulic System Vacuum System Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic C N Diagnostic Trouble Codes Diagnostic Trouble Codes Diagnostic Frouble Codes Door Latches & Hinges Bumpers Windshield Wipers & Washer Windshield Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tiread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Powertrain	C N		C N		C N
Vacuum System Drum Brakes Disc Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Bumpers Windshield Windows Defrost/Heaters Mirrors Seats Se	Accelerator					
Drum Brakes Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Diagnostic Diagnostic Trouble Codes Windshield Wipers & Washer Rear Wiper & Washer Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudguards Window Glazing Structural Integrity Tires & Wheels Tread Depth Tread Section Sidewalls Wiring Battery Switches Alternator	Fuel System					
Disc Brakes Shoes/Pads Anti-Lock (if OEM equipped) Steering Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Trouble Codes Rear Wiper & Washer Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tirea & Wheels Tiread Depth Tread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Exhaust	~				
Shoes/Pads Anti-Lock (if OEM equipped) Steering C N Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Windshield Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudguards Window Glazing Structural Integrity Tiread Depth Tread Depth Tread Section Sidewalls Wheels Electrical Wirring Battery Switches Alternator	Transmission			-		- 10
Anti-Lock (if OEM equipped) Steering Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Windows Defrost/Heaters Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tirea & Wheels C N Tread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Front/Rear/Spindles Axles					
Steering C N Steering Linkage Steering Linkage Steering Linkage Seats Se	Clutch					
Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Mirrors Seats Seat Belts/Airbags Mudquards Window Glazing Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Fluid Levels (power steering, brake)		Anti-Lock (if OEM equipped)			
Steering Lash Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Mintrols Seats Seat Belts/Airbags Mudguards Window Glazing Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	CV Joints		Steering	C N		
Steering Linkage Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Structural Integrity Tires & Wheels Tread Depth Tread Section Sidewalls Window Glazing Structural Integrity Tires & Wheels Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Lamps	C N				
Rack & Pinion Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Rudquards Window Glazing Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Head Lamp Hi Beam					
Power Steering System King Pin Ball Joints Suspension Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Mindow Glazing Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Head Lamp Lo Beam					
King Pin Ball Joints Suspension Leaf springs Strutts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Window Glazhit Structural Integrity Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Head Lamp Location					
Ball Joints Suspension C N Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic C N Diagnostic Trouble Codes Struttan megnty Tires & Wheels Tiread Depth Tread Section Sidewalls Wheels Electrical C N Wiring Battery Switches Alternator	Daytime Running Lamps					
Suspension C N Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multillink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Tires & Wheels Tread Depth Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Tail Lamps				Structural Integrity	
Suspension C N Leaf springs Struts and Shocks Coil spring C N Tread Depth Tread Section Sidewalls Wheels Florsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Tread Depth Tread Section Sidewalls Wheels Flectrical Wiring Battery Switches Alternator	Brake Lamps		Dali Joillo		Tires & Wheels	C N
Leaf springs Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Tread Section Sidewalls Wheels Electrical Wiring Battery Switches Alternator	Turn Signal Lamps		Suspension	C N		
Struts and Shocks Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Sidewalis Wheels Electrical Wiring Battery Switches Alternator	Hazard Warning Lamps		Leaf springs			
Coil spring Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Wheels Electrical Wiring Battery Switches Alternator	Licence Plate Lamp		Struts and Shocks			
Torsion Bar Independent/Multilink Rear Computer Controlled Diagnostic Diagnostic Trouble Codes Torsion Bar Electrical Wiring Battery Switches Alternator	Back-up Lamps		Coil spring	\checkmark		
Independent/Multilink Rear Wiring Battery				-		6 11
Diagnostic C N Switches Alternator	Instruments	C N	Independent/Multilink Rear			CIN
Diagnostic C N Switches Diagnostic Trouble Codes Alternator	Speedometer/Odometer		Computer Controlled			
Diagnostic Trouble Codes Alternator						
nts			Diagnostic Irouble Codes	VI	Alternator	
	Technician Comments				3	
	Z11		- B		i india	×
			H ₁			
A STATE OF THE STA			<i>y</i> .			
	*!	1+		100	(6)	
	Indicator Lamps Horn Hi Beam Indicator Technician Comments This is to certify that I have as	ssessed the	Diagnostic Diagnostic Trouble Codes vehicle described above in accord	lance	Battery Switches Alternator I, the buyer of this vehicle,	
	4 #	14		(- 0)	* 45	
	This is to certify that I have as	ssessed the	vehicle described above in accord	lance		
have assessed the vehicle described above in accordance I, the buyer of this vehicle, acknowledge	with the <i>Traffic Safety Act</i> , Vel	hicle Equipr	nent Regulation (A/R 122/2009). ents of this document are true ar	By d correct.	receipt of this assessment.	
have assessed the vehicle described above in accordance I, the buyer of this vehicle, acknowledge receipt of this assessment.	•	ny the tone				
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By receipt of this assessment. receipt of this assessment.					Signature of Buyer	4
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By nt, I verify the contents of this document are true and correct. Signature of Buyer	ignature of Certified Journeyr	nan Technici	an: - 4314		- 49	
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By nt, I verify the contents of this document are true and correct. Signature of Buyer	17-17	2				
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By nt, I verify the contents of this document are true and correct. Signature of Buyer	echnician Name (Print):	4,	9 (9) (9)	r selfters	buyer (Fillity	,A
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By nt, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print)	centician warne (FIIII):		5 ,	-	Cidnoture of Colorogram	<u> </u>
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By nt, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print)	achnician Trado Cortificato Nu	mher			signature of Salesperson	*
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By Int, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print) Signature of Salesperson	echnician Trade Certificate Nu	mper;				
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By Int, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print) Signature of Salesperson					Salesperson (Print)	
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By Int, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print) Signature of Salesperson	Pate:					
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By Int, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print) Signature of Salesperson Signature of Salesperson	his assessment aunives 170 days a	fter the date is	halisəl əkur		Date	
have assessed the vehicle described above in accordance Act, Vehicle Equipment Regulation (A/R 122/2009). By Int, I verify the contents of this document are true and correct. Signature of Buyer Buyer (Print) Signature of Salesperson Salesperson (Print)	III G G S S S S S S S S S S S S S S S S	rect rise date H	***** 1334CU:		_ ~ ~ ~	