



GST/HST #: 122234156
Printed Date: 1/31/2024 8:17:17 AM

BIG RIG COLLISION
5834 GATEWAY BLVD NW
EDMONTON, AB T6H2H6
(780) 434-7471, (780) 437-6672 Fax

INVOICE
RO# 22617

Est: Kevin Bawol

Birch Mountain Enterprises LP	15 Peterbilt 367	Adjustor: Phone: Claim #: Deductible: 0 Loss Type: Unknown
PO Box 5445	Color:	
Fort McMurray, AB T9H 3G4	Type: CO	
Home:	VIN: 1NPTX4TX0FD250017	
Work: 780-824-1128	Prod Date: Plate: AB 68-N575	
Cell:	Odometer:	
	Engine:	

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
	Parts Existing	Frt Bumper Assembly				Body	Rpr	2.5		C
		Straighten best as possible and polish s								C
	Parts New	Bumper Light Wiring & Pins				Mech	Repl	1.0		C
	Parts Existing	Straighten Grille @ Lower Best As Possib				Body	Rpr	1.5		C
	Parts Existing	R Front Combination Lamp				Body	R&I	0.5		C
	Parts Existing	Hood Assy				Body	R&I	1.5		C
	Parts Existing	R Splash Guard				Body	R&I	0.4		C
	Parts Existing	Hood Assy A				Body	Rpr	14.0		C
		Right Black Fender Only (inner and outer								C
	Parts Existing	Hood Outside					Refn		4.0	C
		Right Black Fender Only								C
	Parts Existing	R Hood Inner Structure inc remove/Instal				Body	Rpr	6.0		C
	Parts Existing	L Inner Hood				Body	Rpr	2.5		C
1	Parts New	L Hood Catch	L03-0001	43.10		Body	Repl	0.2		C
1	Parts New	Hood Wheel Opening Moulding	L42-6006-0475	82.49		Body	Repl	0.5		C
1	Parts New	Hood Extender	15-04486-1230	252.24		Body	Repl	1.0		C
1	Parts New	R Fender Panel Extension	L35-6023-300R	3,239.99		Body	Repl	0.5		C
		R Fender Extension					Refn		1.0	C
		R Add For Inside					Refn		0.5	C
1	Parts New	R fender Light - Wire In	TLED-FPCA	32.22		Body	Repl	0.8		C
1	Parts New	Fender Wheel Opening Moulding	15-04486-0650	254.74		Body	Repl	0.6		C
1	Parts Used	R Lwr Side Step	N.A.	625.00		Body	Repl	0.2		C
1	Parts New	R Frt Susp Leaf Spring -M	59-594ME	762.50		Mech	Repl	1.7		C
2	Parts New	Steer Axle U-bolts	UB7832	75.50		Mech	Repl	2.4		C
1	Parts New	2" Spacer Block	2INSPACER	362.49		Mech	Repl			C
1	Parts New	Dowel - Step	02-01702	19.35		Mech	Repl			C
1	Parts New	R Frt Susp Shock Absorber -M	HS85062	99.49		Mech	Repl	0.5		C
1	Parts New	L Frt Susp Shock Absorber -M	HS85062	99.49		Mech	Repl	0.3		C
1	Parts New	R Frt Susp Dust Shield -M	K249362K	231.85		Mech	Repl	0.3		C
	Parts Existing	R Frt Susp Spindle -M				Mech	R&I	3.5		C
1	Parts New	Magnaflux R Kingpin and Spindle		128.00		Mech	Repl	1.2		C
2	Parts New	Steer Wheel Seal	382-8064	154.60		Body	Repl			C
1	Parts New	Hub Oil	Inventory	36.00		Body	Repl			C
1	Parts New	Steering Stop	971454ETN	30.99		Mech	Repl	0.3		C

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
1	Parts New	R Air Cleaner Assembly	A130143	1,500.00		Body	Repl	1.0		C
1	Parts New	R Exhaust Muffler Guard	M46-6177	550.00		Body	Repl	0.5		C
1	Parts Used	Muffler Guard Handle	M56-6001	300.00		Body	Repl	0.3		C
	Parts Existing	R Exhaust Muffler				Body	Algn	1.0		C
1	Parts New	R Exhaust Pin Kit	M11-8774-004	273.49		Body	Repl	0.8		C
	Parts Existing	R Frt Door Assembly				Body	R&I	1.0		C
	Parts Existing	R Frt Door Repair Panel				Body	Rpr	3.0		C
		R Frt Door Outside					Refn		4.0	C
1	Parts New	R Door Mirror Assy inc wiring	R59-6102-007	463.49		Body	Repl	1.2		C
1	Parts AM	R Convex Mirror inc wiring	10811	78.94		Body	Repl	0.8		C
1	Parts New	R Door Curb Mirror	716858-1	47.24		Body	Repl	0.3		C
	Parts Existing	R Frt Otr Door Sill				Body	Rpr	0.5		C
1	Parts Used	Mirror Arms		937.50		Body	Repl			C
1	Bdy/Sup	Shop Materials		1,726.00			Addl			C
1	Pnt/Mat	Paint/Materials		735.00			Addl			C
1	Haz	Hazardous Waste Disposal		28.35			Addl			C
	Parts Existing	Frame - Check and Report				Frame	Addl	2.0		C
	Parts Existing	Mechanical Inspection				Mech	Addl	1.5		C
	Parts Existing	Pre Repair Scan				Mech	Addl	1.0		C
	Parts Existing	Post Repair Scan				Mech	Addl	1.0		C
	Parts Existing	Scan & Tint Colour					Addl		1.0	C
	Body Materials	Mask for Overspray				Body	Addl	2.0		C
	Sublet	Tri-Axle All Wheel Alignment				Mech	Addl	3.5		C
		Adjusted 3 rear axles. Installed shims.								C
	Parts Existing	Steering Boxes x2				Mech	R&I	7.0		C
	Parts Existing	Frame Repairs				Frame	Rpr	12.0		C
2	Misc	Steering Boxes - Master & Slave		1,214.30		Body	Repl			C
1	Parts New	Power Steering Filter	57557	37.09		Body	Repl			C
1	Parts New	Power Steering Fluid	Inventory	75.00		Body	Repl			C
	Parts Existing	Road Test				Body	Addl	1.0		C
	Parts Existing	Clean Unit				Body	Addl	1.0		C
1	Parts New	Structural Adhesive Adjustment	04672	224.45 -0.01		Body	Repl			C
						Parts			12,231.54	
						Labor			14,490.00	
						Additional Costs			2,489.35	
						Frame Repair			2,660.00	
						Sublet			0.00	
						SubTotal			31,870.88	
						PST			0.00	
						GST/HST			1,593.55	
						Grand Total			33,464.43	

Due from Insurance		Due from Customer	
SubTotal	0.00	SubTotal	31,870.88
Tax	0.00	Tax	0.00
GST/HST Tax	0.00	GST/HST Tax	1,593.55

Grand Total	----- 0.00	Grand Total	----- 33,464.43
		Total Amount	33,464.43

One or more of your tires were off for inspection. Wheels must be retorqued within 150km. Failure to do so may result in damage to your vehicle, or an injury may occur.