



Finished Work Order

Identification: FWO122840 UDN104806	Enterprise:	Date/Time Printed: 10/23/24 10:06:54 AM
Description: REPLACE CLUTCH	Region:	Pages/Printed By: 1 JARED.MCRANN
Address:	Facility: BME	
	Vend. Inv:	

Priority: Routine	Meter Reading:	Date Created: 3/24/2023
Order Type:	Supervisor:	Date Started: 3/25/2023
Maint. Type:	Technician: TYLER TOBIN	Date Completed: 3/5/2024
Work Code:	OSP:	Serial No.: 1NPTX4TX3ED240225
Failure Code:	Policy No.:	Asset ID: HV09

Requirements	Type	No.	Description	Actual Quantity
	Item	0009280367	SHAFT SEAL	0
	Item	513877ETN	KIT-THRU SHAFT	0
	Item	513877ETN	KIT-THRU SHAFT	0

Step	Done	Description	Assigned	Unit Cost	Actual Time	Test Results	Unit of Measure
1	True	Kilometers reading	VINCENT DUPERON	105.00	0.00		KM
2	True	Meter Reading	VINCENT DUPERON	105.00	0.00		HOUR
3	True	REPAIR PARTS	VINCENT DUPERON	105.00	0.00		

Requirements	Type	No.	Description	Actual Quantity	Unit Cost
	Item	308925-25	CLUT EP 15.5,2050 TORQ,VC	1	1235.00
	Item	K3762	CLUTCH INSTALLATION KIT	1	399.73
	Item	CS106C1498	SHAFT-CROSS, CLUTCH	1	13.44
	Item	06-01093	SHAFT-CLUTCH P123	1	85.61
	Item	CB313SP	BRAKE-CLUTCH, 2" LOCKING,	1	51.94
	OSP	OSP000003	RESURFACE CLUTCH	0	111.89
	Item	210737DAN	SEAL-OIL	2	59.77
	Item	513877ETN	KIT-THRU SHAFT	2	170.78
	Item	KL-31219	CD50 SYNTHETIC TRANSMISSION OIL KLONDIKE SAE50 18.9L TF4080	2	249.95

TAG Resources Cost	
Tool Cost	
Item Cost	2746.72
OSP Cost	
Other Cost	
Total Cost	2746.72