



Finished Work Order

Identification: FWO122856 UDN104845

Description: REPLACE REAR DIFFS

Address:

Enterprise:

Region:

Facility: BME

Vend. Inv:

Date/Time Printed: 10/23/24 10:18:21 AM

Pages/Printed By: 1 JARED.MCRANN

Priority: Routine

Order Type:

Maint. Type:

Work Code:

Failure Code:

Meter Reading:

Supervisor:

Technician: TYLER TOBIN

OSP:

Policy No.:

Date Created: 3/29/2023

Date Started: 3/30/2023

Date Completed: 3/5/2024

Serial No.: 1NPTX4TX3ED240225

Asset ID: HV09

Requirements	Type	No.	Description	Actual Quantity
	Item	0009280367	SHAFT SEAL	0
	Item	CM10082217	HUB	0
	Item	504060ETN	KIT-BEARING	0

Step	Done	Description	Assigned	Unit Cost	Actual Time	Test Results	Unit of Measure
1	True	Kilometers reading	GREGG WHITESELL	105.00	0.00		KM
2	True	Meter Reading	GREGG WHITESELL	105.00	0.00		HOUR
3	True	REPAIR PARTS	GREGG WHITESELL	105.00	0.00		

Requirements	Type	No.	Description	Actual Quantity	Unit Cost
	Item	D170DP 4.10R	REAR DIFF D170P 4.10R	2	4315.50
	Item	131095QG	NUT	2	38.31
	Item	170-4-08461-1X	SPL170 YOKE 2.544-49SP 3.820HUB 2.675LTH 6.81CE	1	824.51
	Item	CM10082217	HUB	4	591.63
	Item	504060ETN	KIT-BEARING	2	180.06
	Item	CS8SC062750	5/8 X 7-1/2 GR8 PL NC BOLT	1	6.58
	Item	210737DAN	SEAL-OIL	1	59.77
	Item	131096ETN	CAP DIFF LOCK	1	17.77

TAG Resources Cost	
Tool Cost	
Item Cost	12342.89
OSP Cost	
Other Cost	
Total Cost	12342.89