

NCHS inc.

524 King Street
Spruce Grove, T7X 1B3
7807771996
GST# 710417148RT0001

Date

04/06/2024

Name

[REDACTED]

Phone

[REDACTED]

Invoice # 2024- 048

Item #	Description	Qty	Unit price	Total price
12345-A	10R80 refresh Updated CDF drum rebestous frictions overhaul kit filter	1	\$2,500.00	\$2,500.00
12345-B				

\$0.00

\$0.00

Does not include-

\$2,500.00

Fluid, Electrical, Remove and replace and abuse

Core Deposit

Tax rate

5.00%

1 Year warranty

Sales tax

\$125.00

\$2,625.00

if core deposit required and returned returned upon core return



Tirecraft - Stony Plain
67 Boulder Boulevard
Stony Plain AB T7Z 1V6
Phone: 780-963-5540 Fax: 780-963-6396
e-mail: tstpierre@tirecraft.com

PAGE: 1
DATE: 24 Jun 13
GST REG#: 815717376RT0001
PST REG#:
INVOICE
IN151668 (History)

SOLD TO:

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

CONTACT:

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

HOME:
FAX:

COLOUR	VEHICLE DESCRIPTION		PLATE	UNIT#	TAG	ODO IN
	2017 Ford F150 1/2 Ton - Pickup SUPER CAB 3.5 L 213 CID V6 DOHC 24 Val		ABP 7173			223232
VIN	VEHICLE OPTIONS					ADV ODO AUTH
1FTFX1EGXHKD22064						KM 223232
TIME IN	PROMISED	TERMS	GST EXEMPT#		P.O.	ODO OUT
7:45 AM		Net 30 days			CSP7173	223232
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE	
1	AMVIC	AMVIC PRE-PURCHASE INSPECTION MC 24 Apr 29 ** CHECK OVER TRUCK - WANTS TO KNOW IF WORTH GETTING TRANSMISSION REPAIRED ** SCANNED CODES, P0218-00 TRANSMISSION FLUID TEMPERATURE SENSOR A OVER TEMPERATURE CONDITION. P0455-00 EVAP LARGE LEAK. P144C-00 EPEP PURGE FLOW PERFORMANCE DURING BOOST. TRANSMISSION FLUID IS BURNT. ** TRANSMISSION IS SLIPPING - ** TOWED HERE ** - SHOULD MOVE INTO BAY FOR INSPECTION **			152.10	
	LAB	TRANSMISSION ASSEMBLY Remove & Replace - V6,4WD w/Two Piece Driveshaft MC 24 May 13 Includes: Programming. / Sublet Labour --serial#: 7690 (PROGRAM TCM 17' F150)			1402.38	
1	SUBLET	Automatic Transmission Fluid 12.3 L - Trans Mfr CD 10R80 - ** 15 LITERS TO FILL SYSTEM WITH NEW COOLER - ALL LINES FLUSHED **		230.00	230.00	
15	XT12QULV	MECRON ULV (Ultra-Low Viscosity) Transmission Fluid		10.99	164.85	
13	ehco	ENVIROMENTAL FEE - OIL		.10	1.30	
	LAB	TRANSMISSION OIL COOLER Remove & Replace - All Applicable Models MC 24 Jun 06			243.27	
1	HL3Z7A095A	TRANSMISSION COOLER		123.23	123.23	
2	BG-79232	BG 75w80 Syncro Shift II Synthetic Gear 75W80		38.57	77.14	
2	EHCO	ENVIROMENTAL FEE - OIL		.20	.40	

BILL TO: Rebill TSP4041 Hennig Septic Service Ltd. ()

To help us serve you better we ask that you observe the following:

1. Title of goods remains with Tirecraft Stony Plain until fully paid for.
2. Proof of purchase must accompany all warranty claims.
3. Terms: Net 30 days.
4. Overdue amounts will be charged 2 % per month (24% per annum)
5. NSF cheques will be charged \$30.00 per cheque.

Signature x _____

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST/HST:	
PST:	
TOTAL:	Cont'd



Tirecraft - Stony Plain
67 Boulder Boulevard
Stony Plain AB T7Z 1V6
Phone: 780-963-5540 Fax: 780-963-6396
e-mail: tstpierre@tirecraft.com

PAGE: 2
DATE: 24 Jun 13
GST REG#: 815717376RT0001
PST REG#:
INVOICE
IN151668 (History)

SOLD TO:

[REDACTED]

CONTACT:

[REDACTED]

HOME:

FAX:

COLOUR		VEHICLE DESCRIPTION		PLATE	UNIT#	TAG	ODO IN
		2017 Ford F150 1/2 Ton - Pickup SUPER CAB 3.5 L 213 CID V6 DOHC 24 Val		40P7173			223232
VIN		VEHICLE OPTIONS				ADV	ODO AUTH
1FTFX1EGXHGD22064						KM	223232
TIME IN		PROMISED	TERMS	GST EXEMPT#		P.O.	ODO OUT
7:45 AM			Net 30 days			CSP7173	223232
QTY	ITEM	DESCRIPTION			WARR	NET	EXT.PRICE
1	PSR TI86080XL LAB	Full Inspection Repair Required -- Steering/Suspension: Tie Rod Ends / Ball Joints -- LEFT FRONT INNER TIE ROD HAS PLAY -- Fluids: Transmission -- BADLY BURNT -- Fluids: Axle/Differential -- REAR DIFFERENTIAL AND TRANSFER CASE FLUID DIRTY -- Electrical: Lights -- HI MOUNT BRAKE LIGHT, RIGHT LICENCE PLATE LIGHT OUT TI86080XL TIE ROD/Steering Tie Rod End TIE ROD &/OR END Remove & Replace - Inner,Left 24 May 16 Includes: R&I Outer Tie Rod End. Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed. NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some models. If removal of the Rack and Pinion Gear is necessary, use Steering					Recommended Recommended
1	a14sp	4 WHEEL ALIGNMENT SPECIAL 24 May 16 Subtotals Tax out 0.00 Tax in 0.00 (Declined: Tax out 379.11 Tax in 398.07)					Recommended
	DFSR	BG Synthetic Differential Service Labour - Rear 24 May 16					Recommended
3	BG-75132	Differential Gear Oil 2.6 L - Rear Axle BG Ultra-Guard w/Additive LS SAE 75W90 Synthetic Gear Oil 75W90					Recommended
3	EHCQ	ENVIROMENTAL FEE - OIL					Recommended
BILL TO: Rebill TSP4041 Hennig Septic Service Ltd. ()							

- To help us serve you better we ask that you observe the following:
1. Title of goods remains with Tirecraft Stony Plain until fully paid for.
 2. Proof of purchase must accompany all warranty claims.
 3. Terms: Net 30 days.
 4. Overdue amounts will be charged 2 % per month (24% per annum)
 5. NSF cheques will be charged \$30.00 per cheque.

Signature x _____

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST/HST:	
PST:	
TOTAL:	Cont'd



Tirecraft - Stony Plain
67 Boulder Boulevard
Stony Plain AB T7Z 1V6
Phone: 780-963-5540 Fax: 780-963-6396
e-mail: tstpierre@tirecraft.com

PAGE: 3
DATE: 24 Jun 13
GST REG#: 815717376RT0001
PST REG#:
INVOICE
IN151668 (History)

SOLD TO:

[REDACTED]

CONTACT:

[REDACTED]

HOME:
FAX :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
	2017 Ford F150 1/2 Ton - Pickup SUPER CAB 3.5 L 213 CID V6 DOHC 24 V	ABP 7173			223232
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1FTFX1EGXHGD22064				KM	223232
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
7:45 AM		Net 30 days		CSP7173	223232

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		Subtotals Tax out 0.00 Tax in 0.00 (Declined: Tax out 245.23 Tax in 257.49)			
		Suggested Preventive -- Fluids: Engine OK -- Steering/Suspension: Wheel Bearings -- NO PLAY DID NOT GO FOR ROADTEST -- Tires: Left Front (11 /32) -- HERCULES LT265/70R17 -- Brakes: Front -- 10MM WHEEL ON CHECK -- Brakes: Rear -- 8MM WHEEL ON CHECK -- Brakes: Hydraulic -- NO LEAKS			
		Subtotals Tax out 0.00 Tax in 0.00			
1	SS	Shop Supplies		78.94	78.94
	LAB	*CONFIRM IF ITS VALVE * P0455-00/P144C-00 CANISTER PURGE SOLENOID Remove & Replace - 3.5L Eng,Turbocharger 24 May 16 Includes: Component test.			Recommended
1	BWD CP847	Vapor Canister Purge Valve			Recommended
		Subtotals Tax out 78.94 Tax in 82.89 (Declined: Tax out 185.59 Tax in 194.87) Loyalty Plan Number: TOTAL DISCOUNT GIVEN---> 202.51 Payment Method: OnAccount=2597.30 Thank you for your business.			

BILL TO: Rebill TSP4041 Hennig Septic Service Ltd. ()

- To help us serve you better we ask that you observe the following:
1. Title of goods remains with Tirecraft Stony Plain until fully paid for.
 2. Proof of purchase must accompany all warranty claims.
 3. Terms: Net 30 days.
 4. Overdue amounts will be charged 2 % per month (24% per annum)
 5. NSF cheques will be charged \$30.00 per cheque.

Signature x _____

PARTS:	595.22
LABOUR:	1797.75
OTHER:	80.64
SUB-TOTAL:	2473.61
GST/HST:	123.69
PST:	N/C
TOTAL:	2597.30