



BURTON'S

Burton's AutoBody Ltd

12545 - 71 Street

Edmonton, AB T5B 1W9

Ph: 780-471-3085 Fax: 780-479-7416

1

November 12, 2024

CUSTOMER PAY

RE:

Owner: ~~CHARLENE DUFFY~~

Vehicle: 2024 N/A Hyundai Kona

Repair #: 17300

Claim #: N/A

Policy #: N/A

Attn:

Enclosed is the proper documentation on the repair work which we performed for the above listed vehicle.

The following is a breakdown of the billing and payments received:

Repair Order: \$7,953.69

Supplement: \$410.44

Total Amount: \$8,782.34

Deductible: \$0.00

Less Payments: \$0.00

Current Balance: \$8,782.34

Please review your records and issue payment for the current amount due.

Thank you for your prompt attention to this matter.

Sincerely,

**BURTON'S****Burton's AutoBody Ltd**

12545 - 71 Street
Edmonton, AB T5B 1W9
Ph: 780-471-3085 Fax: 780-479-7416

1

Invoice

RO #: 17300

Unit #:

Arrived: 9/11/2024

Ready:

Estimator: Leonard Forde**Customer Information**

Name: ~~XXXXXXXXXXXX~~
Address: N/A
EDMONTON AB N/A
Phone:

Vehicle Information

Vehicle: 2024 N/A Hyundai Kona
Style: 4 Door Utility
License: N/A
VIN: KM8HB3AB7RU150204
Mileage: N/A
Mileage Out:

Insurance Information

Ins Co: CUSTOMER PAY
Contact: ~~XXXXXXXXXXXX~~
Phone:
Claim #: N/A
Deduct: \$0.00

#	S# Operation	Description	Type	Price	Adj Price	T	Lbr	Addl	Dept	Paint	Addl
1	1 Remove/Replace	Hood Panel	NW	\$922.25	\$1,085.72		1.2		B		
2	Refinish	Hood Outside							R	2.6	
3	Refinish	Add For Hood Underside							R	1.3	
4	Repair								B		
5	Refinish								R		
6	Repair								B		
7	Refinish								R		
8	Remove/Install								B		
9	Remove/Install								B		
10	Remove/Install								B		
11	Remove/Install								B		
12	Refinish	R Roof Rail							R	1.6	
13		R Roof Rail					5.0		B		
14	Refinish	L Roof Rail							R	1.6	
15		L Roof Rail					6.0		B		
16	Repair								B		
17	Refinish								R		
18	Repair	L Frt Door Shell							B		
19	Refinish	L Frt Door Outside							R		
20	Remove/Install								B		
21	Remove/Install	L Frt Rear View Mirror							B		
22	Remove/Install								B		
23	Remove/Install	L Frt Otr Door Belt Moulding							B		
24	Remove/Install								B		
25	Remove/Install	L Frt Lwr Door Moulding							B		
26	Remove/Replace	L Frt Otr Door Belt Moulding	NW	\$136.21					B		
27	Remove/Install								B		
28	Remove/Install	L Frt Door Trim Panel							B		
29	Remove/Install								B		
30	Remove/Install	L Frt Otr Door Handle							B		
31	Repair								B		

**BURTON'S****Burton's AutoBody Ltd**12545 - 71 Street
Edmonton, AB T5B 1W9
Ph:780-471-3085 Fax: 780-479-7416**Invoice**

RO #:17300

Unit #:

Arrived: 9/11/2024

Ready:

Estimator: Leonard Forde**Customer Information**Name: [REDACTED]
Address: N/A
EDMONTON AB N/A
Phone:**Vehicle Information**Vehicle: 2024 N/A Hyundai Kona
Style: 4 Door Utility
License: N/A
VIN: KM8HB3AB7RU150204
Mileage: N/A
Mileage Out:**Insurance Information**Ins Co: CUSTOMER PAY [REDACTED]
Contact:
Phone:
Claim #: N/A
Deduct: \$0.00

32	Refinish						R	
33	Repair						B	
34	Refinish						R	
35	Remove/Install						B	
36	Remove/Install						B	
37	Remove/Install						B	
38	Remove/Install						B	
39	Remove/Install						B	
40	Remove/Install						B	
41	Remove/Install						B	
42			NW				B	
43	Remove/Replace	L Rear Otr Door Belt Moulding	NW	\$60.81		0.2	B	
44	Remove/Install						B	
45	Remove/Install	L Rear Door Trim Panel				0.4	B	
46	Remove/Install						B	
47	Remove/Install						B	
48	Remove/Replace	L Rear Door Outside Handle	NW	\$46.62		0.3	B	
49	Refinish	L Rear Otr Handle					R	0.5
50	1 Remove/Replace	Roof Panel	NW	\$1,223.00	\$1,439.14	16.0	B	
51	Refinish	Roof Panel Outside					R	3.0
52	Refinish	Roof Edge					R	0.5
53		Add To R&I/R&R Side Curtain Air Bags -M				1.6	M	
54	Repair						B	
55	Refinish						R	
56	Remove/Install						B	
57	Remove/Install						B	
58	Remove/Install						G	
59	Remove/Install						B	
60	Remove/Install						G	
61	Remove/Install						B	
62	Repair	Liftgate Shell				3.0	B	
63	Refinish	Liftgate Outside					R	2.2

**BURTON'S****Burton's AutoBody Ltd**

12545 - 71 Street
Edmonton, AB T5B 1W9
Ph:780-471-3085 Fax: 780-479-7416

1

Invoice

RO #:17300

Unit #:

Arrived: 9/11/2024

Ready:

Estimator: Leonard Forde**Customer Information**

Name: ~~XXXXXXXXXX~~
Address: N/A
EDMONTON AB N/A
Phone:

Vehicle Information

Vehicle: 2024 N/A Hyundai Kona
Style: 4 Door Utility
License: N/A
VIN: KM8HB3AB7RU150204
Mileage: N/A
Mileage Out:

Insurance Information

Ins Co: CUSTOMER PAY
Contact:
Phone:
Claim #: N/A
Deduct: \$0.00

64	Remove/Install	Liftgate Spoiler				0.6	B
65	Remove/Install	Upr Liftgate Trim Panel				0.2	B
66	Remove/Install	Liftgate Garnish				0.3	B
67	Remove/Install	Lwr Liftgate Trim Panel				0.4	B
68	1 Remove/Replace	High Mount Stop Lamp Assembly	NW	\$180.00	\$210.83	0.2	B
69			NW				B
70			NW				B
71	Remove/Install						B
72	Remove/Install						B
73	Remove/Install						B
74		Paint/Materials	PM	\$1,200.00	✓		
75		Shop Materials	SS	\$500.00	✓		
76	Addl Labor	Clear Coat				R	2.5

Totals:	RO:	Supp:	Total:
Final (Combined) Totals			
Parts - New	\$2,568.89	\$410.44	\$2,979.33
PARTS TOTAL	\$2,568.89	\$410.44	\$2,979.33
Body Labor	\$2,366.00		\$2,366.00
Refinish Labor	\$1,106.00		\$1,106.00
Mechanical Labor	\$212.80		\$212.80
LABOR TOTAL	\$3,684.80		\$3,684.80
Shop Supplies	\$500.00		\$500.00
Paint Materials	\$1,200.00		\$1,200.00
Sub Total	\$7,953.69	\$410.44	\$8,364.13
GST (5.000%)			\$418.21
GRAND TOTAL			\$8,782.34



Burton's AutoBody Ltd

12545 - 71 Street
Edmonton, AB T5B 1W9
Ph:780-471-3085 Fax: 780-479-7416

BURTON'S

Invoice

RO #:17300

Unit #:

Arrived: 9/11/2024

Ready:

Estimator: Leonard Forde

Customer Information

Name: [REDACTED]
Address: N/A
EDMONTON AB N/A
Phone:

Vehicle Information

Vehicle: 2024 N/A Hyundai Kona
Style: 4 Door Utility
License: N/A
VIN: KM8HB3AB7RU150204
Mileage: N/A
Mileage Out:

Insurance Information

Ins Co: CUSTOMER PAY
Contact:
Phone:
Claim #: N/A
Deduct: \$0.00

GST # 863694048RT0001

Thank you for bringing your vehicle to our shop for repairs.
We appreciate your business.