



Unit Number: 232

Make / Model: Lode King Super-B, Hi-boy (Lead)

Year: 2006

Color:

VIN: 2LDPF323X69043913

Plate Number: 5RS903

Unit Number: 233

Make / Model: Lode King Super-B, Hi-boy (Pup)

Year: 2006

VIN: 2LDPF282069043914

Plate Number: 5RS904

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Units 232 & 233 - Greased Units	Roger guerzon	DT 22342	3/Jan/20	
Unit 232 - Repaired wiring to lights front & rear	Justin Maier	Repair# 00361	29/Jan/20	Y
Unit 232 - Seal	NAPA	011-133607	7/Jan/21	



Unit Number: **232**

Make / Model: **Lode King Super-B, Hi-boy (Lead)**

VIN: **2LDPF323X69043913**

Year: **2006**

Plate Number: **5RS903**

Color:

Unit Number: **233**

Make / Model: **Lode King Super-B, Hi-boy (Pup)**

VIN: **2LDPF282069043914**

Year: **2006**

Plate Number: **5RS904**

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Unit 232 - Replaced pig tail for marker light on drivers side rear of deck	Justin Maier	Repair #: 00374	13/Feb/20	



Unit Number: 232

Make / Model: Lode King Super-B, Hi-boy (Lead)

Year: 2006

Color:

VIN: 2LDPF323X69043913

Plate Number: 5RS903

Unit Number: 233

Make / Model: Lode King Super-B, Hi-boy (Pup)

Year: 2006

VIN: 2LDPF282069043914

Plate Number: 5RS904

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Unit 232 - Repaired passenger side front lights on unit	Justin Maier	Repair #: 00338	24/Mar/20	
Unit 232 - Wash unit	Dave Merko	D7110	18/Mar/24	
Fix ABS Wires, install new dustsheild	RBOL - Dan Howey	D7073	15/May/24	



Unit Number: 232

Make / Model: Lode King Super-B, Hi-boy (Lead)

Year: 2006

Color:

VIN: 2LDPF323X69043913

Plate Number: 5RS903

Unit Number: 233

Make / Model: Lode King Super-B, Hi-boy (Pup)

Year: 2006

VIN: 2LDPF282069043914

Plate Number: 5RS904

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Fix flat	Dan Anthony	D2488	25/Jul/21	Unit 232
Purchase Brake drums,brake shoes & hdwr kits	NAPA	011-214299	17/Jul/22	Unit 232
Finish installing air bag on rear axle drivers side,change marker light	RBOL - Dan Howey	D6172	20/Jul/22	Unit 233
Replace brake drums and brake shoes	RBOL - Dan Howey	D6171	17/Jul/22	Unit 232
Purchase Air spring rolling lobe and ftgs	NAPA	011-214714	19/Jul/22	Unit 233
Truck tire change over	KALTIRE	604074172	29/Jul/22	Unit 233



Unit Number: **232**

Make / Model: **Lode King Super-B, Hi-boy (Lead)**

Year: **2006**

Color:

VIN: **2LDPF323X69043913**

Plate Number: **5RS903**

Unit Number: **233**

Make / Model: **Lode King Super-B, Hi-boy (Pup)**

Year: **2006**

VIN: **2LDPF282069043914**

Plate Number: **5RS904**

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Unit 232 - Grease Unit, check lights, check brakes - rear Axle on lead needs adjustment- Done, side boxes ok, Fixed Dunage racks on trailers,	Randy Stasynec	Repair #: 00077	13/Aug/19	
Greased Unit	Justin Maier	23640	25/Aug/20	
Replace DS rear marker light	RBOL - D Howey	1769	18/Aug/22	Unit 232
Replace rear marker light & license plate light	RBOL - D Howey	1769	18/Aug/22	Unit 233
Replace pig tail and light on rear driver console	RBOL - D Howey	1771	27/Aug/22	Unit 232



Unit Number: **232**

Make / Model: **Lode King Super-B, Hi-boy (Lead)**

Year: **2006**

Color:

VIN: **2LDPF323X69043913**

Plate Number: **5RS903**

Unit Number: **233**

Make / Model: **Lode King Super-B, Hi-boy (Pup)**

Year: **2006**

VIN: **2LDPF282069043914**

Plate Number: **5RS904**

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Replace broken and damaged glad hands, tie up hanging wires	RBOL - D Anthony	1793	10/Sep/22	Unit 232,233
Replace RH brake shoes, drum, slack adjuster, inner cam-tube bushing and backing plate	Edge HD	5096	9/Sep/22	Unit 232
Purchase Air spring Rolling Lobe	NAPA	011-222282	7/Sep/22	Unit 232/233
Purchase Cplgs & Bshings	NAPA	011-221809	1/Sep/22	Unit 233
Replace Airbag	RBOL - D Howey	1773	1/Sep/22	Unit 233
Purchase gladhands	NAPA	011-222217	6/Sep/22	Unit 233
Grease lead & pup	Edge HD	5132	29/Sep/22	Unit 232
Purchase crank handle	NAPA	011-225610	27/Sep/22	Unit 232
Grease Units 233 & 232	RBOL - D Merko	D8567	17/Sep/24	



Unit Number: 232

Make / Model: Lode King Super-B, Hi-boy (Lead)

VIN: 2LDPF323X69043913

Year: 2006

Plate Number: 5RS903

Color:

Unit Number: 233

Make / Model: Lode King Super-B, Hi-boy (Pup)

VIN: 2LDPF282069043914

Year: 2006

Plate Number: 5RS904

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Purchase Hub Caps	NAPA	011-173719	26/Oct/21	
Purchase gear oil	NAPA	011-173714	26/Oct/21	



Unit Number: 232

Make / Model: Lode King Super-B, Hi-boy (Lead)

Year: 2006

Color:

VIN: 2LDPF323X69043913

Plate Number: 5RS903

Unit Number: 233

Make / Model: Lode King Super-B, Hi-boy (Pup)

Year: 2006

VIN: 2LDPF282069043914

Plate Number: 5RS904

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Replaced outer mount hub, computer diagnostic, installed new bearing hub, filled hub with customer supplied oil	Double R Heavy Duty	5266	8/Nov/19	Unit 233
Repair air leak	RBOL - D Merko	D8740	4/Dec/24	Unit 232