

UNIT: 2-44
YEAR: 2013
MAKE: WESTERN STAR
SERIAL: 5KJ/AED10EPFL8929

DATE **REPAIRS/SERVICES COMPLETED**

16-Apr-2013	Rigg Up Truck
26-Apr-2013	Install Air Pot Plugs
02-May-2013	Refer To W/o 3250213 Radio Install
24-May-2013	Take Unit To Dunlop For Error Codes
18-Jun-2013	Install Quick Drain Valve
18-Jun-2013	Work Order For Interval Service
25-Jun-2013	Check And Grease Unit
17-Jul-2013	Cab - Install Windshield
29-Jul-2013	Work Order For Interval Service
12-Sep-2013	Work Order For Interval Service
20-Sep-2013	Cab - Repair Windshield
03-Oct-2013	Windshield Repair
25-Oct-2013	Truck Tire Change Over
05-Nov-2013	Work Order For Interval Service
12-Nov-2013	Supply Locking Fuel Caps
15-May-2014	Work Order For Interval Service
28-May-2014	Check Over And Grease Unit
30-May-2014	Replace Tank Bushings
19-Jun-2014	Check For Plugged Fuel Lines
02-Jul-2014	Install Windshield
02-Jul-2014	Replace Fuel Line And Fittings
07-Jul-2014	Check Over And Grease Unit
	Work Order For Interval Service
14-Jul-2014	Check For Rear Wheel Oil Leak
25-Jul-2014	Install Fuel Level Sender
	Work Order For Certification

15-Aug-2014	Work Order For Interval Service
27-Aug-2014	Check Over And Grease Unit
09-Sep-2014	Electrical System - Replace Work Lights
26-Sep-2014	Work Order For Interval Service
01-Oct-2014	Replace Batteries
	Service Trip To Check Batteries Poor Start
01-Oct-2014	Check Over And Grease Unit
20-Oct-2014	Replace Hood Bushings
23-Oct-2014	Check Over And Grease Unit
28-Oct-2014	Balance And Rotate Tires
28-Oct-2014	Adjust Hood
	Replace Rad Cap
13-Nov-2014	Work Order For Interval Service
26-Nov-2014	Check For Coolant Leak
	Tighten Clamps
24-Feb-2015	Install Remote Head Kit
18-Mar-2015	Check Over Unit
	Replace Air Valve
	Replace Dash Bulbs
25-Mar-2015	Turn Both Fuel Tanks
01-Apr-2015	Flat Tire Repair
22-Apr-2015	Work Order For Interval Service
05-May-2015	Tire Change Over
06-May-2015	Replace Wiper Blades
19-May-2015	Check Tail Lights
27-May-2015	Cooling System - Check Check For Leaks & Debris
05-Jun-2015	Replace Damaged Windshield
15-Jun-2015	Preform Pmb Inspection
	Work Order For Interval Service
07-Jul-2015	Flat Tire Repair And Service Trip
29-Jul-2015	Do A Valve Set
	Work Order For Interval Service
29-Jul-2015	Work Order For Certification

28-Sep-2015	Work Order For Interval Service
14-Oct-2015	Repair Inoperative A/c Blue Rocker Switch, burnt Out
06-Nov-2015	Coolant Leaking From Middle To Lower On Passenger Side Of Radiator Loosen Fuel Tank And Re Position For Proper Function, Tanks Have Turned Oil Leaking From Oil Pan Passenger Side Window Cracked, Replace Via Toms Glass, Booked For Monday Nov 2nd Remove And Replace Drivers Side Seat With New Remove And Replace Main Engine Fan Belt Repair Broken Work Light
	Work Order For Interval Service
04-Jan-2016	Replace Worn Out Drivers Side Seat Cushion.
11-Mar-2016	Replace Broken Toggle Switch Guard.
17-Mar-2016	Work Order For Interval Service
22-Mar-2016	Check Over And Grease Unit
22-Apr-2016	Change Passenger Side Windshield Wiper Blade, Old One Worn.
26-Apr-2016	Replace Washer Pump And Nozzles
26-Apr-2016	Replace Drivers Side Marker Light
26-Apr-2016	Repair Unit For No Start
21-Jul-2016	Check Over And Grease Unit Work Order For Interval Service
29-Jul-2016	Adjust Clutch Replace Burnt Out Head Lamp Replace Leaking Wheel Seal, Drum And Shoes. Work Order For Interval Service
29-Aug-2016	Remove And Replace Def Pump
29-Aug-2016	Supply Tow Hook To Brent
09-Sep-2016	Work Order For Interval Service
21-Sep-2016	Replace Broken Fan Belt On Unit
01-Nov-2016	Remove And Install New Drivers Side Windshield
23-Nov-2016	Test Batteries. Batteries Load Tested And Failed. Batteries Replaced.
17-Feb-2017	Work Order For Interval Service
13-Jul-2017	Inspection - CVIP Inspection - Pmc

13-Jul-2017	Work Order For Interval Service
11-Aug-2017	Brake Linnings And Drum Found To Be Incorrect. Correct Ones Installed Repair Wheel Seal Leaking On Rear Axle
30-Aug-2017	At Approx 3712 Hrs The Mcm Was Replaced And Was Zero Houred. This Was Carried Out On 26 April 2016.
28-Nov-2017	R&r Water Pump.(leaking)
12-Mar-2018	Cab Roof Marker Light Broken. R&r Roof Marker Light.
14-May-2018	Wheel Seal Leaking D/s Front Drive. Replaced Brakes And Cleaned Drum.Replenished Oil.
24-May-2018	Work Order For Interval Service
01-Jun-2018	Flat Repair And Rotation
04-Jun-2018	Flat Repair On Unit
20-Jul-2018	Flat Repair
31-Jul-2018	Inspection - CVIP Inspection - Pmc
27-Sep-2018	1. Inspect Leveling Valve.2. Windshields Damaged.3. Tarp Switch Faulty.4. Check Clutch Freeplay And Operation.5. Install A Wabas
27-Sep-2018	Check And Repair Coolant Leak On Unit Work Order For Interval Service
09-Oct-2018	Diagnose Active Cel, Replace Inlet And Outlet Nox Sensors.
26-Oct-2018	Changeover Medium Truck
26-Oct-2018	Replaced Trailer And Tractor Plugs For Gate And Tarp. Installed A New Ground Cable.
04-Apr-2019	Remove Rad So It Can Be Cleaned And Resealed. 2. Reinstalled Rad And Filled.3. Tested For Leaks. Ok
10-Jul-2019	Work Order For Interval Service
09-Sep-2019	Inspection - CVIP Inspection - Pmc
12-Sep-2019	1.r&r Brakes On Rear Axle.2.r&r Wheel Seal On D/s Rear Drive Axle. P/s Highbeam Nlight Replaced
22-Oct-2019	1.drivers Side Windshield Replaced. 2. Shifter Repositioned. 3. Clutch Adjusted. 4. Mirror Lights Repaired.
18-Nov-2019	1. Coolant Leak.
19-Dec-2019	Replace Air Line Clamp
14-Apr-2020	P/s Windshield Cracked
04-May-2020	1. Cooloant Leak. Rad Removed And Sent Out For Repairs.

14-May-2020	Engine Surging.
14-May-2020	P/s Frt Wheel Hub Leaking.
14-May-2020	Work Order For Interval Service
14-May-2020	R&r Frt Wheel Hub Oil Reservoir Plugs (red).Air Leak At Trailer Push Pull Button.leak Is Minor And Doesnt Fail Cvip Standard.
11-Jun-2020	Diagnose And Repair Inoperative Kaltronics
16-Jun-2020	Missed Parts On Radiator Repair, Bill Came Late.
23-Jun-2020	Windshield Replacement
20-Jul-2020	Work Order For Internal Service 4501 Hrs
22-Jul-2020	CVIP INSPECTION
28-Jul-2020	Install New Gravel Program.
05-Aug-2020	Flat Repair
	Hvac Rigid Pipe Leaking
	Fan Pulley Idlers/ Tensioner Squeaking.
17-Aug-2020	Work Order For Interval Service
17-Aug-2020	Remove And Replace Horn Brush, Contacts Intermittently Resulting In Horn Working Sometimes.
19-Aug-2020	R&r Batterys.
19-Aug-2020	Replace Windshield Glass
20-Aug-2020	Tire Change Over
14-Sep-2020	Rad Leak
17-Sep-2020	Supply Hood Spring To Darry For Install
13-Oct-2020	Replace Hydraulic Steering Hoses With New.
27-Oct-2020	Work Order For Internal Service.
12-Nov-2020	Flat Repair
19-Apr-2021	Work Order For Internal Service
	Xtra Filters Billed As Driver Had Issues Installing
21-Apr-2021	Fender Replacement
07-May-2021	Work Order For Internal Service.
05-Jul-2021	Work Order For Internal Service.
08-Jul-2021	Tire Rotation
08-Jul-2021	Flat Repair
24-Aug-2021	Inspection - CVIP
	Inspection - Pmc
21-Oct-2021	Remove And Replace Shifter Lever

07-Feb-2022	Service Required
06-Jun-2022	Rad Leak
07-Jul-2022	Work Order For Interval Service
14-Jul-2022	Replace Def Header
23-Sep-2022	Replace Def Gauge
23-Sep-2022	Flat Repair
17-Feb-2023	Inspection - CVIP
	Inspection - Pmc
	D/s Mirrors Replaced.4 Air Bags Replaced
03-Mar-2023	No Clutch Brake.
	Replace Batteries
19-Apr-2023	Windshield Replacement
24-Jul-2023	Inspection - Perform CVIP
	Front Drive Right Wheel Seal
	Reverse Lights Not Working
	Tires Worn Beyond Spec
21-Aug-2023	Mil Light On
	Poor Gravel Radio Reception
14-Sep-2023	Repair For Shifter Location
11-Oct-2023	Driver Air Ride Seat Not Working
19-Oct-2023	Duplicate Workorder
31-Oct-2023	Service 250hrs
04-Dec-2023	Abs Light On
	Coolant Leak
	Noisy Bearing Front Of Engine
	Replace Glazed Fan Belts
	Right Rear Drive Wheel Seal
	Tighten Rad Tank Bolts
18-Apr-2024	Repair Air Leak At Firewall
08-May-2024	250 Hour Service
	Replace Headlight
21-Jun-2024	Check Engine Lights On
	Repair Scr Codes

04-Jul-2024	Replace Nox Sensors Replace Def Injector Inspect For Def Build Up In Exhaust Replace Aftertreatment Harness Check Engine Lights On Scr Conversion Low Def Quality Codes Diagnose Codes Abs Lights On
22-Jul-2024	Remove And Replace Speed Sensors Rear Axle
22-Jul-2024	Inspection CVIP Replace Steer Axle Tires Repair Leaking Wheel Seal Repair Cab Marker Lights Repair Egr Linkage Replace Bent Tie Rod Tube Set Toe In
30-Jul-2024	Check Engine Lights On Perform Service Regen
19-Aug-2024	Engine 250 Hr Service
09-Sep-2024	Repair Missing Mudflaps
25-Sep-2024	Remove Titan Remove Radios
	Get Unit Ready For Auction