

So-Lo Auto Repair Ltd.
469 B SOUTH AVE
SPRUCE GROVE, AB. T7X 3B5
(780) 962-4478
Writer: T.J. MCKIE



NAPA AUTOPRO

INVOICE # 19105

so-loauto@hotmail.com
so-loauto.ca

| | | | |
|-------------|--------------------|-------------------|--------------------|
| YEAR: | 2014 | TRANS/DRIVE: | 6 SPD BOTH AUTOMA/ |
| MAKE/MODEL: | FORD FLEX SEL | LICENSE/PROVINCE: | BYJ 5462/AB |
| VIN: | 2fmhk6c80ebd30093 | KM IN/KM OUT: | 311436/311436 |
| ENGINE: | 3.5L V6 F DOHC 24V | | |

In: 11/21/2024 Out: 11/25/2024

VEHICLE ISSUE #1: INTERMITTENT HEAT LOSS. CUSTOMER SUSPECTS THERMOSTAT. BLOCKED HEATER CORE.

ADV NOTES: WATER PUMP, TIMING CHAIN REPLACED.
INTAKE GASKET(S), VALVE COVER GASKET(S), THERMOSTAT, SERPENTINE BELT, SPARK PLUGS AND IGNITION COIL
BOOTS REPLACED.
OIL CHANGE. 5.7L 5W20 SYNTHETIC W/FILTER
COOLANT FILLED (FORD ORANGE)
AC RECHARGE R134 @ 2.31LBS

HARMONIC BALANCER BUSHING WORN.

| | | | | |
|--------------------|--|----------------|------------|-------|
| PART: 90738SWP | NAPA TIMING PRODUCTS ENGINE TIMING SET | 1 @ \$1,459.22 | \$1,459.22 | NEW |
| PART: AT4Z 6256 B | SPROCKET CAMSHAFT | 2 @ \$435.47 | \$870.94 | NEW |
| PART: AT4Z 6C525 D | CAM | 2 @ \$282.52 | \$565.04 | NEW |
| PART: AT4Z 6279 D | BOLT | 2 @ \$11.56 | \$23.12 | NEW |
| PART: AT4Z 6279 E | BOLT | 2 @ \$12.25 | \$24.50 | NEW |
| PART: AT4Z 6M280 A | SOLENOID - ENGINE VA | 2 @ \$108.18 | \$216.36 | NEW |
| PART: AT4Z 6M280 B | SOLENOID - ENGINE -VA | 2 @ \$107.15 | \$214.30 | NEW |
| PART: BR3Z 6584 B | GASKET | 1 @ \$44.18 | \$44.18 | NEW |
| PART: BR3Z 6584 C | GASKET | 1 @ \$44.94 | \$44.94 | NEW |
| PART: AT4Z 9H486 A | GASKET | 1 @ \$48.39 | \$48.39 | NEW |
| PART: 354-180 | THERMOSTAT | 1 @ \$23.92 | \$23.92 | NEW |
| PART: 89930501 | DORMAN COIL BOOT | 1 @ \$33.40 | \$33.40 | NEW |
| PART: 35489 | FEL-PRO GASKETS ENGINE COOLANT THERMOSTAT O-RING | 1 @ \$20.59 | \$20.59 | NEW |
| PART: 17 | ACDELCO SPARK PLUG | 6 @ \$16.19 | \$97.14 | NEW |
| PART: 27502MP | NAPA PROFORMER ENGINE OIL FILTER | 1 @ \$6.70 | \$6.70 | NEW |
| PART: MAG65445 | 5W20 FULL SYNTHETIC ENGINE OIL | 5.7 @ \$16.10 | \$91.77 | NEW |
| PART: 49604OGM | RECOCHEM ENGINE COOLANT / ANTIFREEZE | 1 @ \$26.55 | \$26.55 | NEW |
| LABOR: MCFARLAN | TIMING CHAIN, R&R, FLEX, W/O TURBO, BOTH | 13 @ \$155.00 | \$2,015.00 | LABOR |

Recommended Repairs:

| | |
|------------|------------|
| Labor/Jobs | \$2,325.00 |
| Parts | \$4,731.22 |
| Sublet | \$0.00 |
| Total Fees | \$232.50 |
| Subtotal | \$7,288.72 |
| GST @ 5% | \$310.91 |
| Total | \$7,599.63 |
| Payments | \$0.00 |
| Balance | \$7,599.63 |

YOU'RE COVERED BY OUR 24 MONTH / 40,000KM LIMITED WARRANTY! We stand behind our parts and our workmanship! For eligible warranty service, you must have a copy of your original service invoice. If you are less than 40 kilometers away - call us! If you are more than 40 kilometers away, call our Warranty Administrator at 1-866-GET-NAPA, (1-866-438-6272) between the hours 8:00 am to 8:00 pm Monday through Friday (E.T.) and 8:00 am to 5:00 pm Saturdays, excluding holidays. They will direct you to the nearest participating NAPA Dealer (or alternate) location. For additional details, please see www.napaautopro.com for complete terms and conditions or ask our Service Advisor today! No warranty on customer supplied parts, new and used. No refund if concerns are addressed by a third party PRIOR to inspection/approval by So-Lo Auto Repair or affiliated NAPA Autopro location. If your service include

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 11/25/2024

So-Lo Auto Repair Ltd.
469 B SOUTH AVE
SPRUCE GROVE, AB. T7X 3B5
(780) 962-4478
Writer: T.J. MCKIE



INVOICE # 19105

so-loauto@hotmail.com
so-loauto.ca

| | | | |
|-------------|--------------------|-------------------|--------------------|
| YEAR: | 2014 | TRANS/DRIVE: | 6 SPD BOTH AUTOMA/ |
| MAKE/MODEL: | FORD FLEX SEL | LICENSE/PROVINCE: | BYJ 5462/AB |
| VIN: | 2fmhk6c80ebd30093 | KM IN/KM OUT: | 311436/311436 |
| ENGINE: | 3.5L V6 F DOHC 24V | | |

Total for "INTERMITTENT HEAT LOSS. CUSTOMER SUSPECTS THERMOSTAT. BLOCKED HEATER CORE.": \$5,826.06

VEHICLE ISSUE #2: INSPECT FRONT END

ADV NOTES: FRONT LEFT OUTER TIE ROD FOUND MAJOR PLAY.
FRONT RIGHT INNER TIE ROD FOUND PLAY.
SUSPECT FRONT STRUTS TOP MOUNT BEARINGS ARE STICKING.
THUMPING NOISE AS DESCRIBED IS COMING FROM FRONT END ISSUES.

REPLACED BOTH SIDES LOWER CONTROL ARMS.

RECOMMEND REPLACE BOTH SIDES INNER AND OUTER TIE RODS TO SAVE LABOR.
RECOMMEND REPLACE BOTH FRONT QUICK STRUTS W/LINKS TO PREVENT FUTURE SPRINGS COLLAPSING.

| | | | | |
|-----------------|--|--------------|--------------------------------|-------|
| PART: 2608421 | NAPA PREMIUM CONTROL ARMS SUSPENSION CONTROL ARM AND BALL JOINT ASSEMBLY | 1 @ \$460.08 | \$460.08 | NEW |
| PART: 2608422 | NAPA PREMIUM CONTROL ARMS SUSPENSION CONTROL ARM AND BALL JOINT ASSEMBLY | 1 @ \$460.08 | \$460.08 | NEW |
| LABOR: MCFARLAN | CHECK FRONT END, BALL JOINTS? | 1 @ \$155.00 | (Discount: \$155.00) \$0.00 | LABOR |
| LABOR: MCFARLAN | LOWER CONTROL ARM, R&R, FLEX, BOTH SIDES | 2 @ \$155.00 | \$310.00 | LABOR |

Total for "INSPECT FRONT END": \$1,230.16

MECHANICAL MATERIALS AND ENVIRONMENTAL DISPOSALS : \$232.50

Recommended Repairs:

YOU'RE COVERED BY OUR 24 MONTH / 40,000KM LIMITED WARRANTY! We stand behind our parts and our workmanship! For eligible warranty service, you must have a copy of your original service invoice. If you are less than 40 kilometers away - call us! If you are more than 40 kilometers away, call our Warranty Administrator at 1-866-GET-NAPA, (1-866-438-6272) between the hours 8:00 am to 8:00 pm Monday through Friday (E.T.) and 8:00 am to 5:00 pm Saturdays, excluding holidays. They will direct you to the nearest participating NAPA Dealer (or alternate) location. For additional details, please see www.napaautopro.com for complete terms and conditions or ask our Service Advisor today! No warranty on customer supplied parts, new and used. No refund if concerns are addressed by a third party PRIOR to inspection/approval by So-Lo Auto Repair or affiliated NAPA Autopro location. If your service include

| | |
|------------|------------|
| Labor/Jobs | \$2,325.00 |
| Parts | \$4,731.22 |
| Sublet | \$0.00 |
| Total Fees | \$232.50 |
| Subtotal | \$7,288.72 |
| GST @ 5% | \$310.91 |
| Total | \$7,599.63 |
| Payments | \$0.00 |
| Balance | \$7,599.63 |

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 11/25/2024