



CALGARY

9115 - 52 Street SE, Calgary, Alberta T2C 2R4 Phone: (403) 720-3400 Fax: (403) 720-3409

RED DEER

7690 Edgar Industrial Ct, Red Deer, Alberta T4P 4E2 Phone: (403) 314-1919 Fax: (403) 314-2203

Sold To: TRICAN WELL SERVICE LTD. E00710 TRICAN PARTNERSHIP

Ship To: TRICAN WELL SERVICE LTD.
TRICAN PARTNERSHIP

CUSTOMER INVOICE
Invoice Number

#2900, 645 - 7 AVENUE SW CALGARY, AB T2P 4G8 403 266-0202 #2900, 645 - 7 AVENUE SW CALGARY, AB T2P 4G8 R29953

Date: 10-08-20

403 200 0202				Page 1 of 2			
Year	Ma	ike / Model	VIN	License	Mileage	Unit/Stock	
2013	KENV	VORTH / T800	1XKDD40X0DJ957761	BGH-5389	506322	610058	
Delivery Mileage	Delivery Date	Engine N	lodel / Serial #	Tra	ansmission Model/Seria	1#	
05-03-12 ISX-15 /		/ 79551646		1			

Engine Hours	Reefer Hours Stand	by Hours P.O. Number	Open Date / Time	Complete	Service Writer
	1856.0	720084	10-05-20 / 12:25PM	10-07-20	ES*ES
Memo					

Tax ID Date:

Tax ID:

1	PERFORM EXPRESS ASSESSMENT
	BEFORE:AFTER:
	THERE OF A LINE TO
	INSPECT & ADVISE FOR:
	AIR COMPRESSOR WILL NOT BUILD AIR
	PERFORM EXPRESS ASSESSMENT
	BEFORE:AFTER:
	TNCDECT 0 ADVITCE FOR.

INSPECT & ADVISE FOR:

CAUSE:

INTERNAL COMPRESSOR FAULT

CORRECTION:

CONCERNS OF AIR COMPRESSOR NOT BUILDING AIR AND ALSO ENGINE TICK RAN UNIT AT 1500RPM. UNIT SEEMED TO BUILD AIR NORMALLY TO 100PSI. LET UNIT IDLE AND AIR PRESSURE CONTINUED TO RISE UNTIL COMPRESOOR UNLOADED. FANNED BRAKES TO REDUCE TANK PRESSURE AND LET UNIT IDLE. AIR PRESSURE BUILT 10PSI HIGHER ONLY AND TOOK AN EXTENDED TIME TO BUILD. LET UNIT IDLE FOR SEVERAL MORE MINUTES. PRESSURE BUILT SLOWLY TO 110 PSI AND SEEMED TO STOP. INSTALLED A GAUGE AND CONFIRMED UNLOADER PRESSURE BUILT QUICKLY AND EXHAUSTED QUICKLY WHEN UNIT WAS BUILDING PROPER PRESSURES. ALSO NOTED ENGINE TICK NOISE GOT PROGRESSIVLY LOUDER AS TANK PRESSURE INCREASED AND TICKING QUIT WHEN COMPRESSOR UNLOADED. SUSPECT INTERNAL FAILURE OF COMPRESSOR CAUSING SLOW BUILD TIME AND TICKING NOISE.

LOOSENED RESIVOIR BRACKET BOLTS. DISCONNECTED AIR AND COOLANT LINES FROM COMPRESSOR. REMOVED COMPRESSOR FROM ENGINE. CLEANED GASKET SURFACES ON ENGINE AND POWER STEERING PUMP. MARKED FITTING ORIENTATION ON NEW AND OLD COMPRESSOR. SWAPPED FITTINGS TO NEW COMPRESSOR USING NEW O-RINGS. MASKED AND PAINTED NEW COMPRESSOR. INSTALLED COMPRESSOR TO ENGINE AND INSTALLED ALL REMOVED LINES. INSTALLED POWER STEERING PUMP WITH NEW GASKET AND INSTALLED ALL REMOVED BRACKETS AND SUPPORT RODS.

TOTAL LABOR TOTAL PARTS TOTAL FREIGHT 517.50 1,895.58

25.00

Qty Part Number

Description

List

Unit Extended

R29953

Date: 10-08-20 R29955

						rage 2 01 2
Year	Ma	ke / Model	VIN	License	Mileage	Unit/Stock
2013	KENW	/ORTH / T800	1XKDD40X0DJ957761	BGH-5389	506322	610058
Delivery Mileage	Delivery Date	Engine N	lodel / Serial #	Ti	ransmission Model/Ser	ial#
	05-03-12	ISX-15	/ 79551646		1	

Complete Service Wr
10-07-20 ES*ES

	Tax ID	Date: Tax II	D:	
2 3103015 1 3685614 1 4988280 1 3690864RX 2 3102109 1 FREIGHT	GROMMET, GASKET,AC GASKET COMPRESSO SEAL,O RI FREIGHT	8.10 23.13 6.39 2,618.99 11.00 50.00	1,854.78	
G.S.T REG. NO. 84800	 02507RT0001	5 % OF	2,480.40 =	124.02
LABOR 51	17.50			
PARTS 1,89	95.58			
SUBLET	0.00			
SUPPLIES	12.32			
FREIGHT	25.00			
OTHER CHGS	0.00			
		SUBTOTAL		2,480.40
		G.S.T. 8480	02507RT000	1 124.02
		TOTAL		2,604.42

I acknowledge as an owner or representative of the above company and/or individual, the indebtedness for any and all requested repairs, diagnostics, and declined warranty; and understand and grant that a Garage Keeper's lien will be filed to secure the amount of these and all possible warranty repairs thereto by RIAMES MANAGEMENT GROUP LTD. I hereby acknowledge my indebtedness in the amount of the balance of this invoice either by purchase order, signature, email, and/or phone confirmation. I authorize RIAMES MANAGEMENT GROUP LTD. to collect, use and disclose the personal and business information that I have provided for the purpose of providing goods and services as requested, to better understand needs and preferences, to establish and maintain responsible commercial relations, and to provide ongoing service(s). It is also understood that all warranty or policy claims are submitted on behalf of the customer pending vendor inspection and approval. It cannot be assumed that there is warranty and responsibility for any and all debt of the repair(s) is assumed by the customer in full until approval is granted. RIAMES MANAGEMENT GROUP LTD. will issue a credit to you or your account for the amounts paid by the vendor when and if a warranty or policy claim is approved. Only repairs performed by RIAMES MANAGEMENT GROUP LTD. at an authorized facility of RIAMES MANAGEMENT GROUP LTD. Will have a 90 day workmanship guarantee and all claims made can only be honored at these facilities. If wheels are removed for any reason, it is the customer's responsibility to have them re-torqued at 100 kms. RIAMES MANAGEMENT GROUP LTD. Will not be liable for loose wheels. TERMS: The full amount of this invoice is payable 30 days following purchases of products or services. SERVICE CHARGES: 2% per month or 24% per annum on overdue accounts. A \$50.00 service charge will apply to all NSF cheques.

CUSTOMER: X		DATE
•	GST#: 848002507 RT0001	