



Truck - Trailer
Parts and Service
www.fleetbrake.com

FLEET BRAKE PARTS & SERVICE LT

158 QUEENS DRIVE
RED DEER AB T4P 0R4
403-343-8771

INVOICE DATE	
09/25/2020 01:15PM	
INVOICE NO.	PAGE
110006906	1
CUSTOMER NO.	BRANCH
64131	* 11*

SOLD TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

SHIP TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

CUSTOMER P.O.	REFERENCE NO	GST# R101819472	
719476	015910	(403) 346-4667	48 053/948
TERMS: (60) N60		PRICE/PER	EXTENSION
FINISH TIME			
AFTER HOURS PICKUP 4034061432		CONTACT INFO TYLER	
COMPLETION DATE: 09/24/2020			
UNIT: 610058		YEAR: 2013 MAKE/MODEL: KENWORTH T800	
SERIAL: 1XKDD40X0DJ957761		KILOMETERS: 502480	
INSP#:			
JOB#01 24 000 02 CHECK DRIVE LINE ANGLES			
CUSTOMER SAID THAT UNDERLOAD AT @ 100 TO 110KM			
HAS A VIBRATION THROUGH THE TRUCK.			
CHECKED DRIVELINE ANGLES ON DRIVE SHAFTS AND DIFFERENTIAL ANGLES.			
REPLACED HEIGHT CONTROL LINKAGE. ADJUSTED RIDE HEIGHT.			
ADJUSTED DRIVE LINE ANGLE ON AXLE TWO.			
1 HEN S-14187	LINK ASSEMBLY - BOLTE	\$22.41	14.92EA 14.92
2 MOO K8943	ALIGNMENT SPACER	\$11.10	10.49EA 20.98
PARTS SUBTOTAL			35.90
LABOR SUBTOTAL			440.00
SHOP SUPPLIES			44.00
** JOB SUBTOTAL			519.90
JOB#02 59 000 01 5TH WHEEL			
REPLACED 5TH WHEEL LEG BRACKET ASSEMBLY AND 5TH WHEEL			
HEAD.(CUT OFF THE STOPS ON THE SLIDE PLATE, CLEANED			
PLATE, SLID OFF THE LEG BRACKETS, INSTALLED NEW ASSEMBLY			
AND WELDED STOPS BACK ON)			
1 HOL XA-7009	SLIDER BRACKET 10.0	\$2216.86	1536.98EA 1536.98
1 HOL XA-351-A-L-P	FIFTH WHEEL,FW35 SE	\$1395.00	1095.00EA* 1095.00
PARTS SUBTOTAL			2631.98
LABOR SUBTOTAL			385.00
SHOP SUPPLIES			38.50
** JOB SUBTOTAL			3055.48
JOB#03 13 000 03 AIR BRAKE LINE/HOSE			
REPLACED TWO FOOT SECTION OF LINE THAT HAD A HOLE BURNT			
I, THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURES RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-50 KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL WORK PERFORMED WILL BE FREE OF DEFECTS IN MATERIAL OR WORKMANSHIP, UNDER NORMAL USE AND SERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR THOUSAND (4000) MILES OR SIXTY-FOUR HUNDRED (6400) KM, WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK. SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE. PAYMENT TO BE NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERETO.			
WORK AUTHORIZED AND PAYMENT GUARANTEED BY			
FREIGHT	SUBTOTAL	TAX STATUS/STATE	SALES TAX
			CONTINUED



PLEASE REMIT TO:
C/O C25032
PO Box 2532
Station M
CALGARY, AB
T2P 5P9

TERMS



**Truck -Trailer
Parts and Service**
www.fleetbrake.com


FLEET BRAKE PARTS & SERVICE LT

158 QUEENS DRIVE
RED DEER AB T4P 0R4
403-343-8771

INVOICE DATE	
09/25/2020 01:15PM	
INVOICE NO.	PAGE
110006906	2
CUSTOMER NO.	BRANCH
64131	* 11*

SOLD TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

SHIP TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

CUSTOMER P.O.		REFERENCE NO.		GST# R101819472	
719476		015910		(403) 346-4667	
				48	053/948
				PRICE/PER	EXTENSION
IN IT.					
2	FAR 1462-6	FITTING, UNION COUPLING \$3.01		2.24EA	4.48
2	FAR 1485-6-REEL	TUBING-PLASTIC PARFLEX \$1.11		0.82EA	1.64
PARTS SUBTOTAL					6.12
LABOR SUBTOTAL					44.00
SHOP SUPPLIES					4.40
** JOB SUBTOTAL					54.52
JOB#04 13 000 11 ABS BRAKES					
SET UP ON COMPUTER, CODE INDICATED OPEN CIRCUIT IN RIGHT REAR WHEEL SENSOR. TESTED ALL SIX SENSORS, ALL READ GOOD. CLEARED CODES, TEST DROVE UNIT AND ABS LIGHT CAME BACK ON. RECHECKED AND THE SAME CODE CAME UP, PULLED BACK LOOM AND FOUND THE SENSOR CALBE WAS CRUSHED HALF WAY DOWN. REPLACED SENSOR, TEST DROVE UNIT AND ABS LIGHT STAYED OFF.					
" "CHARGED ONLY FOR THE SENSOR, NO CHARGE FOR LABOUR, REFER TO IN#110006683"					
1	FLS ABS180-1.8M65MM STRAIGHT SENSOR 1.8M	\$53.90		50.96EA	50.96
POLICY ADJUSTMENTS					143.00-
MISC SUBTOTAL					143.00-
PARTS SUBTOTAL					50.96
LABOR SUBTOTAL					143.00
** JOB SUBTOTAL					50.96
JOB#05 17 000 00 TIRES, TUBES, LINERS AND VALVES					
NOTE; BOTH STEER TIRES HAVE RUN OUT AND SLIGHT AND BALANCE ISSUE-SHOULD HAVE BOTH STEER TIRES BALANCED.					
PARTS SUBTOTAL					0.00
LABOR SUBTOTAL					0.00
** JOB SUBTOTAL					0.00
*TOTAL PARTS:					2724.96
*TOTAL LABOR:					1012.00
*TOTAL OTHER:					143.00-
I, THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURES RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-50 KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL WORK PERFORMED WILL BE FREE OF DEFECTS IN MATERIAL OR WORKMANSHIP, UNDER NORMAL USE AND SERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR THOUSAND (4000) MILES OR SIXTY-FOUR HUNDRED (6400) KM, WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK. SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE . PAYMENT TO BE NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERETO.					
WORK AUTHORIZED AND PAYMENT GUARANTEED BY 					
FREIGHT		SUBTOTAL		TAX STATUS/STATE	SALES TAX
					PLEASE PAY
					CONTINUED



PLEASE REMIT TO:
C/O C25032
PO Box 2532
Station M
CALGARY, AB
T2P 5P9

TERMS



**Truck -Trailer
Parts and Service**
www.fleetbrake.com


FLEET BRAKE PARTS & SERVICE LT

158 QUEENS DRIVE
RED DEER AB T4P 0R4
403-343-8771

INVOICE DATE	
09/25/2020 01:15PM	
INVOICE NO.	PAGE
110006906	3
CUSTOMER NO.	BRANCH
64131	* 11*

SOLD TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

SHIP TO: TRICAN WELL SERVICE LTD
8037 EDGAR INDUST. CRES
RED DEER AB T4P 3R2

CUSTOMER P.O.	REFERENCE NO.	GST# R101819472		
719476	015910	(403) 346-4667	48	053/948
			PRICE/PER	EXTENSION
*TOTAL SHOP SUPPLIES:				86.90
***SUB TOTAL:				3680.86
***PST/PST TXBL -PROVINCE:AB				0.00
***GST - 101819472				184.04
I, THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD, DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURERS RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-50 KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL WORK PERFORMED WILL BE FREE OF DEFECTS IN MATERIAL OR WORKMANSHIP, UNDER NORMAL USE AND SERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR THOUSAND (4000) MILES OR SIXTY-FOUR HUNDRED (6400) KM, WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK. SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE . PAYMENT TO BE NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERETO.				
WORK AUTHORIZED AND PAYMENT GUARANTEED BY 				
FREIGHT		SUBTOTAL	TAX STATUS/STATE	SALES TAX
			PLEASE PAY	
			3864.90	



PLEASE REMIT TO:
C/O C25032
PO Box 2532
Station M
CALGARY, AB
T2P 5P9

TERMS