## . LECH MECHANICAL SERVICES INC.



60309 Range Road 471 PO BOX 5385 Bonnyville, AB T9N 2G5 780-201-3682

## Invoice

| Date       | Invoice # |
|------------|-----------|
| 2021-06-23 | 697       |

|   |      |    | -  |
|---|------|----|----|
| 1 | nvo  | 00 | 10 |
| э | IIVU | CC |    |

North East Bulk Services 6410-54 ave. Bonnyville, Alberta T9N 2L6 780-826-2041

| P.O. No. | Terms  | Unit #    |
|----------|--------|-----------|
|          | Net 30 | H2 330CLC |

| Qty | Description  | Rate   | Amount      |
|-----|--|--------|-------------|
| 67  | Removed engine, replaced rod bearings, repaired timing cover, replaced rear main seal, rebuilt fan hub, assembled and installed engine.  Diagnose rough idle, re-routed wiring to crank sensor, repaired wiring to temp sensor, repaired wiring to oil pressure switch and replaced switch, replaced fuel filter, cleaned air filter, replaced o-rings on oil feed line to injection pump. | 110.00 | 7,370.00    |
| 1   |  | C-1-   | Tax Cummons |

Sales Tax Summary

GST@5.0% Total Tax 368.50 368.50

| Thank you for your business. | Total | \$7,738.50 |
|------------------------------|-------|------------|
|                              | 1000  | 41,100.00  |