County of St. Paul No. 19

2008 Chev 3500 Suburban Repair History

		,
July 2022 237,274 km	Control Arm	\$249.10
	Rear A/C Line Set	\$490.89
	Control Arm & Ball	\$188.89
June 2023 234,000km	New Tires	\$1,260.21
	Vent Door Actuator	\$141.70
	Wheel alignment	\$139.70
May 2023 233,267km	Thermostat	\$85.93
	Water Pump kit	\$406.28
	Pipe	\$40.65
	Tie Rod Ends	\$225
	Pitman arm assembly	\$186
	Power steering hose	\$41.79
	Detail Unit	\$450
	Cooler Lines	\$237.06
	Lift Arm Kit	\$302
	Two shocks	\$103.98
	Two control arms and ball	\$527.18
	Stabilizer bar link	\$38.98
	Two struts	\$180.82
	Eight spark plugs	\$31.04
	One coil pack	\$45.57
April 2022 230,000km	Hub Bearing Assembly	\$373.19
Mar. 2022 228,000km	HVAC Module	\$308.28
	Blower Motor	\$120.69
Sept. 2021 222,000km	Fuel pump	\$484.67