

JudgeMotive Automotive Services & Sales Ltd.

7012 82 Avenue NW

Edmonton, AB

T6B 0E7

Tel.#: (780) 761-2886 Fax: (780) 757-2887

INVOICE ADMIN:

2017 RAM 1500 LONGHORN L

Plate :

ODO : 252,099

V.I.N.: 1C6RR7PT8HS739291

Unit #:

INV # : 35429

Date : 09/05/2024

Time :

PO # :

REG # : 780703294RT0001

C#: B#: Engine: 5.7L V8 F OHV 16V

Tech. : SUNNY/

Qty	Hrs.	Description	Parts Ea.	Tot. Parts	Labour	Tx	Total	C
1.00		OOP Inspection			160.00	GST	160.00	
		Recom.				GST		
		* Front left Axle needs to be replaced				GST		
		* Front Left Axle Seal seepage				GST		
		* Front right Inner tie rod have minor play				GST		
		* Rear left license plate bulb not working				GST		
		* Windshield cracked				GST		
		* Front left Fog lamp picktail needs to be replaced				GST		
1.00		Installation of both exhaust mufflers ABC	370.00	370.00		GST	370.00	
		Sub. Total: 530.00				GST		
1.00	1.20	Installation of front LHS axle wsi	194.12	194.12	132.00	GST	326.12	
		Sub. Total: 326.12				GST		
1.13		AC gas recharge .51KG r1234	170.00	192.10	160.00	GST	352.10	
		Sub. Total: 352.10				GST		
1.00		Shop Supplies	15.12	15.12	9.04	GST	24.16	

WO# 38966

Copyright 2024 Autogence Inc. - LANKAR 11.17.3

PAID BY:...

09/05/2024 Visa 1,294.00

Thank You for choosing JudgeMotive Automotive Services & Sales Ltd. for your vehicle repairs. We were glad to assist you and hope to see you again. We do full automotive service & repairs on all makes & models/Out of Province Inspections/Insurance Inspections. Recommendation : Retorque lugnuts after 100 kms

Sub Tot.	771.34	461.04	1,232.38
		GST	61.62
		Deductible	0.00
		Total	1,294.00

Page

1 of 1