

**Genuine Automotive Service LTD**

16809 113 AVE NW
101
EDMONTON, AB T5M 2X2
Tel: 780-455-0024
info@genuineautomotive.ca

Invoice I001775

Technician: Michael Boucher
Date: 12-27-2023
Estimate: Q001350
R/O: J001653

2012 Ford F-250 Super Duty XLT
6.7 DIESEL
1FT7W2BT1CEB01555

License Plate:

km In: 264,585
km Out: 264,585

CUSTOMER ISSUES AND ADVISORIES**Symptoms and Diagnostic Trouble Codes**

Smoking from exhaust a lot

Advisory Notes

Found a lot of engine oil present in the exhaust system, removed the intake to inspect the turbo cold side and when spinning the impeller the bearings are extremely loud and have a fair amount of play. Required turbo removal and rebuild.

Also, suspect the injector to be over-injecting.

Vehicle as a tuned computer and can cause diagnostic and repair to not be accurate. No warranty is possible with tuned vehicle

WORK PERFORMED**Full Synthetic Oil Change**

Labor		Tech	Hrs	Price	Discount	Total
Oil & Filter Service			0.20	100.00	0.00%	20.00
Parts		Part No	Qty	Price	Discount	Total
Oil Filter			1.00	18.51	0.00%	18.51
5W40 Special Tec AA (DSL)			16.00	10.00	0.00%	160.00

SubTotal: Full Synthetic Oil Change **\$198.51**

Turbocharger

Labor		Tech	Hrs	Price	Discount	Total
Replace - Turbocharger -			5.50	90.00	0.00%	495.00
Parts		Part No	Qty	Price	Discount	Total
Turbocharger Mounting Gasket Set			1.00	232.50	15.00%	197.63
New Turbocharger			1.00	2,100.00	0.00%	2,100.00
Oil Feed tube Assembly			1.00	43.46	20.00%	34.77
Diesel Engine Coolant			1.00	35.88	0.00%	35.88

SubTotal: Turbocharger **\$2,863.28**

Diagnostic - General**Work Description**

Verify and diagnose malfunction of vehicle based on customer report and observations. Please advise on repairs to restore vehicle to designed operation.

Labor		Tech	Hrs	Price	Discount	Total
Diagnostic			1.50	120.00	100.00%	0.00

SubTotal: Diagnostic - General **\$0.00**

Genuine Automotive Service LTD

Tel: 780-455-0024

Invoice I001775

Date: 12-27-2023

• 2012 Ford F-250 Super Duty XLT

Labor	515.00
Parts	2,546.79
Hazmat*	0.00
Supplies*	51.50
GST/HST	155.67
PST	0.00

Invoice Total**\$3,268.96**

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

AUTHORIZATION

Date/Time:	Authorizer	Method	Contact Details	Original Estimate Total
12-07-2023 1:40 PM				3,189.29

X

Customer Signature

REPAIR AUTHORIZATIONS

Date/Time	Authorizer	Method	Contact Details	Additional Cost	New Value
12-27-2023 08:39 AM				79.67	3,268.96

Save replacement parts for inspection or return? (Core may apply)☐ Yes☐ No

Thank you for choosing Genuine Automotive Service!

By signing this document I acknowledge I have received the above products and/or services in good order. Warranty on Parts and labour is 3 Months or 1000 km, which ever comes first. Warranty work must be performed in our shop and does not cover towing charges or any 3rd party costs. No Warranty will be given on customer supplied parts, or if any modifications are done after services have been provided. All warranty work will be diagnosed and determined by Genuine Automotive Service ONLY. Abuse or neglect of the vehicle will result in all warranty being void. Customers are allowed to ask for all parts replaced or removed from their vehicle, a core fee may apply on some specific parts.

If service required wheels to be removed from vehicle, RE-TORQUE is REQUIRED within 100km or service and safety can not be guaranteed