

Vehicle Repair Log

Last modified:

Year	2014
Make	MAZDA
Model	CRUZE
Vehicle ID No. (VIN)	1M1AW0YYXEM042738
License No.	G 41233

NEXT SERVICE

Date	Description of Work	SHOP INV#	KM	OTHER	Labor Cost	Parts Cost	GST	Total Cost
JAN 28/22	REPLACE GLAD HAND	C-MAC 1072986			\$28.34		1.42	\$29.76
MAR 10/22	HEATER ACTUATOR	DRB SO-3102	412513	65.70	\$657.00	\$600.66	66.17	\$1,389.53
FEB 25/22	REPAIR 5TH WHEEL AIR LEAK	C-MAC 1073333			\$50.52		2.53	\$53.05
MAY 5/22	LUBE FILTER, REPLACE 5TH WHEEL PINS AND	DRB SO-3437	433895	122.35	\$1,223.49	\$2,337.95	184.19	\$3,867.98
MAY 30/22	SIDE WIPER ARM	DRB SO-3563	445189	27.38	\$273.75	\$338.73	31.99	\$671.85
JUNE 21/22	CLUTCH	DRB SO-3879	457019	32.85	\$328.50	\$7.32	18.43	\$387.10
JULY 18/22	REPLACE CONDENSER, RECHARGE AC,	DRB SO-4080	469263	50.23	\$602.25	\$455.47	55.9	\$1,173.85
NOV 14/22	REPAIR REAR LIGHT	C-MAC 1076239			\$113.47			\$113.47
MAY 12/23	REPLACE 5TH WHEEL	TT 220637	513957	33.60	\$420.00	\$2,380.10	141.69	\$2,975.39
MAY 12/23	FOR PUMP, REPLACE AIR SUSPENSION	TT 220637	513957	788.28	\$4,291.00	\$2,857.96	396.86	\$8,334.10
MAY 18/23	RETORQUER, REPLACE FUEL DOSER MODULE	TT 220686	514186	54.72	\$684.00	\$1,042.85	89.08	\$1,870.65
JUN 9/23	TIRE CHANGE OVER	ST 172323	520873		\$45.00		2.25	\$47.25
JULY 18/23	REPLACE AIR LINE	C-MAC 1078859	535115		\$152.02		7.6	\$159.62
JULY 12/23	REPLACE MUDFLAPS	C-MAC 1078762	534202		\$464.28		23.21	\$487.49
SEPT 18/23	5TH WHEEL REBUILD KIT	C-MAC 1079330	539239		\$1,268.95		63.45	\$1,332.40
OCT 11/23	REPLACE DRIVES	FOUNT 0951091854	539286	112.00	\$395.60	\$3,089.13	179.84	\$3,776.57
NOV 15/23	REPAIR AIR LEAK IN SECONDARY AIR SYSTEM	TT 515	539901	39.36	\$492.00	\$244.20	38.78	\$814.34
JAN 26/24	ADJUST 5TH WHEEL	TT 755	541511	6.91	\$86.40		4.67	\$97.98
JUNE 6/24	ENGINE DELETE, OIL LUBE FILTER,	TT 1002	542709	19.20	\$4,740.00	\$385.88	257.12	\$5,402.20
NOV 21/24	LEAK AT DIFF LOCK, REPLACE EMERGENCY	TT 1225	561013	191.38	\$2,392.20	\$2,777.58	268.025	\$5,629.19
DEC 11/24	INSTALL NEW INJECTOR KIT	TT 1674	567767	224.26	\$2,803.20	\$6,879.49	495.35	\$10,402.30
	CHARGING TRAILER LIFT GATE	TT 1741	568727	68.74	\$859.20	\$686.14	80.7	\$1,694.78
								\$0.00

Total repair expenses:

\$50,710.85