



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

VIN: 1NPF40X57D678936

Year: 2007

Plate Number:

Color: Med Blue

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Change oil and filter (42-litres 5-40) [21000 hrs]	Lee Godin		2-Jan-18	1243268 km
Replace direct mount dump pump			12-Jan-18	
Changed out hydraulic pump	Joshua Hofer		13-Jan-18	
Drain & refill hydraulic oil in Hydraulic tank	Kelly Irwin		15-Jan-18	
Repaired light cord & Put wheel chains on	Kelly Irwin		15-Jan-18	
Repair washer	Kelly Irwin		19-Jan-18	
Put extra poly in	Kelly Irwin		20-Jan-18	
Wheel end Replace, cooling system repair	Overdrive	01S35474	2-Jan-19	1352558 km
Changed out water pump	Joshua Hoffer	21955	8-Jan-19	
Changed out steering box	Joshua Hoffer	21956	10-Jan-19	
wash unit	Vaughn MacDonald	19088	11-Jan-19	
Wash unit / grease unit	Vaughn MacDonald	19091	16-Jan-19	
install mud flaps/install brackets in light stand...	Vaughn MacDonald	19093	18-Jan-19	
frozen/seized brakes	Eden Holley	24487	25-Jan-19	
alignment diagnose	Overdrive	01S35678	25-Jan-19	1358358 km
took hose off unit to get new made @ Matichuk...	Ernie Roux	23875	28-Jan-19	
Str gear core; freight in/out steering box	Overdrive	01S35533	28-Jan-19	1352558 km
Removed & replaced exhaust under cab	Justin Maier	Repair# 00324	11-Jan-20	1408814 km
Parts purchased to replace Exhaust under cab	Overdrive	01P38460	13-Jan-20	
Water pump	Edmonton Kenworth	02NP487957	3-Jan-21	
Replace water pump	Overdrive	01S40015	4-Jan-21	1451892 KM
Horn, Bushing - hood pivot, bolts, nuts, washers, hairpin clip	Stahl Peterbilt	S1363468	5-Jan-21	
Chain hanger set	Fort Garry Industries	F8427728	5-Jan-21	
Wash unit	Robert Urquart	DT 19620	5-Jan-21	
Wash unit	Robert Urquart	DT 19623	7-Jan-21	
Fuel tank vent	NAPA	011-133796	9-Jan-21	
Replace clutch brake, replace abs valves	Truck Zone	905-002666	12-Jan-21	1453139 KMS
Replace axle seal on 2nd axle drivers side	Dan Howey	DT 19803	26-Jan-21	
Purchase cotton cover hose	Matichuk Equip	88259900	10-Jan-22	
Purchase Bracket kit	NAPA	011-185026	10-Jan-22	
Purchase oil & fuel filters	NAPA	011-185459	12-Jan-22	
Flat repair	Fountain Tire	0331135157	12-Jan-22	
Change Oil and Filter, Change Fuel filters, Grease unit	RBOL - D Anthony	00492	12-Jan-22	1486893 kms
Replace Multifunction switch	RBOL - D Anthony	00493	13-Jan-22	1487659 kms
Wash Unit	RBOL - D Anthony	00494	21-Jan-22	
Purchase washer pump and wiper nozzle kit	NAPA	011-187527	25-Jan-22	
Flat repair	Fountain Tire	0331135155	12-Jan-22	1486888 kms
Purchase electric ABS cable	NAPA	011-240111	4-Jan-23	
Repair motor	RBOL - Dan Howey	D4765	31-Jan-23	
Engine repair	Adrenaline Deisel	6653	15-Jan-24	
Torque drive wheels, top up fluids	RBOL - D Merko	D6925	17-Jan-24	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

Year: 2007

Color: Med Blue

VIN: 1NPF40X57D678936

Plate Number:

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Repair Dump Truck Pump & Air Cylinder			14-Feb-17	
Fix Tarp Wire			16-Feb-17	
Fix Pump Valve			27-Feb-17	
Boost and fix	Kelly Irwin		1-Feb-18	
Repair Fender	Kelly Irwin		8-Feb-18	
Changed out a tire			8-Feb-18	
Grease Seals / Unit			12-Feb-18	
Starter; welding cable	Napa	011-044388	16-Feb-19	
starter - new install	Joshua Hoffer	21974	16-Feb-19	
18 exact fit wiper BL (front)	Napa	011-044931	21-Feb-19	
fixed air leaks on Superbees that were hooked onto unit	Joshua Hoffer	21976	25-Feb-19	
Replaced right rear mud flap	Lloyd Breen	DT# 23064	14-Feb-20	
Union coupling tub, nylon tubing	Napa	011-092801	24-Feb-20	
Tire Chain boomer, cross chain hook, orange nylon flag	Matichuk	83513500	25-Feb-20	
starter relay on the firewall melted, replaced start assembly,	Overdrive	01S37867	25-Feb-20	1402128 km
repaired tire chain on tractor	Justin Maier	Repair# 00393	25-Feb-20	1418257 km
Purchase Blower Motor	Brandt	L1781506	2-Feb-22	
Install new blower motor	RBOL - D Anthony	00967	2-Feb-22	1499131 km
Purchase gasket	NAPA	011-189742	9-Feb-22	
Change wheel seal	RBOL - R Macd	D3954	3-Feb-22	
Purchase spin on lube filter	NAPA	011-191155	17-Feb-22	
Purchase Hydraulic ftg	Matichuks	88554200	24-Feb-22	
Tire rotation	Mallaig Tire	5969	24-Feb-22	
Reinstall motor, start unit and let run for 2 hrs	RBOL - D Howey	D4767	2-Feb-23	
Purchase crosshead valve and gear plug cover	Edmonton Kenworth	04LP336725	1-Feb-23	
Purchase Brakleen	NAPA	011-244690	2-Feb-23	
Grease Unit	RBOL - J Lawrance	D7588	7-Feb-23	
Fix lower drivers side step, install new electrical cords	RBOL - D Howey	D4773	8-Feb-23	
Wash engine on heater A/C unit	RBOL - Derek	D6992	2-Feb-24	
Fix 2 faulty injectors	Adrenaline Deisel	6813	16/Feb/24	
Fix oil leak	RBOL - D Howey	D7056	21-Feb-24	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

VIN: 1NPF40X57D678936

Year: 2007

Plate Number:

Color: Med Blue

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Fix Air Compressor	OVERDRIVE		7-Mar-18	
STR box I/P seal kit	OVERDRIVE		8-Mar-18	
Air compressor, gasket, pump & governor	TRUCK ZONE		9-Mar-18	
Filter - spin on secondary	G Force		13-Mar-18	
pressure sensor and pto end plate gasket	OVERDRIVE		13-Mar-18	
Solenoid valve	Kelly Irwin		15-Mar-18	
Install Brace for Hyd. Tank	Fountain Tire		21-Mar-18	
Change tire and valve stem	TRUCK ZONE		23-Mar-18	
Transmission oil leak, damaged PTO shaft, repaired, Relocate fuel tank mounts, Change DS mirror bracket, Power steering res gasket, oil			31-Mar-18	
fix wiring on right rear tail light	Vaughn MacDonald	24033	4-Mar-19	
wash unit - B trains	Vaughn MacDonald	24041	9-Mar-19	
wash unit	TRUCK ZONE	2290720006	13-Mar-19	
socket, ABS ISO 3731 7 pin	Overdrive	01P36593	13-Mar-19	
low clnt sensor	TRUCK ZONE	2290850032	26-Mar-19	1371646 km
check for leak on line going to #1 air tank.	Vaughn MacDonald	24246	27-Mar-19	
wash unit/install shocks	Derek Batke	24253	27-Mar-19	
change out anti-freeze level sensor & all shocks	Justin Maier	Repair# 00396	5-Mar-20	1421391 km
Checked hydraulic system, repaired 2 wires rubbing together causing the brake lights to remain on	FGI	F7877308	7-Mar-20	
Airshift PTO	Double R Heavy Duty	5805	9-Mar-20	1421768 km
Diagnosed & replaced hydraulic pump, dead head at cylinder. Possible fitting, replaced	Justin Maier	Repair# 00398	9-Mar-20	1421768 km
replaced PTO on transmission pump, then Double R replaced pump	Napa	011-094689	10-Mar-20	
Spring Brake 3030	Justin Maier	Repair# 00333	10-Mar-20	1421768 km
replaced Drivers side #3 Axle brake pot	Stahl Peterbilt	Inv #: S1288752	12-Mar-20	
Air Tank & U-bolt	Craig Whittaker & Randy	DT #: 22673	14-Mar-20	
Change out Air Tank on unit	Justin Maier	Repair #: 00131	30-Mar-20	1427235 km
Grease Unit, check front hub levels & rear diff levels, check trans. Level, change hose clamp for PTO oil supply line, topped up coolant level, change engine oil & oil filter	Canadian Fabrication	3407	12-Mar-21	
Fabricate removeable rig mat carriers	Matichuk	86068100	15-Mar-21	
Single wire cover	Napa	011-142695	19-Mar-21	
Purchased "MC54" Switch	OVERDRIVE	01S40482	29-Mar-21	
Transmission Manual Replace	Dan Howey	DT - 2827	30-Mar-21	
Install racks on truck, Put straps and winch bar... with truck	Mallaig Tire	Invoice # 3774	11-Mar-21	
Tire Rotation 11/R24.5 NT989 O/S DR LRH 16 Ply	RBOL - Dan Howey	01147	1-Mar-22	1507789 km
Fix harness that shorted out	RBOL - Dan Howey	01156	8-Mar-22	
Dryer freezing up. Pull line off compressor. Replace	RBOL - R Macdonald	D6302	11-Mar-22	



Unit Number: **131**

Make / Model: **Peterbilt 378 T/A Sleeper**

VIN: 1NPF40X57D678936

Year: **2007**

Plate Number:

Color: **Med Blue**

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Tighten up head light	RBOL - R Macdonald	D6316	22-Mar-22	
Replace psngr sd signal light comp/housing	Dan Howey	D6325	29-Mar-22	



Unit Number: **131**

Make / Model: **Peterbilt 378 T/A Sleeper**

VIN: **1NPFD40X57D678936**

Year: **2007**

Plate Number:

Color: **Med Blue**

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Cleaned up sleeper cab	TRUCK ZONE		30-Apr-18	
Purchase of linkage kit	Derek Batke	24257	9-Apr-19	
fix burnt out lights/chng serpentine belt	Overdrive	01P36751	9-Apr-19	
belt (1-21/32"X91")	Truckzone	005-001126	9-Apr-19	
lamp LED w/c mirror	Derek Batke	24258	10-Apr-19	
Greased Unit	Napa	011-145497	12-Apr-21	
Oil Filter	Tristan Goldie	DT 2743	13-Apr-21	
Welded Parts on truck	Cervus equipment	L759036	23-Apr-21	
Divider-fuel hi flow Rnd	Overdrive	01S40699	30-Apr-21	
Clutch Alignment	NAPA	011-197718	2-Apr-22	
Purchase Load sign	NAPA	011-198058	5-Apr-22	
Purchase junction box	RBOL - D Howey	D6503	5-Apr-22	1512193 kms
Install new junction box & wiring	RBOL - D Howey	D6509	15-Apr-22	1513440 kms
Fix brake lights on trailer	Overdrive	01P45078	25-Apr-22	
Purchase actuator	NAPA	011-200678	24-Apr-22	
Fix wiring harness	Adrenaline Diesel	6976	1/Apr/24	
Replace brakes w/Derek	RBOL - D Merko	D7120	3-Apr-24	
Purchase brake drums & shoe	Napa	011-310700	3-Apr-24	
Fix air leaks and actuators, change oil & filter	Boersma Ent.	233702	10-Apr-24	1563463 kms
Fixed connection to ECM	Coppertop	28385	11-Apr-24	1563292 kms
Adjust APU, rewire and re position	RBOL - D Howey	D7061	15-Apr-24	
Purchase screws, washers & locknuts	Bonnyville Bolt	1-33999	16-Apr-24	
Fix leaking fuel line, change out coolant valve, replace o-ring	RBOL - D Batke	D6963	17-Apr-24	
Purchase screws, washers & locknuts	Bonnyville Bolt	1-34002	17-Apr-24	
Purchase 1/2" WOG valve	OVERDRIVE	01P50481	17-Apr-24	
Find area under bunk to fit A/C unit	RBOL - D Howey	D7062	18-Apr-24	
Hook up lines for APU unit	RBOL - D Batke	D6968	23-Apr-24	
Purchase electrical tubing	Matichuk	93707600	23-Apr-24	
Purchase misc. hose clamps and accesories	Matichuk	93704300	23-Apr-24	
Purchase heat shrink & belt	Napa	011-314124	24-Apr-24	
Purchase white & red wiring	Matichuk	93710500	24-Apr-24	
Purchase gates belt	Matichuk	93713300	24-Apr-24	
Fix aux cable,	RBOL - Dan Howey	D7065	27-Apr-24	
Fix cat walk	RBOL - Dan Howey	D7066	29-Apr-24	



Unit Number: **131**

Make / Model: **Peterbilt 378 T/A Sleeper**

VIN: **1NPF40X57D678936**

Year: **2007**

Plate Number:

Color: **Med Blue**

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Purchase Oil Filter	Fixed by OVERDRIVE		11-May-17	
A/C Repair	Herbert Brown		15-May-17	
Grease Seals / Unit	Fixed by OVERDRIVE		26-May-17	
Diagnose weak A/C & replace A/C Condensor	Herbert Brown		29-May-17	
General Maintenance On Tarp	Fountain Tire		4-May-18	
Flat repair, drivers front steer repair	Derek Batke	DT 24263	7-May-19	1373255 Km
Checked fuel filter, its full, ran unit for an hour	Derek Batke	DT 24267	15-May-19	1373256 Km
greased unit, fixed air leak on line that rubber	Dylan West	D3626	25-May-21	
Put T valve in for return fuel line	Cold/Bonn	4604	12-May-22	
Replace Windsheild	Double R	9168	18-May-22	
Adjust clutch	RBOL - R MacD	1354	19-May-22	
Take to Fountain tire for tire change	NAPA	011-206470	30-May-22	
Wash unit	RBOL - D Merko	D7915	17-May-23	
Fix fitting to repair air leak	RBOL - Dan Howey	D7074	22-May-24	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

Year: 2007

Color: Med Blue

VIN: 1NPF40X57D678936

Plate Number:

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Check ABS Codes	Overdrive		13-Jun-17	
Repair ABS Coding Problems	Michael Kleinsasser		18-Jun-18	
grease unit	Cold/Bonn glass	3411	5-Jun-19	
replaced drivers side windshield	Edge Heavy Duty	3768	28-Jun-19	1374448 kms/ 23906 hrs
Replaced Stick shift with used one, ran power balance test on engine, replaced new 5-6 injectors, installed ini shaft,	Justin Maier	DT #: 23917 - Kal-Tire #: 639071831	10-Jun-20	1,429,302 Km
Took to Kal-Tire to have new tires installed	Highmark HD Services	0381	12-Jun-20	1,430,391 kms
Replaced all 4 rear dust shields & slacks & pins, drill	Justin Maier	WO #: 00419	17-Jun-20	1,430,295 Km
Greased Unit & set clutch for better clutch brake	Highmark HD Services	0386	22-Jun-20	1,430,391 kms
Diesel is getting into coolant (see invoice for details)	Mitch Gaulin	DT # 20935	7-Jun-21	
Change wiper motor	Napa	011-153899	7-Jun-21	
wiper motor purchase	Dylan west	D.3689	19-Jun-21	
Service Unit	Double R	7627	30-Jun-21	
AC Charge	Dan Howey	D2846	19-Jun-21	
Straighten bumper hook	Edge Heavy Duty	4971	12-Jun-22	1,522,224 kms
Fix clutch brake, Fix leaking fuel shut off valve	NAPA	011-209047	15-Jun-22	
Purchase oil filter	NAPA	011-209146	15-Jun-22	
Purchase heat shrink	Overdrive	01P45507	15-Jun-22	
Purchase bumper eyebolt	Bonnyville Bolt	1-25890	17-Jun-22	
Purchase screw and lock nut	RBOL - R MacDonald	1591	17-Jun-22	
Repair front bumper	RBOL - D Howey	6151	15-Jun-22	
Change oil & Service, fix plug wires on cable	RBOL - D Howey	6153	17-Jun-22	
Wash Unit	RBOL - Mike S.	3303	21-Jun-24	
Change oil & Service	RBOL - D Howey	D5187	22/Jun/24	
Remove wiring for proheat	RBOL - D Howey	D5189	25/Jun/24	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

Year: 2007

Color: Med Blue

VIN: 1NPF40X57D678936

Plate Number:

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Replace Air Bag	TRUCK ZONE		25-Jul-18	
change eng oil and filters	Smoky Lake Tire&Auto	100437	17-Jul-19	
2 tires replaced	Edge Heavy Duty	3784	22-Jul-19	1382335 Km
recharged air conditioner	Overdrive	01P37461	29-Jul-19	
FW35 complete 5th wheel	Highmark HD	0404	15-Jul-20	1,431,311 kms
Replace Primary Air tank, repaired A/C, replaced fuel	Dan Howey	D2934	18-Jul-21	
Hook up to 241 Ready for inspection	Telephone Conn	110054	14-Jul-21	
Purchase radio speaker mic	Peterbilt	K11140	7-Jul-21	
Purchase parts	Brandt Tractor	L795240	25-Jul-22	
Purchase driveline inter axle 19.0"	Brandt Tractor	L795327	26-Jul-22	
Purchase kit, yoke, slinger, hdwe	NAPA	011-215936	27-Jul-22	
Purchase Bearing Kit	NAPA	011-215938	27-Jul-22	
Purchase bearing kit and strap kit	Double R	9602	27-Jul-22	1,527,980 kms
Install new yokes on axles, install new driveshaft, repair	Double R	9606	28-Jul-22	1,528,015 kms
AC Charge	NAPA	011-215947	27-Jul-22	
AC Charge	Double R	12815	10-Jul-24	1,565,401 kms
Purchase Adapter, cplg & paint mrkr	Matichuk Equip	94268400	12-Jul-24	
Purchase kit yoke assy, U joint amd pinion seal	NAPA	011-331246	30-Jul-24	
Replace above parts, grease unit	Double R	12912	30-Jul-24	1,565,490 kms



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

Year: 2007

Color: Med Blue

VIN: 1NPFD40X57D678936

Plate Number:

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
	Michael Kleinsasser		18-Aug-17	
Grease Seals / Unit	TRUCK ZONE		21-Aug-17	1219633 Km
Wheel Alignment	Joshua Hofer		16-Aug-18	
grease unit	Overdrive	01S36983	7-Aug-19	1383947 Km
repaired trailer socket & cord end for the trailer, adjusted clutch, check codes, check ABS, ABS diagnose	Fountain tire	033I110610	12-Aug-19	1385518 Km
purchased 4 tires and did a rotation	Truck zone	005-002614	22-Aug-19	
Pail of oil	Overdrive	01S36902	23-Aug-19	
vehicle coupling system rebuilt and installed	Superior Safety	144644	27-Aug-19	
Flammable solid placard	Highmark	0426	27-Aug-20	1435022 KM
Repaired alarm wire, & installed new sensor	NAPA	011-165291	25-Aug-21	
Purchase LED turn Sig Light	RBOL - D Anthony	1827	17-Aug-22	1530672 KM
Wash out radiator	RBOL - D Anthony	1832	16-Aug-22	1531973 KM
Replace cab air bag	Stahl Peterbilt	S1538949	20-Aug-22	
Purchase Cab air spring and ftg	Mallaig Tire	6769	22-Aug-22	
Rotated steer tires from 125				



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

VIN: 1NPF40X57D678936

Year: 2007

Plate Number:

Color: Med Blue

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
	G Force		6-Sep-17	
Coolant Leak, Chng filter, Truck Vibration & Oil Change	Derek Batke		17-Sep-18	
pull starter and replace	Lyndon Elock		26-Sep-18	
change hose ends, repair tarp crank	Fountain Tire		27-Sep-18	
change over and valve stem	TRUCK ZONE		27-Sep-18	
diagnose wiring issue	Overdrive	01P37757	16-Sep-19	
STR Shaft Assy	Napa	011-072847	19-Sep-19	
40" Pogostick	Fountain Tire	0331120732	1-Sep-20	1436107 KMS
Flat repair, changeover & valvestem	Justin Maier	143	5-Sep-20	
Change out Windsheild washer pump	Napa	011-118005	5-Sep-20	
Windsheild washer pump	Overdrive	01P40078	10-Sep-20	
1/4" Tubing, 1/4" - 1/8" Elbow	Napa	011-118625	11-Sep-20	
T-Bolt Clamp	Justin Maier	19554	11-Sep-20	
Service Work	Matichuk	84916100	11-Sep-20	
Dump Pump, Snap Ring, Bearing Ball	Red L	4341265	17-Sep-20	
Hose & Union	Matichuk	84994700	21-Sep-20	
Oil Suction, Clamp, Pipe Sealant	Overdrive	01P40147	21-Sep-20	
Hydraulic Oil	Justin Maier	DT 19566	21-Sep-20	
Drained hyd fluid & replaced supply line	Double R heavy Duty	6481	21-Sep-20	
Fitted hoses & rebuilt air and electrical to tank bar	Napa	011-120127	23-Sep-20	
Fuel Cap Gasket	Justin Maier	DT 19571	24-Sep-20	
Service Work	Justin Maier	DT 19572	24-Sep-20	
Replace Hyd pump, set brakes, greased unit	Flo-Draulic Controls	2892100	24-Sep-20	
Dump Pump	Edge Heavy Duty	4604	5-Sep-21	1469810 km
Purchase new EGR valve	Double R heavy Duty	7940	7-Sep-21	1469987 km
Replace Rear Drive axle airbags	Overdrive	01S41472	10-Sep-21	1468683 KM
Install new EGR valve	Stahl Peterbilt	S1542757	1-Sep-22	
Purchase Alternator	RBOL - D Howey	1773	1-Sep-22	
Install new Alternator	NAPA	011-222052	3-Sep-22	
NAPA	Overdrive	01P46259	14-Sep-22	
Purchase hose & clamps	Truck Zone	05P4989	28-Sep-22	
Purchase dimensional load sign and red flagging	NAPA	011-225212	25-Sep-22	
Purchase oil & fuel filters	RBOL - D Howey	1780	25-Sep-22	
Replace blown fuse on left turn signal	RBOL - D Merko	2344	25-Sep-22	
Change oil & service, grease & inspect	Stahl Peterbilt	S1550764	29-Sep-22	
Purchase lever style fuel cap	RBOL - D Howey	1781	30/Sep/22	
Fix coolant leak	RBOL - D Howey	D8529	7/Sep/24	
Purchase couplers & bshings	NAPA	011-338538	8/Sep/24	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

Year: 2007

Color: Med Blue

VIN: 1NPF40X57D678936

Plate Number:

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Fix lights on unit	HD Mechanical		19-Oct-16	
Low Power - checked over	Jacob Hofer		2-Oct-17	
Wired Lights	Kevin Entz		2-Oct-17	
Fixed Mud Flaps	Overdrive		2-Oct-17	
Replace steady bearing	Overdrive		5-Oct-17	
Repair Diff Problem, replace steady bearing	Kevin Entz		11-Oct-17	
Fixed wiring problem	TRUCK ZONE		17-Oct-17	
Replace Cab Panel & 48" Sleeper PA	Derek Batke		26-Oct-17	
Replace blown tires, (shoes & drum x4)	Derek Batke		26-Oct-17	
Fix Antifreeze leak	Derek Batke		26-Oct-17	
Install Drum & Shoes	TRUCK ZONE		27-Oct-17	
Pulled Starter and sent out for repair	Iron Knuckle		29-Oct-17	
Troubleshoot Engine Shutdown Condition			30-Oct-17	
Replace Grit guard seal & axle gasket	TRUCK ZONE		30-Oct-17	
Check Starter & Service	Kal Tire		9-Oct-18	
2 tires	Lydon Elock	19127	2-Oct-18	
Unit washed	Joshua Hoffer		9-Oct-18	
took of hydraulic tank and put on steps, pass side	Overdrive		26-Oct-18	
Heater hose	TRUCK ZONE		30-Oct-18	
Filter; OW40 Rotella	TRUCK ZONE		31-Oct-18	
Filter - lube	Coop	00153581A	1-Oct-19	
Purchased oil	Overdrive	01S37550	22-Oct-19	1390999 Km
Replaced rear shackle pins and bushings on 1st axle, Replaced steering shaft, installed new bolts on 2nd Axle left lower rear torque,	Ken Hatfield	DT 20363	3-Oct-20	983964 hrs
Clean inside of unit	Ken Hatfield	DT 20366	4-Oct-20	1441217 km
Wash Unit	Derek Batke	DT 20338	7-Oct-20	1442734 KM
Change oil	Overdrive	01P40330	7-Oct-20	
Oil Filter	Napa	011-122788	14-Oct-20	
6" amber Led, Glad hand seal close	Napa	011-122934	15-Oct-20	
Windsheild washer pump	Highmark	0432	15-Oct-20	
Replace exhaust pipes	Justin Maier	DT 19590	16-Oct-20	
Greased Unit	NAPA	011-124381	26-Oct-20	
Heat Guard	NAPA	011-124514	26-Oct-20	
Compression Sleeve, Compression Nut	Derek Batke	DT 20553	27-Oct-20	1448148 KM
Help Dan Change out air lines on air pots	Matichuk	85249400	27-Oct-20	
Hydraulic Hose, Swivel Fitting	Matichuk	85251300	27-Oct-20	
Hydraulic Hose, Swivel Fitting	Ken Hatfield	DT 20381	28-Oct-20	
Wash Unit	Overdrive	01P43469	13-Oct-21	
Purchase Exh Pressure Sensor	NAPA	011-172437	19-Oct-21	
Purchase Washers Screws & Nuts	Dan Howey	D2950	17-Oct-21	
Front bumper hanging up, block bumper up, cut bolts out	NAPA	011-227197	7-Oct-22	
Purchase mesh safety Flag	RBOL - D Howey	1783	10-Oct-22	
Check Oil level and top up coolant	Overdrive	01P46577	18-Oct-22	

Unit Number: **131**Make / Model: **Peterbilt 378 T/A Sleeper**VIN: **1NPF40X57D678936**Year: **2007**

Plate Number:

Color: **Med Blue****Maintenance Record**

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Purchase bumper eye bolt	NAPA	011-228184	16-Oct-22	
Purchase Knob Control head	Stahl Petebilt	S1771922	10-Oct-24	
Oil Change,	HD Mechanical		18-Nov-16	
Changed Belts	Kelly Irwin		21-Nov-17	
Repair Mud Flap	Kelly Irwin		21-Nov-17	
Install New Lights	Kelly Irwin		22-Nov-17	
Fill Alcohol Sniffer			23-Nov-17	
Replace cab air filter	Vaughn MacDonald	D 1919	23-Nov-18	
Wash unit	Vaughn MacDonald	D 1925	30-Nov-18	
Wash unit	Overdrive	01P38071	7-Nov-19	
Sec & Primary Fuel Filter	Roger Guerzon	DT 21273	9-Nov-19	need
Changed Oil, washed unit, greased	Napa	011-079705	12-Nov-19	
Hose clamp & fittings for Coolant leak	Roger Guerzon	DT 21274	12-Nov-19	
repaired coolant leak	Double D Heavy duty	5294	13-Nov-19	1399481 Km
ABS lights - replaced melted relays & melted fuse holders, fixed broken wires	Roger Guerzon	DT 21481	19-Nov-19	
Checked over unit & put in new fire extinguisher	Overdrive	01P38188	21-Nov-19	
Fuel Cap	Overdrive	01S37745	21-Nov-19	1399377 Km
Drive line repair - replaced transmission output nut, steady bearing, 2nd input axel u-joint	Napa	011-081895	27-Nov-19	
electric cable ABS	Justin Maier	repair# 00290	28-Nov-19	1403346 Km
installed new light cord lug into trailer cord	Dan Howey	DT 20590	12-Nov-20	1448156 km
Chase wiring to find power source for on key power -	NAPA	011-175108	4-Nov-21	
Purchase Fuel Filter	Edm Kenworth	02NP564988	6-Nov-21	
Replace pump gear fuel kit	NAPA	011-175079	4/Nov/21	
Purchase Fuel Filter	Dan Howey	D3003	8-Nov-21	
Remove & Replace fuel pump with new	Brandt	L803982	1-Nov-22	
Purchase Peterbilt name plate and latch	Stahl Peterbilt	S1563598	10-Nov-22	
Purchase window lift switch	RBOL - D Howey	D2589	16-Nov-22	
Check for air leaks - GOOD	Edm Kenworth	02NP663106	26-Nov-22	
Change out 8 tires	RBOL - D Merko	2131	15-Nov-23	
Torque wheels	RBOL - D Merko/D Howey	2132/D6806	16-Nov-23	
Charge batteries and add antifreeze	RBOL - D Batke	D6884	24-Nov-23	



Unit Number: 131

Make / Model: Peterbilt 378 T/A Sleeper

VIN: 1NPF40X57D678936

Year: 2007

Plate Number:

Color: Med Blue

Maintenance Record

Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Km / Hr
Replaced Water Pump & Refilled Coolant	Lee Godin		13-Dec-17	
Rewire Trailer	Kelly Irwin		14-Dec-17	
Repair Light Cord	Dawson Hamel		19-Dec-17	
Cleaned P.T.O and found leak	Kelly Irwin		20-Dec-17	
Repair Light Cord & Air Lines	Highmark HD Services		26-Dec-17	
Replaced shaft in turbo, flex pipe, step clamps, Air Filter	Randy Batke		27-Dec-17	
Replace gasket exhaust manifold	Warco Ind Cooling Serv		28-Dec-17	
Flush & Test Charged air	Vaughn MacDonald	24377	2-Dec-18	
clean box/ cut liner for install	Vaughn MacDonald	24379	3-Dec-18	
install box liner	Overdrive		6-Dec-18	
Engine heater diagnose, repair	TRUCK ZONE		19-Dec-18	
4" round LED S/T/T, grommet, rubber rin 4, pigtail	Northern Truck		18-Dec-18	
Toggle switch, 4 in tail light box	Eden Holley	24477	19-Dec-18	
Wash unit	Vaughn MacDonald	24397	20-Dec-18	
2 marker lights / fix cylinder	TRUCK ZONE		27-Dec-18	
0W40 Rotella, filter	Yellowhead		21-Dec-18	
Windshield	Matichuk Equip			
Nitrile Quad Ring, 4-1/2 X1 16X7/8 C/O WHL	Justin Maier	Repair# 00295	4-Dec-19	1403861 Km
Inspected unit	NAPA	011-085387	27-Dec-19	
Conelok locknut , radiator caps	Justin Maier	Repair# 00306	31-Dec-19	1407358 Km
Changed oil & Oil Filter, greased unit, set brakes, changed fuel filters, changed DS air bag, checked hub levels, lengthened out light cords	Dan Howey	DT 20709	8-Dec-20	
Replace grease nipple on jack shaft output U-joint	Edmonton Kenworth	04LP263871	10-Dec-20	
Air valve	Derek Batke	DT 20693	14-Dec-20	
Check for where antifreeze leak is coming from	Robert Urquhart	DT 19609	14-Dec-20	
Wash unit	NAPA	011-132415	28-Dec-20	
Hub cap	NAPA	011-179802	6-Dec-21	
Purchase Batteries	RBOL	D2393	6-Dec-21	
Replace Batteries & Grease Unit	RBOL - D Howey	D2597	5-Dec-22	
Pro Heat burned out	Overdrive	01P47016	8-Dec-22	
Purchase turbo charger	Overdrive	01P47012.02	9-Dec-22	
Purchase Engine Heater & proheat timer	RBOL - D Howey	D4527	10-Dec-22	1554661 km
Replace 3rd axle psgr side brake pot	Overdrive	01P47077	16-Dec-22	
Purchase hood cable	Fort Garry	F9807120	15-Dec-22	
Purchase cabinet Rack w/ oval lights	RBOL - D Anthony	2237	15-Dec-22	1555134 km
Replace turbo charger	Overdrive	01S44691	21/Dec/22	
Start Pro Heat	RBOL - D Howey	D8709	16/Dec/24	
Purchase tire chains	Bonnyville Bolt	1-137165	18-Dec-24	
Add methanol to tank behind cab	RBOL - J Ippolito	D8808	18-Dec-24	



Plate Number:

[illegible]