



VEHICLE CONDITION REPORT

TO BE COMPLETED IN FULL (except where noted)

Prepared by: Shane Norman Date Prepared: 30-Aug-23

VEHICLE INFORMATION

Unit#: 7721 Application: Pool vehicle
Driver: Various Average Monthly KM: 3.5 - 4 k

Make: Chevy Model: Traverse Year: 2019

Serial #: 1GNGVMKW6KJ133

Engine Size: 3.6L V6 Cab Type: 2 or 4 wheel drive: 4

Transmission: Automatic Body Color: White Odometer in KMs: 197482
(must be working at time of sale)

APPEARANCE

		GOOD	FAIR	POOR	Details Required for Poor or Fair
Interior	General	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Seats	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Door Panels	<u>Y</u>	<u></u>	<u></u>	<u></u>
Exterior	General	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Paint	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Body	<u>Y</u>	<u></u>	<u></u>	<u></u>
Tires	Front	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Rear	<u>Y</u>	<u></u>	<u></u>	<u></u>
Fenders	Front	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Rear	<u>Y</u>	<u></u>	<u></u>	<u></u>
Doors	Right	<u>Y</u>	<u></u>	<u></u>	<u></u>
	Left	<u>Y</u>	<u></u>	<u></u>	<u></u>
Glass	Windshield	<u></u>	<u>Y</u>	<u></u>	<u>Small chips and cracks.</u>
	Door Glass	<u>Y</u>	<u></u>	<u></u>	<u></u>

MECHANICAL

	GOOD	FAIR	POOR	Details Required for Poor or Fair
Engine	<u>Y</u>	<u></u>	<u></u>	<u></u>
Transmission	<u>Y</u>	<u></u>	<u></u>	<u></u>
Rear Axle	<u>Y</u>	<u></u>	<u></u>	<u></u>
Steering	<u>Y</u>	<u></u>	<u></u>	<u></u>
Springs	<u>Y</u>	<u></u>	<u></u>	<u></u>
Shocks	<u>Y</u>	<u></u>	<u></u>	<u></u>
Brakes (front)	<u>Y</u>	<u></u>	<u></u>	<u></u>
Brakes (rear)	<u>Y</u>	<u></u>	<u></u>	<u></u>

WHOLESALE MARKET VALUE - to be completed by Leasing Company Only

Wholesale Market Value \$ (excluding taxes) Good until:

DATE: