

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

☐ Truck/Truck-Tractor	GVW _____	☐ School Bus	Seating Capacity _____
☐ Light Truck	GVW _____	☐ Commercial Bus	Seating Capacity _____
☐ Converter		☐ Motor Coach	Seating Capacity _____
☒ Trailer			

Company Name OR Name of Owner of Vehicle DANDY OIL PRODUCT LTD				Business Telephone Number (789) 4541878	
Address Street 15630 -118 AVE		Town/City EDMONTON		Province AB	Postal Code T5V 1C4
Vehicle Identification Number 2C9LEA25861026064					
Make COLUMBIA		Model QUAD PULL (TANK)		Year 2006	Unit Number 401 (P4)
Odometer -	Km ☐ Miles ☐	Licence Plate Number UG8134		Province AB	

IT IS AN OFFENCE TO FALSIFY OR PRE-SIGN AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Name of Inspection Facility DANDY OIL PRODUCTS LTD	Inspection Facility Number 15565
Name of Inspection Technician (PRINT clearly) DAVID BURNETT	Inspection Technician Number A1485
Inspection Technician Comments HAVE REGISTRATION CHANGED TO MATCH VIN ON TRAILER	
Office Use Only	

David Burnett Signature of Inspection Technician **May/5/07** Date of Inspection (year/month/day)

This information is collected under the Traffic Safety Act and will be used to administer the Vehicle Inspection Program. For more information, call the Vehicle Safety Section in Edmonton at (780) 427-8901 or toll-free at 310-0000. Mailing address: Alberta Infrastructure and Transportation, Vehicle Safety and Carrier Services Branch, Box 900, Station Main, Edmonton, Alberta T5J 2L8.

Commercial Vehicle Record of Inspection

P 3

Registered Owner's Name: DANNY OIL PRODUCTS Phone No.: (780)

Address: 15630-118 Ave City: Edmonton Postal Code: T5V 1G4

Vehicle Make: Columbia Model: QUAD ROLL Year: 2006 GVWR or Bus Capacity: -

VIN: 2C9LEA2S861026064 Odometer: -

Unit No.: 401 License Plate No.: V68134 Jurisdiction of Issue: ALBERTA

Type of Vehicle: ☐ School Bus ☐ Commercial Bus ☐ Motorcoach
☐ Light Truck ☐ Truck/Tractor ☒ Trailer/Converter

Items in Red require measurements to be documented.

QUAD

		LEFT	FRONT	RIGHT		
m.m. PSI	14	5/8"	DRUMS/ROTORS	5/8"	14	m.m. PSI
	100	1.5"	LININGS/PADS	1.5"	100	
		40°	PUSH ROD TRAVEL	40°		
			CAM ROTATION			
m.m. PSI	14	5/8"	DRUMS/ROTORS	5/8"	14	m.m. PSI
	100	1.5"	LININGS/PADS	1.5"	100	
		40°	PUSH ROD TRAVEL	40°		
			CAM ROTATION			
m.m. PSI	14	5/8"	DRUMS/ROTORS	5/8"	14	m.m. PSI
	100	1.5"	LININGS/PADS	1.5"	100	
		40°	PUSH ROD TRAVEL	40°		
			CAM ROTATION			
m.m. PSI	14	5/8"	DRUMS/ROTORS	5/8"	14	m.m. PSI
	100	1.5"	LININGS/PADS	1.5"	100	
		40°	PUSH ROD TRAVEL	40°		
			CAM ROTATION			

☐ Wheel Torque Checked (_____ lbs)

Inspection Technician Comments (if applicable, write the section number and sub-section letter from the second page)

UIW NO WRONG

Inspection Date: 20070504 Time: 8:00 am/pm Inspection Passed? Yes / No

Certificate Issued? Yes / No Certificate No.: CU1110853 Certificate Issue Date: May 5 07

Inspection Facility Name: Danny Oil Product Facility No.: 15565

Inspection Technician Name: DAVE BURNETT Technician No.: A1485

Inspection Technician Signature: Dave Burnett

☐ Vehicle was returned to the Registered Owner without repairs completed.

OK REPAIR

- [illegible]

11

-

22

-

11

-
- Handwriting practice sheet for the letter 'n'. The sheet includes a vertical column of boxes, each containing a blue 'n' and a checkmark. To the right of the boxes are several horizontal lines for additional practice.

100

-

-

OK REPAIR

- [illegible]

- 

-

- [illegible]

-