

**PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION**

- |  |           |   |                        |
|--|-----------|---|------------------------|
| <input type="checkbox"/> Truck/Truck-Tractor | GVW _____ | <input type="checkbox"/> School Bus     | Seating Capacity _____ |
| <input type="checkbox"/> Light Truck         | GVW _____ | <input type="checkbox"/> Commercial Bus | Seating Capacity _____ |
| <input type="checkbox"/> Converter           |           | <input type="checkbox"/> Motor Coach    | Seating Capacity _____ |
| <input checked="" type="checkbox"/> Trailer  |           |   |                        |

Company Name OR Name of Owner of Vehicle <b>Dandy Oil Products</b>			Business Telephone Number <b>(780) 454-1878</b>	
Address	Street	Town/City	Province	Postal Code
<b>15630-118 AVE</b>	<b>NW</b>	<b>Edmonton</b>	<b>AB</b>	<b>T5V 1C4</b>

Vehicle Identification Number **2C9LEA25861026064**

Make <b>Columbia</b>	Model <b>Quad Pull</b>	Year <b>2006</b>	Unit Number <b>401</b>
-------------------------	---------------------------	---------------------	---------------------------

Odometer <b>82530</b>	Km <input checked="" type="checkbox"/> Miles <input type="checkbox"/>	Licence Plate Number <b>V68134</b>	Province <b>AB</b>
--------------------------	---	---------------------------------------	-----------------------

**IT IS AN OFFENCE TO FALSIFY OR PRE-SIGN AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Name of Inspection Facility <b>Dandy Oil Products</b>	Inspection Facility Number <b>15565</b>
Name of Inspection Technician (PRINT clearly) <b>David Burnett</b>	Inspection Technician Number <b>A1485</b>

Inspection Technician Comments

**Work completed on 2406**

**Office Use Only**

**David Burnett**  
Signature of Inspection Technician

**2010-4-26**  
Date of Inspection (year/month/day)

This information is collected under the Traffic Safety Act and will be used to administer the Vehicle Inspection Program. For more information, call the Vehicle Safety Section in Edmonton at (780) 427-8901 or toll-free at 310-0000. Mailing address: Alberta Transportation, Vehicle Safety and Carrier Services Branch, Box 900, Station Main, Edmonton, Alberta T5J 2L8.



# Commercial Vehicle Record of Inspection

Registered Owner's Name: Dandy oil products Phone No.: (789) 454-1878  
 Address: 15630-118 AVE City: Edmonton Postal Code: T5V 1C4  
 Vehicle Make: Columbia Model: Tank Year: 2006 GVWR or Bus Capacity: 34000kg  
 VIN: 2C9LEA25861026064 Odometer: 82530  
 Unit No.: 401 License Plate No.: V681-34 Jurisdiction of Issue: A.B.  
 Type of Vehicle: ☐ School Bus ☐ Commercial Bus ☐ Motorcoach  
☐ Light Truck ☐ Truck/Tractor ☒ Trailer/Converter

Items in Red require measurements to be documented.

		LEFT	FRONT	RIGHT		
<div>18 100 m.m. PSI</div>	<div>18 100 m.m. PSI</div>	<div>1 1/2" 1 1/2" 90°</div>	DRUMS/ROTORS LININGS/PADS PUSH ROD TRAVEL CAM ROTATION	<div>1 1/2" 1 1/2" 90°</div>	<div>18 100 m.m. PSI</div>	<div>18 100 m.m. PSI</div>
<div>14 100 m.m. PSI</div>	<div>13 100 m.m. PSI</div>	<div>1 1/2" 1 1/2" 90°</div>	DRUMS/ROTORS LININGS/PADS PUSH ROD TRAVEL CAM ROTATION	<div>1 1/2" 1 5/8" 90°</div>	<div>13 100 m.m. PSI</div>	<div>12 100 m.m. PSI</div>
<div>18 100 m.m. PSI</div>	<div>17 100 m.m. PSI</div>	<div>1 1/2" 1 3/8" 90°</div>	DRUMS/ROTORS LININGS/PADS PUSH ROD TRAVEL CAM ROTATION	<div>1 1/2" 1 3/8" 90°</div>	<div>17 100 m.m. PSI</div>	<div>19 100 m.m. PSI</div>
<div>14 100 m.m. PSI</div>	<div>13 100 m.m. PSI</div>	<div>1 1/2" 1 1/2" 90°</div>	DRUMS/ROTORS LININGS/PADS PUSH ROD TRAVEL CAM ROTATION	<div>1 1/2" 1 1/2" 90°</div>	<div>13 100 m.m. PSI</div>	<div>15 100 m.m. PSI</div>

☒ Wheel Torque Checked ( 450 lbs)

Inspection Technician Comments (if applicable, write the section number and sub-section letter from the second page)

loosen slack pins - Adjust front brakes  
40,000k since last inspection

Inspection Date: 20100426 Time: 11:00 am pm Inspection Passed? Yes / No  
 Certificate Issued? Yes / No Certificate No.: CU1924252 Certificate Issue Date: 2010-4-26  
 Inspection Facility Name: Dandy oil Facility No.: 15565  
 Inspection Technician Name: Dave Burnett Technician No.: A1485  
 Inspection Technician Signature: [Signature]

☐ Vehicle was returned to the Registered Owner without repairs completed.

page 1 of 2



## OK REPAIR

- Handwritten text: NA

☒ ☐

- [illegible]

☐ ☐

- 
- N D

22

- [illegible]

☐ ☐

- Handwritten signature: *[Signature]*

☒

- 


OK REPAIR

- 
- A handwriting practice sheet for the letter 's'. The sheet is divided into two main sections by a vertical line. The left section contains a grid of 10 rows, each with a large 's' and a smaller 's' for tracing. The right section contains 10 rows of blank space for independent practice. The letter 's' is written in a cursive style, starting with a blue dot and following a curved path. The grid lines are blue, and the letter 's' is also blue.

☒

- 
- A grid of 10 squares (2 columns by 5 rows) with handwritten checkmarks. The first column has 5 checkmarks, and the second column has 5 checkmarks. To the right of the grid are five horizontal lines for writing.


☐ ☒

- 

☐ ☐

- [illegible]



- 
- olly