

## 120 Multi-Point Vehicle Inspection

### Vehicle Information

|                          |                            |
|--------------------------|----------------------------|
| Date/Time:               | 02-09-2024                 |
| Vehicle year/make/model: | 2014 Ford Fusion SE Hybrid |
| VIN:                     | 3FA6P0LU4ER153210          |
| Mileage:                 | 210712                     |
| License Plate:           | N/a                        |
| RO-Customer:             | 4106-Baba                  |
| Technician:              | Marc                       |

### Pre-Inspection Visual Walk Around

|                  |                                   |
|------------------|-----------------------------------|
| Vehicle Pictures |                                   |
| Vehicle Video    | <a href="#">Click to Download</a> |

### Interior/Exterior

|                                  |                                                                                                                                                                                                                                                                                                   |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Instrument Warning Lights        | Good                                                                                                                                                                                                                                                                                              |
| Single Photo                     |                                                                                                                                                                                                                                                                                                   |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| Horn Operation                   | Good                                                                                                                                                                                                                                                                                              |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| Headlight Dimmer Operation       | Good                                                                                                                                                                                                                                                                                              |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| Signal Light Switch              | Good                                                                                                                                                                                                                                                                                              |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| Hazard Light Operation           | Good                                                                                                                                                                                                                                                                                              |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| Park Brake Operation             | Good                                                                                                                                                                                                                                                                                              |
| Multi Photo                      |                                                                                                                                                                                                                                                                                                   |
| Notes                            |                                                                                                                                                                                                                                                                                                   |
| HVAC Operation                   | Advise                                                                                                                                                                                                                                                                                            |
| Notes                            | Airflow through the passenger vents is low and the temperature is not changing correctly to match the passenger side. With a/c on, drivers vent temp is at 60 degrees f. Passenger vent temp is at 42 degrees f. When set to full hot, the vent airflow is equal and vent temperatures are equal. |
| Heater Vent Temp & A/C Vent Temp | 140 degrees f max heat, 42 degrees f a/c on                                                                                                                                                                                                                                                       |
| Cabin Air Filter                 | Advise                                                                                                                                                                                                                                                                                            |
| Multi Photo                      |                                                                                                                                                                                                                                                                                                   |


## 120 Multi-Point Vehicle Inspection

|                                      |                                                                                         |
|--------------------------------------|-----------------------------------------------------------------------------------------|
| Notes                                | Requires glove box disassembly to inspect. Suggest replacement if attempting to inspect |
| Audio Controls                       | Good                                                                                    |
| Notes                                |                                                                                         |
| Interior Lights                      | Good                                                                                    |
| Notes                                |                                                                                         |
| Power/Manual Mirror Operation        | Good                                                                                    |
| Notes                                |                                                                                         |
| Power/Manual Window Operation        | Good                                                                                    |
| Notes                                |                                                                                         |
| Power/Manual Lock Operation          | Good                                                                                    |
| Notes                                |                                                                                         |
| Power/Manual Seat Operation          | Good                                                                                    |
| Notes                                |                                                                                         |
| Sunroof                              | Good                                                                                    |
| Notes                                |                                                                                         |
| Steering Column                      | Good                                                                                    |
| Notes                                |                                                                                         |
| Seat Belts & Buckle Operation        | Good                                                                                    |
| Notes                                |                                                                                         |
| Sun Visors                           | Good                                                                                    |
| Notes                                |                                                                                         |
| Windshield Wipers                    | Good                                                                                    |
| Notes                                |                                                                                         |
| Windshield/Glass Condition           | Good                                                                                    |
| Notes                                |                                                                                         |
| Windshield Wiper Nozzles/Washer Pump | Good                                                                                    |
| Notes                                |                                                                                         |
| Windshield Drainage                  | Good                                                                                    |
| Notes                                |                                                                                         |
| Exterior Lights/Housings             | Advise                                                                                  |
| Notes                                | License plate lights inoperative                                                        |
| Door and Door Handle Operation       | Good                                                                                    |
| Notes                                |                                                                                         |

## 120 Multi-Point Vehicle Inspection

|                         |      |
|-------------------------|------|
| Trunk/Liftgate/Tailgate | Good |
| Notes                   |      |
| Trailer Plug Operation  | N/A  |
| Notes                   |      |
| Hood Release            | Good |
| Notes                   |      |

### Under Hood

|                                        |                                                                                     |
|----------------------------------------|-------------------------------------------------------------------------------------|
| Hood Shocks/Prop                       | Good                                                                                |
| Notes                                  |                                                                                     |
| Engine Oil Level & Condition           | Good                                                                                |
| Notes                                  |                                                                                     |
| Engine Area Fluid Leaks                | Advise                                                                              |
| Multi Photo                            |  |
| Notes                                  | Minor oil leaks on engine                                                           |
| Engine Area Cleanliness                | Good                                                                                |
| Multi Photo                            |                                                                                     |
| Notes                                  |                                                                                     |
| Coolant Level & Condition              | Good                                                                                |
| Notes                                  |                                                                                     |
| Transmission Level & Condition         | Advise                                                                              |
| Notes                                  | Fluid condition suspect. ATF leak under transmission                                |
| Clutch Fluid Level & Condition         | N/A                                                                                 |
| Notes                                  |                                                                                     |
| Power Steering Fluid Level & Condition | N/A                                                                                 |
| Notes                                  |                                                                                     |
| Brake Fluid Level & Condition          | Good                                                                                |
| Notes                                  |                                                                                     |

## 120 Multi-Point Vehicle Inspection

|                                     |                                                                                     |
|-------------------------------------|-------------------------------------------------------------------------------------|
| Brake Master Cylinder               | Good                                                                                |
| Notes                               |                                                                                     |
| Accessory Belt Condition            | N/A                                                                                 |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Accessory Belt Tensioner & Pulleys  | N/A                                                                                 |
| Notes                               |                                                                                     |
| Engine Air Filter                   | Advise                                                                              |
| Multi Photo                         |                                                                                     |
| Notes                               | Dirty                                                                               |
| Timing Belt                         | N/A                                                                                 |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Battery                             | Advise                                                                              |
| Multi Photo                         |                                                                                     |
| Notes                               | Battery was dead on arrival. Boosted vehicle. Battery cannot be tested at this time |
| Battery Test Results                |                                                                                     |
| Battery Terminals/Cables & Mounting | Good                                                                                |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Alternator & Starter Operation      | N/A                                                                                 |
| Notes                               |                                                                                     |
| Radiator & Hoses                    | Good                                                                                |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Radiator/AC Cooling Fan             | Good                                                                                |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Water Pump & Fan Clutch             | N/A                                                                                 |
| Multi Photo                         |                                                                                     |
| Notes                               |                                                                                     |
| Coolant Reservoir & Heater Hoses    | Good                                                                                |
| Multi Photo                         |                                                                                     |

## 120 Multi-Point Vehicle Inspection

|                  |      |
|------------------|------|
| Notes            |      |
| AC Components    | Good |
| Notes            |      |
| Oil Cooler Lines | N/A  |
| Multi Photo      |      |
| Notes            |      |
| Engine Mounts    | Good |
| Multi Photo      |      |
| Notes            |      |

### Wheels, Tires & Brakes

|                                   |        |
|-----------------------------------|--------|
| Rim/Wheel Condition               | Good   |
| Multi Photo                       |        |
| Notes                             |        |
| Tire Pressure - Front Left (psi)  | 35     |
| Tire Pressure - Front Right (psi) | 35     |
| Tire Pressure - Rear Right (psi)  | 35     |
| Tire Pressure - Rear Left (psi)   | 35     |
| Tire Tread Condition              | Advise |
| Tire Tread - Front Left (mm)      | 1      |
| Tire Tread - Front Right (mm)     | 1      |
| Tire Tread - Rear Right (mm)      | 2      |
| Tire Tread - Rear Left (mm)       | 2      |
| Spare Tire Condition & Pressure   | N/A    |
| Multi Photo                       |        |
| Notes                             |        |
| Lug Nuts/Bolts                    | Good   |
| Multi Photo                       |        |
| Notes                             |        |
| Front Brake Pads                  | Good   |
| Multi Photo                       |        |
| Notes                             |        |
| Front Brake Rotors                | Advise |

## 120 Multi-Point Vehicle Inspection

|                                       |                                                                                     |  |
|---------------------------------------|-------------------------------------------------------------------------------------|--|
| Multi Photo                           |    |  |
| Notes                                 | Rotor surface rusted from sitting for an extended period                            |  |
| Front Brake Calipers/Sliders/Hardware | Good                                                                                |  |
| Multi Photo                           |                                                                                     |  |
| Notes                                 |                                                                                     |  |
| Front Brake Hoses                     | Good                                                                                |  |
| Multi Photo                           |                                                                                     |  |
| Notes                                 |                                                                                     |  |
| Rear Brake Pads or Shoes              | Good                                                                                |  |
| Multi Photo                           |                                                                                     |  |
| Notes                                 |                                                                                     |  |
| Rear Brake Rotors or Drums            | Advise                                                                              |  |
| Multi Photo                           |  |  |
| Notes                                 | Surface rusted from sitting for an extended period of time                          |  |
| Rear Brake Calipers/Sliders/Hardware  | Good                                                                                |  |
| Multi Photo                           |                                                                                     |  |
| Notes                                 |                                                                                     |  |
| Rear Brake Hoses                      | Good                                                                                |  |
| Multi Photo                           |                                                                                     |  |

## 120 Multi-Point Vehicle Inspection

|                                  |      |
|----------------------------------|------|
| Notes                            |      |
| Brake Lines                      | Good |
| Multi Photo                      |      |
| Notes                            |      |
| Wheel Cylinders                  | N/A  |
| Multi Photo                      |      |
| Notes                            |      |
| Park Brake Components            | Good |
| Multi Photo                      |      |
| Notes                            |      |
| Brake Booster (Vacuum/Hydraulic) | Good |
| Multi Photo                      |      |
| Notes                            |      |

## Steering & Suspension

|                           |      |
|---------------------------|------|
| Power Steering Pump/Motor | Good |
| Multi Photo               |      |
| Notes                     |      |
| Power Steering Hose       | N/A  |
| Multi Photo               |      |
| Notes                     |      |
| Steering Gear/Rack        | Good |
| Multi Photo               |      |
| Notes                     |      |
| Steering Shaft            | Good |
| Multi Photo               |      |
| Notes                     |      |
| Tie Rod Inner & Outer     | Good |
| Multi Photo               |      |
| Notes                     |      |
| Steering Shock            | N/A  |
| Multi Photo               |      |
| Notes                     |      |
| Pitman Arm/Idler Arm      | N/A  |
| Multi Photo               |      |


## 120 Multi-Point Vehicle Inspection

|                               |                                      |
|-------------------------------|--------------------------------------|
| Notes                         |                                      |
| Centre Link/Drag Link         | N/A                                  |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Front Struts/Shocks           | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Front Spring/Torsion Bar      | N/A                                  |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Front Control Arms & Bushings | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Rear Struts/Shocks            | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Rear Spring/Leaf              | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Rear Control Arms & Bushings  | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Stabilizer Links & Bushings   | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |
| Ball Joints                   | Safety                               |
| Multi Photo                   |                                      |
| Notes                         | Left front lower ball joint has play |
| Wheel Bearings/Hub Assembly   | Good                                 |
| Multi Photo                   |                                      |
| Notes                         |                                      |

## Transmission, Driveline & Axles

|                     |      |
|---------------------|------|
| Transmission Mounts | Good |
| Multi Photo         |      |

## 120 Multi-Point Vehicle Inspection

|                                          |                                                                                     |
|------------------------------------------|-------------------------------------------------------------------------------------|
| Notes                                    |                                                                                     |
| Transmission Cooler Lines                | Good                                                                                |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Transmission Gaskets/Seals               | Good                                                                                |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Drive Shaft Universal Joints             | N/A                                                                                 |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Drive shaft Center Bearing/Support       | N/A                                                                                 |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Drive Axles                              | Good                                                                                |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Axle Seals                               | Advise                                                                              |
| Multi Photo                              |  |
| Notes                                    | Left axle seal is leaking atf                                                       |
| CV Axle Boots                            | Good                                                                                |
| Multi Photo                              |                                                                                     |
| Notes                                    |                                                                                     |
| Front Differential Oil Level & Condition | N/A                                                                                 |
| Notes                                    |                                                                                     |
| Transfer Case Oil Level & Condition      | N/A                                                                                 |
| Notes                                    |                                                                                     |

## 120 Multi-Point Vehicle Inspection

|                                         |     |
|-----------------------------------------|-----|
| Rear Differential Oil Level & Condition | N/A |
| Notes                                   |     |

### Fuel Tank & Exhaust System

|                        |      |
|------------------------|------|
| Fuel Tank              | Good |
| Multi Photo            |      |
| Notes                  |      |
| Fuel Cap/Filler Neck   | Good |
| Multi Photo            |      |
| Notes                  |      |
| Fuel Tank Straps       | Good |
| Multi Photo            |      |
| Notes                  |      |
| Fuel Lines             | Good |
| Multi Photo            |      |
| Notes                  |      |
| Exhaust Manifold(s)    | Good |
| Notes                  |      |
| Catalytic Converter(s) | Good |
| Multi Photo            |      |
| Notes                  |      |
| Turbo Charger          | N/A  |
| Notes                  |      |
| Flex Joint(s)          | Good |
| Multi Photo            |      |
| Notes                  |      |
| Exhaust Hangers        | Good |
| Notes                  |      |
| Muffler                | Good |
| Multi Photo            |      |
| Notes                  |      |

### Accessories

|              |                                             |
|--------------|---------------------------------------------|
| Remote Start | Advise                                      |
| Notes        | Aftermarket remote start remote inoperative |

## 120 Multi-Point Vehicle Inspection

|                     |      |
|---------------------|------|
| Block Heater        | Good |
| Notes               |      |
| Rear Defrost        | Good |
| Notes               |      |
| Cruise Control      | Good |
| Notes               |      |
| Heated/Cooled Seats | N/A  |
| Notes               |      |
| Reverse Camera      | Good |
| Notes               |      |
| Park Assist         | Good |
| Notes               |      |