

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information																	
VIN	W	B	A	V	B	5	3	5	2	6	K	W	2	9	1	9	2
Make BMW				Model 323i				Year 2006				Odometer 102572					
Customer Information																	
Organization Name																	
Address														Postal Code			
Section 1 - Pre-Inspection																	
Component		P	F	NA	Component		P	F	NA								
1.1a. Request for Inspection (RFI)		✓			1.3c. Vehicle Wanders or Pulls		✓										
1.1b. Vehicle Accurately Described On The RFI		✓			1.3d. Brake System Performance		✓										
1.2a. VIN Plate Condition		✓			1.3e. Driveability		✓										
1.2b. VIN Consistent With RFI		✓			1.3f. Speedometer Operation		✓										
1.3a. CV Joint Road Test Result		✓			1.3g. Odometer (if equipped) Operation		✓										
1.3b. Universal Joint Road Test Result		✓															
NOTES:																	
Section 2 - Onboard Diagnostic Systems																	
Component		P	F	NA	Component		P	F	NA								
2.1a. PCM Codes Present		✓			2.4b. SRS Lamp Fails To Illuminate		✓										
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate		✓			2.4c. SRS Lamp Remains Illuminated		✓										
2.2a. ABS Codes Present		✓			2.4d. Airbag(s) Present		✓										
2.2b. ABS Lamp Fails To Illuminate		✓			2.4e. Airbag Cover Integrity		✓										
2.2c. ABS Lamp Remains Illuminated		✓			2.5. Electronic Stability Control (ESC)		✓										
2.3a. Brake System Warning Lamp Fails To Illuminate		✓			2.6. Powertrain Warning Lamps		✓										
2.3b. Brake System Warning Lamp Remains Illuminated		✓			2.7. Other Safety Systems		✓										
2.4a. SRS Codes Present		✓															
NOTES: all systems scanned okay at this time																	
Section 3 - Interior																	
Component		P	F	NA	Component		P	F	NA								
3.1. Doors		✓			3.11. Instrument Panel Lamps		✓										
3.2. Rear View Mirror		✓			3.12. HVAC		✓										
3.3. Sun Visors		✓			3.13. Windshield Wiper and Washer Operation		✓										
3.4. Horn		✓			3.14. Accelerator		✓										
3.5. Seats		✓			3.15. Service Brake Pedal		✓										
3.6. Seatbelts		✓			3.16. Clutch Pedal Assembly		✓										
3.7. Signal Lamp Switch and Indicator		✓			3.17. Park Brake		✓										
3.8. Hazard Lamps		✓			3.18. Neutral Safety Switch Operation		✓										
3.9. Headlamp Switch and High Beam Indicator		✓			3.19. Entertainment Display Lockout		✓										
3.10. Auxiliary Lamp Indicator(s)				✓													
NOTES:																	

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass						
Component	P	F	NA	Component	P	F NA
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓	
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓	
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓	
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓	
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓	

NOTES:

Section 5 - Lamps						
Component	P	F	NA	Component	P	F NA
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓	
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓	
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓	
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓	
5.5. Auxiliary Lamps			✓	5.11. Emergency Lighting	✓	
5.6. Front Side Marker Lamps	✓					

NOTES:

Section 6 - Exterior, General						
Component	P	F	NA	Component	P	F NA
6.1. Fuel Cap	✓			6.3. Bumpers	✓	
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation		✓

NOTES:

Section 7 - Under Hood						
Component	P	F	NA	Component	P	F NA
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder		✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓	
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓	
7.4. Battery	✓			7.10. Oil Leaks	✓	
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓	
7.6. Brake Master Cylinder	✓					

NOTES:

Section 8 - Steering and Suspension						
Component	P	F	NA	Component	P	F NA
8.1. Wheel Bearings	✓			8.8. Steering Gear	✓	
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓	
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓	
8.4. Pitman Arm			✓	8.11. Control Arms	✓	
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓	
8.6. Steering Stabilizer / Damper	✓			8.13. Springs	✓	
8.7. Steering Shaft Assembly	✓					

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF: 6.3 mm, RF: 6.9 mm, LR: 5.2 mm, RR: 5.8 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		
NOTES: B/S P205 55 r 16							
Section 10 - Brakes							
Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR: 160.0 mm, RR: 160.0 mm	✓		
10.2. Park Brake Lining- LR: 3.4 mm, RR: 3.6 mm	✓			10.6. Brake Rotor Thickness- LF: 24.3 mm, RF: 24.6 mm	✓		
10.2. Brake Lining- LF: 11.3 mm, RF: 11.0 mm, LR: 4.0 mm, RR: 4.5 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR: 19.5 mm, RR: 19.8 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						
NOTES:							
Section 11 - Under Vehicle							
Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		
NOTES:							
Certification The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.							
Date of Inspection 2024/06/21	Technician Number A8552		Facility Number 16055		Signature 		
Customer Acknowledgment I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.					Date (Year/Month/Day) Customer Signature 		