



Commercial Vehicle Inspection Report

Decal Number: GA71069
Decal Expiry Date: 2024-Dec-31
Inspection Number: 20749829

Inspection Result:
PASS

FACILITY:	FREIGHTLINER OF CRANBROOK LTD. / S20049	INSP. TYPE:	Complete	INSP. START:	2023-Dec-07 07:00 AM MST
INSPECTOR:	Hudson, Darrin Neil / 111245	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2023-Dec-07 08:00 AM MST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	02926685	VIN:	JLSCCH1S47K004594
PLATE #:	NK8218	UNIT/FLEET#:	408	OWNER/LESSEE NAME:	TITAN GMS GP, INC
LICENCED GVW(kg):	8000	BODY STYLE:	Flat Deck	ADDRESS:	7012 8 ST NE
VEHICLE YEAR:	2007	ODOMETER:	313796 KM		CALGARY, Alberta
MAKE:	STERLING	HUB ODOMETER:			T2E8L8, Canada
MODEL:		BRAKE TYPE:	Hydraulic		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed with Caution
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed with Caution
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

ADVISE AND MONITOR REAR SPRING EYE BUSHINGS, REAR SHACKLE BUSHINGS, STEER FRONT SPRING BUSHINGS.

ADVISE AND MONITOR STEER RH RIM DAMAGE

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	11.9			11.9	✓	Pad	10	10	Rotor	43.00	43.00
2	15.1	15.1	15.1	15.1		Pad	11	11	Rotor	38.00	38.00
Comment:						Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: Hudson, Darrin Neil Signature:

This Inspection Report was submitted to CVSE on 2023-Dec-07 10:46 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.