

CANADIAN FIRE #302

5200 Richmond Rd. SW
Calgary, AB T2E 6M9

403-246-1961

REG #: 4 07/12/2024 08:51:56 TRANS #: 9
OPERATOR #: 4233 Float: 001

==PARTS ORDER #: 10030200091859==
010-3501-6 MotoMaster MOT3 \$ 188.99
010-4700-6 MotoMaster MOT4 \$ 200.99
==END OF ORDER #: 10030200091859==

SUBTOTAL	\$	389.98
5% GST	\$	19.50
	\$	0.00
TOTAL	\$	409.48
M/C TEND	\$	409.48

MASTERCARD PURCHASE
MASTERCARD #: *****1294

CHIP CARD

2024/07/12 08:52:29

REFERENCE: 0010010011 C

AUTHORIZATION: 06905Z

A0000000041319

MASTERCARD

0000008000E800

01 APPROVED - THANK YOU 02/

IMPORTANT

Retain this copy for your records

You could have collected \$15.60 in
CT Money with a Triangle Mastercard.
Cardmembers get 4% in CT Money at
Canadian Tire and 5 cents back per litre
in CT Money on regular gas at
participating gas locations.
*Calculated pre-tax. Terms & Conditions
apply. Visit Triangle.com for details.

CUSTOMER COPY

Visit canadiantire.ca or download the
Canadian Tire Mobile App today!

Take our survey each month for a chance
to win a \$1000 Canadian Tire gift card.
No purchase necessary. Conditions apply.
Visit tellcantire.com and enter code:

4719-2030-00200-19836



0030224071244983000000010009

New Buttery

VOID
has updated

Alberta Government

K104C

PR5519953



80081700005519953

CERTIFICATE NUMBER

**Out of Province Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Automotive	Seating Capacity:	
GVW:		Brake Type:	Hydraulic
Owner Name:	[REDACTED]		
Address:	[REDACTED]		
City:	[REDACTED]	Province:	AB
		Postal Code:	[REDACTED]
Telephone Number:	[REDACTED]		
Vehicle Identification Number:	JN8AS5MVXAW136172		
Make:	Nissan	Model:	Rogue
Year:	2010	Unit Number:	
Odometer:	139098 KM	Licence Plate Number:	ED842R
		Province:	BC

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Out of Province Vehicle.

Inspection Facility Name:	Facility Number:
Ryanco Automotive Inc.	13443
Inspection Technician Name:	Technician Number:
Maynard Morrison	B6844
Inspection Technician Signature:	[Signature]
Inspection Date:	2021/10/27

NOTICE TO VEHICLE OWNER

1. This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information

VIN	J	N	8	A	S	5	M	V	X	A	W	1	3	6	1	7	2
Make Nissan				Model Rogue				Year 2010				Odometer 139098					

Customer Information

Last Name [REDACTED]								First Name [REDACTED]							
Address [REDACTED]												Postal Code [REDACTED]			

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result	✓			1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

pass inner cv boot split/ replaced

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present	✓			2.4b. SRS Lamp Fails To Illuminate	✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate	✓			2.4c. SRS Lamp Remains Illuminated	✓		
2.2a. ABS Codes Present	✓			2.4d. Airbag(s) Present	✓		
2.2b. ABS Lamp Fails to Illuminate	✓			2.4e. Airbag Cover Integrity	✓		
2.2c. ABS Lamp Remains Illuminated	✓			2.5. Electronic Stability Control (ESC)	✓		
2.3a. Brake System Warning Lamp Fails to Illuminate	✓			2.6. Powertrain Warning Lamps	✓		
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems	✓		
2.4a. SRS Codes Present	✓						

NOTES:

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly			✓
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout	✓		
3.10. Auxiliary Lamp Indicator(s)	✓						

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass

Component	P	F	NA	Component	P	F	NA
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓		
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓		
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓		
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓		
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓		

NOTES:

Section 5 - Lamps

Component	P	F	NA	Component	P	F	NA
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓		
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓		
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓		
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓		
5.5. Auxiliary Lamps	✓			5.11. Emergency Lighting	✓		
5.6. Front Side Marker Lamps	✓						

NOTES:

licence lights out/ replaced bulbs

Section 6 - Exterior, General

Component	P	F	NA	Component	P	F	NA
6.1. Fuel Cap	✓			6.3. Bumpers	✓		
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation	✓		

NOTES:

Section 7 - Under Hood

Component	P	F	NA	Component	P	F	NA
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder			✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓		
7.3. Remote Starter Operation	✓			7.9. Exhaust Manifold(s)	✓		
7.4. Battery	✓			7.10. Oil Leaks	✓		
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓		
7.6. Brake Master Cylinder	✓						

NOTES:

Section 8 - Steering and Suspension

Component	P	F	NA	Component	P	F	NA
8.1. Wheel Bearings	✓			8.8. Steering Gear	✓		
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓		
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓		
8.4. Pitman Arm			✓	8.11. Control Arms	✓		
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓		
8.6. Steering Stabilizer / Damper	✓			8.13. Springs	✓		
8.7. Steering Shaft Assembly	✓						

NOTES:

dr sway bar excessive play/replaced

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:4.5 mm,RF:4 mm,LR:5 mm,RR:4.5 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:

Section 10 - Brakes

Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:171.28 mm,RR:171.5 mm	✓		
10.2. Park Brake Lining- LR:3 mm,RR:3 mm	✓			10.6. Brake Rotor Thickness- LF:25.88 mm,RF:25.92 mm	✓		
10.2. Brake Lining- LF:8 mm,RF:8 mm,LR:4 mm,RR:4 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:15.1 mm,RR:15.16 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:

Section 11 - Under Vehicle

Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #5519953)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2021/10/27	Technician Number B6844	Facility Number 13443	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2021/10/27

Customer Signature