



Commercial Vehicle Inspection Report

Decal Number: GD33826
Decal Expiry Date: 2025-Jan-31
Inspection Number: 21004553

Inspection Result:
PASS

FACILITY:	ACCELERATED MECHANICAL LTD. / S16580	INSP. TYPE:	Complete	INSP. START:	2024-Jul-15 05:00 PM PDT		
INSPECTOR:	IRWIN, JOSHUA JAMES / 200836	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Jul-15 07:15 PM PDT		
WORK ORDER #:	6255	INSP. REASON:	Semi-annual				
VEHICLE JUR:	British Columbia	REGI:	03302976			VIN:	1HTMSAAR19H083728
PLATE #:		UNIT/FLEET#:	HD541			OWNER/LESSEE NAME:	SKELTER IMPORTS INC., DBA EXXEL TRUCK AND EQUIPMENT
PERMITTED GVW(kg):	22500	BODY STYLE:	Flat Deck			ADDRESS:	11445 KITCHEN ROAD, 11445 KITCHEN ROAD
VEHICLE YEAR:	2009	ODOMETER:	446373 KM			Chilliwack, British Columbia	
MAKE:	INTERNATNA	HUB ODOMETER:		V2P6H5, Canada			
MODEL:		BRAKE TYPE:	Air				
		FUEL TYPE:	Diesel				

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	38	39
2	Clamp	30L	Automatic	37	38
3	Clamp	30L	Automatic	39	38

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			13	✓
14	14	14	14	
14	14	14	14	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	60	60
3	60	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	16	16
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: IRWIN, JOSHUA JAMES

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Jul-16 08:23 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/16/2024 8:23:31 AM PDT