



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	22550 kg	Brake Type:	Air
Owner Name:	W. Parkers Transport		
Address:	5011 baysel ave		
City:	Swan hills	Province:	AB
		Postal Code:	T0G 2C0
Telephone Number:	(780) 333-2610		
Vehicle Identification Number:	M910854		
Make:	Kenworth	Model:	w900
Year:	1981	Unit Number:	117
Odometer:	941319 KM	Licence Plate Number:	J74318
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Geter Done Mechanical Ltd.	19789
Inspection Technician Name:	Technician Number:
Kendall Profit	C5053
Inspection Technician Signature:	<i>Kendall Profit</i> <i>Robert Parker</i>
Inspection Date:	2024/07/04