

ELU-Shi (Y-94) Cognight © 1985 The Reynolds and Reynolds Company (Canada) LTD、CC623694 Q (12/21)

PAGE 1 OF 2

CUSTOMER COPY

## **Kia West Edmonton**

A Division of 864475 Alberta Ltd.

10151 - 179 Street Edmonton, Alberta T5S 1P9 Tel: (780) 444-8645 Fax: (780) 444-3638

coolant 48,000

		a	0	INDEBTED	NESS IS HEI	REBY ACKNO	WLEDGED IN THE	SUM OF \$	BEING ALL	
			Ŭ	OF THE BY	ALANCE OWI	NG FOR BED	AIRS PARTS & A	CECCODIEC DECODIDED I	N THIS WORK ORDER.	
G S T VENDOE	NO. 87421 5726RT	ALL ITEMS ARE SUBJECT		DATE		SIGNATURE		UM) CHARGED ON PAST DU	JE ACCOUNTS.	
CUSTOMER NO.	110.07 121 572011	ALL TILING AIL GODGEG	ADVISOR	07.112		ITA	G NO.	INVOIGE DATE	INVOICE NO.	
			JUL TANA			855	3999 METRES	08/01/23	K1CS257395	
			1	1	NSE NO.	KILON	TETRES		STOCK NO.	
34	*	16g - 8	170.00 YEAR/MAKE/MOD	EL, J			204,858	SNOWWHITE P	DELIVERY KMS.	
		s c	12/KTA/	12/KTA/SORENTO/2.4L LX AWD			03/27/12			
								SELLING DEALER NO.	PRODUCTION DATE 65	
			5 X Y K	L C A	6 8 C	G 2 9	1821	R. O. DATE	IN SERVICE DATE	
		ru testic						06/30/23	03/27/12	
		PHONE COMMENTS .								
		MO: 24086	0							
LABOR & PARTS							We want			
J# 1 36K1Z ENG. ELECTR-BASE CODE TECH(S):1070 WARRANT COMPLAINT: CHECK AND ADVISE CUSTOMER STATES VEHICLE WAS							WARRANTY	you wry		
•	OPERATING AND VEHICLE STALLED AND WONT START AGAIN							1000/1		
CUSTOMER WAS NOTED BY OUTSIDE SHOP ENGINE WAS SEIZED CAUSE: INSPECTED AND FOUND THE ENGINE WAS SEIZED.								to be satisfied!		
CHECKED THE OIL LEVEL IS OK.									ina vour	
CODDECTIONS	FOUND THE STARTER BURNED OUT.								Thank you for having your vehicle serviced at	
CORRECTION:	CORRECTION: REPLACED ENGINE LONG BLOCK ASSY WITH SERVICE KIT. ROAD TEST AND RECHECK LEAK, NO LEAK. IS ALL NORMAL.							KIA West Edmonton		
								You may soon receive a		
PARTSQTYFP-NUMBERDESCRIPTIONLIST PRICE-UNIT PRICE-								Service Survey.		
JOB # 1	1 211112GK50QQ	OK SERVICI	KIT	F121 PR	TCE-UNIT	PRICE-	WARRANTY		25	
JOB # 1		1 . 211112GK70QQK SERVICE KIT . WARRANTY							If you are unable to respond "Very Satisfied" to the	
JOB # 1 JOB # 1		1 - 392502G100 SENSOR ASSY-KNO WARRANTY 1 254702G050QQK TUBE ASSY-OIL C- WARRANTY								
JOB # 1	1 2151323001	1 2151323001 GASKET-OIL PLUG WARRANTY							following questions, please tell	
JOB # 1 JOB # 1		5 CAMAGSW30BULK ,GTX MAGNATEC SA WARRANTY							us why, so we may serve you better.	
JOB # 1								beller.		
70D # 4	RC109 12-13	2.4 GDI SORENTO					WARRANTI		$\odot$	
JOB # 1 JOB # 1	1 7 3331125050 POLT POTUS OLATS							How satisfied were Very		
_		IN, FULL SYNTH C	IL PLAIL				WARRANTY	you with:	Satisfied	
	177			JOB #	1 TOTAL	PARTS	0.00	Your overall service	9 🕜	
		* X	JOB #	1 TOTAL	LABOR &	PARTS	0.00	experience?		
								The treatment received		
J# 2 11K1ZZO09-APLUS DIAG MIN CHARGE TECH(S):1070 0.00  COMPLAINT: DIAGNOSES MINIMUM CHARGE INCLUDING NO FAULT FOUND								The treatment received from staff?		
	OVER 1 YEAR OR 2000	OKM	NO THOSE TO	SHD					_	
CORRECTION:	FROM \$85 TO \$170							The service staff lis		
	•	0.5	45	·		21	ÿ.	to and understandi	ng 🕴 🅢	
PARTSQ	TYFP-NUMBER	DESCRIP	TION					your needs?	_	
				JOB #	2 TOTAL	PARTS	0.00	The quality of work		
15			JOB #	2 TOTAL	LABOR &	PARTS	0.00	performed?		
7# 3 10K1222	NO DECALLO	CONTRACTOR STATE SECURITION OF						Vour vohiolo roody	whon o	
J#-3 10K1ZZ22 NO RECALLS: TECH(S):1070 0.00								Your vehicle ready when promised?		
CAUSE:								promiseu:		
CORRECTION:	NO RECALLS							Please call (78	0) 444-8645	
PARTSQTYFP-NUMBERDESCRIPTIONLIST PRICE-UNIT PRICE-								Please call (780) 444-8645 And ask for our		
				JOB #	3 TOTAL	PARTS	0.00	Service M		
			JOB #	3 TOTAL	LAROR &	PARTS	0.00	501 1100 [1]		
J# 4+36K1ZZO5 MISC.ELECTRICAL TECH(S):1070 0.00 COMPLAINT: DRIVE BELTS										
	INSTALLED NEW BELT.						125/1			
					7					

[CONTINUED ON NEXT PAGE] 09:53am



## **Kia West Edmonton**

A Division of 864475 Alberta Ltd

10151 - 179 Street Edmonton, Alberta T5S 1P9 Tel: (780) 444-8645 Fax: (780) 444-3638

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_\_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER. SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) CHARGED ON PAST DUE ACCOUNTS. T G.S.T. VENDOR NO. 87421 5726RT ALL ITEMS ARE SUBJECT TO G.S.T. SIGNATURE 🗸 TAG NO. INVOICE DATE SI 3999 JULIANA LABOUR RATE 08/01/23 K1CS257395 204,858 SNOWWHITE DELIVERY KMS. /KIA/SORENTO/2.4L LX AWD 03/27/12 SELLING DEALER NO. PRODUCTION DATE R. O. DATE IN SERVICE DATE 06/30/23 03/27/12 COMMENTS MO: 240860 PARTS-----QTY---FP-NUMBER-------DESCRIPTION------LIST PRICE-UNIT PRICE-We want JOB # 4 1 252122G750 V-RIBBED BELT 84.99 84.99 84.99 JOB # 4 TOTAL PARTS 84.99 to be satisfied! JOB # 4 TOTAL LABOR & PARTS 84.99 J# 5+50K1Z CHASSIS-BASE CODE TECH(S):1070 WARRANTY Thank you for having your COMPLAINT: STARTER vehicle serviced at CORRECTION: REPLACED STARTER MOTOR ASSY. **KIA West Edmonton** PARTS-----QTY---FP-NUMBER------DESCRIPTION-----LIST PRICE-UNIT PRICE-You may soon receive a 2630035505 FILTER ASSY-ENG WARRANTY Service Survey. JOB # 5 TOTAL PARTS 0.00 If you are unable to respond JOB # 5 TOTAL LABOR & PARTS 0.00 "Very Satisfied" to the following questions, please tell TAX SUMMARY----us why, so we may serve you **GST** 4.25 Rbetter. TOTAL S-----TOTAL LABOR.... How satisfied were Very TOTAL PARTS.... 84.99 D/CARD [] CASH [ ] TOTAL SUBLET... 0.00 you with: Satisfied TOTAL G.O.G.... 0.00 Your overall service M/CARD [ ] VISA [] TOTAL MISC CHG. 0.00 experience? TOTAL MISC DISC 0.00 CHEQUE [ ] CHARGE [ ] TOTAL TAX..... 4.25 The treatment received OTHER [ ] **TOTAL INVOICE \$** from staff? 89.24 SHOP SUPPLY FEES ATE 12.5% OF LABOUR. MAX SHOP FEE OF \$100 The service staff listening \*CUSTOMERS MUST RETURN WITHIN 100KM TO HAVE WHEELS RETORQUED to and understanding IF VEHICLE COMES INTO SERVICE DIRTY, THE SMALL SCRATCHES &DAMAGE ON CAR MAY NOT BE VISIBLE AT TIME OF WALK AROUND. your needs? IF WE WASH THE CAR, THE MIGHT APPEAR AFTER THE WASH. The quality of work performed? CUSTOMER SIGNATURE Your vehicle ready when promised? Please call (780) 444-8645 And ask for our Service Manager

ELC-SIT (9-90) Copyright @

CC623694 Q (12/21