



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck			Seating Capacity:		/:					
GVW:		63500 kg			Brake Type:			Air				
Owner Name:		1709590 ALBERTA LTD)			-				_
Address:	32 F	2 PLEASANT RANGE PL										
City:	RO	ROCKYVIEW			rovince:	ovince: AB			Postal Code: T1Z0H2			
Telephone	Num	ber:	(403) 33	3-9037				1 0				_
Vehicle Ide	ntific	ation Nu	mber:		1NKDX40	X07R9	9908	30	N.			_
Make:	ke: Kenworth					Model: Construct						
Year:	2007						Unit Number:			102		
Odometer: 869205 KM Li		Licen	icence Plate Number:			: 04P769		Province	: AE	== 3		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:			
RPM Trailer Repair Service	Ltd.	15327			
Inspection Technician Nam	e:	Technician Number:			
Shri Naidu		B1965			
Inspection Technician Sign	ature:	Aller by			
Inspection Date:	2023/11/21	1			