

unit	Amount Ct Occurred On	Task title	Description
419421	13659.17	6/21/2018 16:02 Yearly Cvip Tractor Wet Kit	CVIP AND REPAIRS(419421)
419421	3711.37	9/15/2018 17:09 PRORATE RENEWAL	PRORATE RENEWAL
419421	3426.90	10/21/2018 9:09 OIL LEAK AT FUEL PUMP - CUMMINS	oil leak @ fuel pump(419421)
419421	33760.62	3/12/2019 REGEN ISSUES - CUMMINS	
419421	33760.62	4/2/2019 9:30 REGEN ISSUES - CUMMINS	REGEN ISSUES - TURBO FAIL - DPF BREACH(419421)

over 55,000
since 2018

-not including
paint + SS CVIP.

Camshaft +

oil pump

main + rod bearings

new oil cooler

egr + turbo rebuild

Turbo actuator

~~one~~ Cat modules

+W/O

particulate filters

rockers replaced.

Complete paint job on truck

105,696 Km

64,051 Km
2125 HRS

419421	Transmission output seal leaking	Normal	2/10/2020 8:25
419421	CHECK TILT STEERING	Normal	2/2/2020 14:26
419421	BENT FENDER BRACKET / HOLE IN P/S	Normal	2/2/2020 14:25
419421	BLOWN AIRBAG D.S	Normal	2/2/2020 14:22
419421	air leak in cab	Normal	2/7/2020 11:32
419421	air leak at leveling valve	Normal	2/7/2020 10:11
419421	ABS light on	Normal	2/7/2020 14:36
419421	air leak under hood	Normal	2/7/2020 17:30
419421	#1 drive axle airbag needs replacing	Normal	2/7/2020 17:29
419421	brakes out of adjustment	Normal	2/7/2020 17:28
419421	steady bearing and #1 diff ujoint need replacing	Normal	2/7/2020 17:28
419421	TOW FROM GUESS INN EDSON TO HINTON	3rd Party	1/27/2020 15:55
419421	AFTER TREATMENT FAULTS, REPAIR WIRING	Normal	1/24/2020 12:05
419421	REPLACE WINDSHIELD	Normal	1/16/2020 12:15
419421	replace brake pot air line lhs steer axel. rotted	Normal	2/2/2020 12:04
419421	passenger side rear fender has hole from chain damage	Normal	2/2/2020 7:48
419421	large crack in passenger side windshield	Normal	2/2/2020 7:47
419421	blown air bag LHS 3rd drive axle	Normal	2/2/2020 7:46
419421	leakingf axle seal	Normal	11/19/2019 17:50
419421	CRACKED FOG LIGHT	Normal	11/20/2019 9:06
419421	DAMAGED BUMPER / REPLACE	Normal	11/21/2019 11:41
419421	Axle seal leak	Normal	11/15/2019 10:48
419421	LEAKING ANTI FREEZE	Normal	11/7/2019 7:39
419421	ABS LIGHT ON	Normal	11/7/2019 7:37
419421	DAMAGED SPRING	Normal	9/15/2019 16:50
419421	DAMAGED BUMPER BRACKET	Normal	9/15/2019 16:51
419421	FUEL GUAGE NOT WORKING	Normal	9/15/2019 16:51
419421	BLOWER PLUMBING	Normal	9/15/2019 16:52
419421	missing muffler bushing	Normal	11/10/2019 8:55
419421	CHECK LIGHTING	Normal	8/31/2019 6:45
419421	CHECK BATTERIES	Normal	8/31/2019 6:45
419421	CHECK OVER	Normal	8/31/2019 6:46
419421	CHECK RADIO - BLOWING FUSES	Normal	8/14/2019 15:39
419421	OUTSIDE GASKET LEAK - FIRST AXLE P/S	Normal	8/14/2019 14:35

419421	CHECK FUEL GAUGE	Normal	8/12/2019 9:43
419421	ENGINE FAN - WONT SHUT DOWN	Normal	7/29/2019 8:15
419421	Wheel Retorque	Field/Yard	7/3/2019 11:37
419421	LEAKING ABS VALVE	Normal	6/22/2019 16:28
419421	CHECK CAB AIR BAG	Normal	6/14/2019 8:21
419421	BLOWN AIR BAG	Normal	6/2/2019 10:49
419421	Spring Unit Inspection	Normal	5/23/2019 10:44
419421	REPLACE U-JOINTS	Normal	5/23/2019 12:53
419421	REPAIR CHAIN RACK	Normal	5/23/2019 12:53
419421	REPAIR AIR LEAK	Normal	5/23/2019 12:55
419421	REPLACE HYDRAULIC COUPLER	Normal	5/23/2019 12:55
419421	REPLACE FUEL LINE	Normal	5/24/2019 11:38
419418	PROWEST - AC SERVICE	Normal	5/22/2019 17:07
419421	SPRING PINS	Normal	6/27/2019 8:08
419421	LH FOG LAMP	Normal	6/27/2019 8:09
419421	RHR FENDER	Normal	6/27/2019 8:09
419421	#2A INPUT UJOINT	Normal	6/27/2019 8:10
419421	#2LRH UJOINT	Normal	6/27/2019 8:11
419421	REPLACE BATTERIES	Normal	6/27/2019 8:12
419421	REPAIR P/S WINDSHIELD	Normal	4/3/2019 9:25
419421	REPAIR P/S DASH	Normal	4/3/2019 9:25
419421	ENGINE LIGHT CAME ON - TOLD TO PARK UNIT	Normal	3/6/2019 11:37
419421	REGEN ISSUES - CUMMINS	Normal	3/12/2019 9:04
419421	PINION SEAL	MIDDLE DI	1/29/2019 15:22
419421	`CHECK ABS	Normal	1/29/2019 15:23
419421	CHECK P/S HEADLIGHT FOR INTERMITTENT FUNCTION	Normal	1/30/2019 12:32
419421	DRIVING LIGHTS N/W	Normal	1/30/2019 15:02
419421	CHECK LIGHTING	Normal	1/21/2019 9:07
419421	INSPECT TRANSMISSION	Normal	1/2/2019 16:56
419421	REPLACE WINDSHIELD	Normal	12/15/2018 14:48
419421	CHECK ENGINE LIGHT	Normal	12/15/2018 14:48
419421	ABS LIGHT	Normal	12/15/2018 14:49
419421	REPLACE BRAKE POT	Normal	12/2/2018 8:52
419421	CHECK LIGHTS	Normal	12/2/2018 8:53

419421	CHECK P/S HIGH BEAM	Normal	11/29/2018 11:48
419421	ABS ISSUES	Normal	11/5/2018 15:19
419421	CHECK A/C PUMP - PRO-WEST	BROKEN	10/26/2018 11:08
419421	CHECK ENGINE BREATHER SENSOR	Normal	10/26/2018 11:09
419421	CHECK ENGINE WIRING	Normal	10/26/2018 11:09
419421	REPLACE MUDDLAPS	Normal	10/28/2018 17:01
419421	BROKEN SENSOR ON SIDE OF MOTOR	Normal	10/26/2018 16:00
419421	REPLACE P/S DUST SHIELD	Normal	11/2/2018 14:13
419421	CHECK LIGHTS	Normal	11/2/2018 14:13
419421	TILT STEERING BROKEN	Normal	11/25/2018 12:05
419421	OIL LEAK AT FUEL PUMP - CUMMINS	Normal	10/21/2018 9:07
419421	HYDRAULIC FAN ALWAYS ON	Normal	9/28/2018 11:28
419421	FAN BLOWS HOT AIR ALL THE TIME	Normal	9/28/2018 11:28
419421	BROKEN ENGINE FAN	Normal	9/28/2018 11:27
419421	Install MSB-2018-013 PIC Decals	New PIC (P ZZSafety/D	9/21/2018 10:06
419421	ENGINE OIL LEAK - CUMMINS	Normal	9/10/2018 12:34
419421	NO BACK UP ALARM	Normal	9/10/2018 12:33
419421	COOLANT LEAK	Normal	9/9/2018 11:14
419421	ACCESSORY LIGHTS ON FRONT FENDER	NOT WORK	9/9/2018 11:13
419421	NEEDS MUD FLAPS	Normal	9/9/2018 11:13
419421	ENGINE OIL LEAK	Normal	9/9/2018 11:12
419421	ABS WARNING ON DASH	Normal	8/8/2018 8:43
419421	CUSHION, SEAT BOTTOM GPC EAST PARTS LAYAWAY SHELF	Normal	8/4/2018 15:42
419421	ENGINE OIL LEAK	Normal	4/17/2018 15:41
419421	REPAIR GROUND CABLE ON FRAME	Normal	10/1/2018 16:38
419421	RUN TEST/SERVICE WEBASTO FOR WINTER	Normal	10/1/2018 16:38
419421	LOAD TEST AND CLEAN BATTERY CONNECTIONS	Normal	10/1/2018 16:39
419421	REPAIR STEP	Normal	10/24/2018 11:26
419421	CHECK BRAKE PEDAL	Normal	10/24/2018 11:30
419421	Fall Frac Tractor Inspection	PM	8/1/2018 16:33
419421	CHECK OIL LEAK ON COOLER FAN	Normal	7/31/2018 7:47
419421	CHECK WINDSHIELD	Normal	7/23/2018 10:45
419421	CHECK DRIVER SEAT	UNCOMFO	7/4/2018 10:03
419421	CHECK FOR AN AIR LEAK	BEHIND CA	5/24/2018 8:31

419421	ADJUST CLUTCH	Normal	5/8/2018 11:14
419421	CHECK D/S MIRROR	SCRATCHES	5/8/2018 11:14
419421	CHECK WIPERS	NOT WORK	5/8/2018 11:15
419421	CHECK SWIFTER KNOB(PLASTIC)	NEEDS NEW	5/8/2018 11:15
419421	CHECK WINDSHIELD	CRACKED	3/25/2018 8:38
419421	CHECK COOLANT LINE TO HYDRAULIC TANK	LOOPED DOWN	3/2/2018 9:51
419421	REPLACE HYDRAULIC TANK STRAPS	Normal	4/17/2018 15:35
419421	REPLACE HYDRAULIC FLUID	Normal	4/17/2018 15:36
419421	REPLACE EXHAUST STACK MOUNT	Normal	4/17/2018 15:37
419421	CHECK HOOD BUSHINGS	Normal	4/17/2018 15:38
419421	LEAKING COOLER	Normal	4/17/2018 15:38
419421	INSPECT STEERING U JOINTS	Normal	4/17/2018 15:39
419421	REPLACE FLAGGED HOSES	Normal	4/17/2018 15:39
419421	EXHAUST MANIFOLD LEAK	Normal	4/17/2018 15:40
419421	CORRECT BATTERY DISCONNECT	Normal	4/17/2018 15:40
419421	STEER AXLE SPRING STRAP BRACKET	Normal	4/17/2018 15:41
419421	TRANSMISSION LEAK	Normal	4/17/2018 15:42
419421	FUEL TANK SENDING UNIT WIRING	Normal	4/17/2018 15:42
419421	INSPECT 7 PIN CONNECTOR	Normal	4/17/2018 15:42
419421	REPLACE SLACK ADJUSTOR	Normal	4/17/2018 15:43
419421	Wheel Retorque	Field/Yard	2/13/2018 11:48
419421	CHECK GLADHANDS	Normal	2/6/2018 17:37
419421	STOP ENGINE LIGHT	Normal	2/6/2018 17:37
419421	REPAIR FIRE DAMAGE	DISCONNECT	1/25/2018 9:28
419421	coolant leak	Normal	1/24/2018 9:59
419421	ENGINE LIGHT ON	EXHAUST T	1/15/2018 10:17
419421	CHECK P/S AND D/S WINDSHIELD	CHIPPED	12/1/2017 10:29
419421	CHECK FAN HUB	LEAKING	1/12/2018 10:54
419421	D/S WINDOW NOT WORKING	Normal	1/7/2018 14:44
419421	D/S WINDSHIELD	Normal	1/7/2018 14:44
419421	SIDE STEP BROKEN	Normal	1/7/2018 14:45
419421	CHECK MARKER LIGHTS	Normal	1/7/2018 14:45
419421	CHECK P/S REAR FENDER	Normal	1/7/2018 14:45
419421	back up alarm not working	Normal	3/14/2017 14:11

419421 Hydraulic Fan switch not working
419421 Check Stairs on both sides
419421 Damage to step on Driver's side
419421 TRAILER PLUG ISSUES
419421 CHECK ENGINE LIGHT IS ON
419421 CHECK QUICK RELEASE VALVE
419421 CHECK D/S AND P/S WINDSHIELD
419421 Check Heater
419421 Check mirror bracket
419421 Check exhaust clamp
419421 Cummins Engine Valve Set
419421 DPF After Treatment Service

Normal 10/26/2017 7:45
Normal 10/26/2017 7:44
Hit a deer c Normal 9/29/2017 9:01
Normal 1/15/2018 12:06
Normal 11/20/2017 14:31
Normal 11/16/2017 17:15
LEAKING Normal 11/8/2017 11:43
Normal 10/26/2017 7:43
Normal 10/26/2017 7:44
Normal 10/26/2017 7:44
PM 9/21/2017 11:14
PM 9/21/2017 11:14