55195





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck			Seating Capacity:							
GVW:		14600 kg			Brake	Brake Type:		Hydra	Hydraulic			
Owner Nan	1e:	Pacific West Systems Supply Ltd.										
Address:	147	4735 Yellowhead Trail NW										
City:	Edn	Edmonton			Province:	AB			Post	Postal Code:		3C4
Telephone	Num	ber:	(780) 45	2-520	2							
Vehicle ide	ntific	ation Nu	mber:		2AYNF8JT	0K3S	14079					
Make:	ŀ	lino					Mode	el: Hino				
/ear: 2019							Unit Number:			491		
Odometer:	1	87810 K	м	Lice	nce Plate Nu	ımber:	В	ZW6478		Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:				
B N V Diesel Services Inc.		15679				
Inspection Technician Name):	Technician Number:				
Anantpreet Sekhon		C2629				
Inspection Technician Signa	ture:	Aront Stan				
Inspection Date:	2024/04/08					