

Make / Model: Arnes Side Lead Trailer VIN: 2A920312XBA003655

Year: 2011 Plate Number: 5CC570

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Removed wheels & changed wheel speed sensor (L) side	Joshua Hofer		5/Jan/18	
Replace ABS Sensor			19/Jan/18	
Dustsheild clamp-on kit	NAPA	011-86579	8/Jan/20	
Greased Unit, installed new dust sheild on 2nd axle	Justin Maier	Repair# 00317	8/Jan/20	
Worked on Solenoid and found a new one is required	Justin Maier	Repair# 00320	9/Jan/20	
Purchased Solenoid	NAPA	011-087046	10/Jan/20	
installed new solenoid valve to control diverter	Justin Maier	Repair# 00325	11/Jan/20	
Spiral hose, Coupling, Bearing ball	Matichuk	83249600	20/Jan/20	
Check & adjust brakes, grease axles, fix control valve	RBOL - Dan Howey	01137	19/Feb/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Fix Tire	Fountain Tire		30/Mar/17	
control line valve	Northern Truck & Ind		30/Mar/19	
Purchase Tubing,cplgs & bshgs,	NAPA	011-193731	7/Mar/22	
Pull valve bank apart, install ftgs for hoses, mount bank on side of trailer, hook up hyd lines, run 4 new air linesfrm spool to solenoids	RBOL - Dan Howey		7/Mar/22	
Replace main cylinder hyd line	RBOL - Dan Howey	01165	29/Mar/22	
Inspect & rebuild valve bank	Source Ind.	SB1-225074-00	8/Mar/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Change solenoid, check lights	Lee Godin		10/Apr/18	
Flat repair, rotate tires	Fountain Tire		20/Apr/18	
Fix air leak on valve bank at air solenoid, adjust brakes on all axles	RBOL - Dan Howey	D6502	4/Apr/22	
Change oil & filter	RBOL - Dan Howey	D6501	3/Apr/22	90065 kms
Purchase arctic trailer cable	NAPA	011-198856	9/Apr/22	
Fix right turn signal	RBOL - Dan Howey	D6506	8/Apr/22	
Purchase copper lugs	NAPA	011-199047	11/Apr/22	
Fix tarp motor	RBOL - Dan Howey	D6508	11/Apr/22	
Check and adjust brakes	RBOL - Dan Howey	D6514	26/Apr/22	
Replace solenoid for tarp	RBOL - Dan Howey	D6513	25/Apr/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Grease trailer	RBOL - J Lawrance	D6090	29/May/22	
Install 2 new tires, right rear	Elk Point Tire	1253	17/May/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
General Maintenance On Tarp	Kevin Entz		5/Jun/17	
Grease Unit & Adjust Brakes	Truck Zone		9/Jun/17	
Greased Unit, moved wire for end-dump lower solenoid	Justin Maier	WO #: 00416	14/Jun/20	
Purchase tarp gear motor	NAPA	011-209623	17/Jun/22	
Greases trailer,achecked hubs and oild tarps	RBOL - J Lawrance	D6011	18/Jun/22	
Purchase socket head capscrews	NAPA	011-210424	22/Jun/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
CVIP Inspection	HD Mechanical		25/Jul/16	
Welded pin	Trend Fabrication	Inv #: 2194	18/Jul/19	
Greased Unit	Justin Maier	DT #: 23631	31/Jul/20	
Adjust brakes & grease trailer	RBOL - D Howey	D6168	8/Jul/22	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Color: Leasing From:

Maintenance Record **Driver Log** Invoice / Daily **Work Completed** By Whom Generated Ticket / Service Date Report Y/N Replaced tarp relay in battery box & cord end Justin Maier DT #: 23641 27/Aug/20 **Greased Unit** Justin Maier 29/Aug/20 DT#: 23645 Replace front mrkr light psngr side **RBOL** - Dan Howey 18/Aug/22 1769 Purchase cable, LED light & pigtail 19/Aug/22 NAPA 011-1219594 Purchase rubber moulding NAPA 23/Aug/22 011-220057 Purchase rubber moulding NAPA 011-221322 30/Aug/22 Finish wiring top marker light, install new pigtailand light, tie up wires in back of trailer, remove seal off back **RBOL - Dan Howey** 1770 20/Aug/22 door Clean up back door after seal was removed, remove RBOL - Dan Howey 1771 27/Aug/22 fender Tarp needs replacing RBOL - Dan Howey D4946 23/Aug/23 Cut tarp off **RBOL - Dan Howey** 24/Aug/23 D4947 Install bearing on end of top shaft **RBOL** - Dan Howey D4948 25/Aug/23 Drop in yard. Tarp needs to be ordered **RBOL - Dan Howey** D4949 26/Aug/23 Purchase clearance markers NAPA 011-276562 23/Aug/23 Purchase brg & nuts & bolts NAPA 011-276788 24/Aug/23



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
new brakes and shoes	Truck Zone		25/Sep/18	
Slack adjuster	Napa		26/Sep/18	
Greased Unit	Justin Maier	DT # 23650	4/Sep/20	
Purchase rubber moulding	NAPA	011-221653	1/Sep/22	
Replace fenders	RBOL - Dan Howey	1773	1/Sep/22	
Install new tarp	RBOL - Dan Howey	D4892	30/Sep/23	



Grease & Inspect

Unit Number: 217

Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Color: Leasing From:

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Changed brakes	Kevin Entz		2/Oct/17	
Took Tires off	Jacob Hofer		9/Oct/17	
Purchase Hub & Gasket	NAPA	011-171244	8/Oct/21	
Purchase Camshaft kit, Brake drum and shoes	NAPA	011-170975	7/Oct/21	
Purchase Camshaft and seal	NAPA	011-171290	8/Oct/21	
Purchase lock washers	NAPA	011-171093	7/Oct/21	
Purchase Camshaft kits	NAPA	011-170451	3/Oct/21	
Purchase Lockwashers	NAPA	011-170772	5/Oct/21	
Purchase Brake shoes and drums	NAPA	011-170355	2/Oct/21	
Purchase Seal	NAPA	011-170369	2/Oct/21	
Inspect and Observe needs new brake drum	Dan Howey	D2943	2/Oct/21	
Remove Camshaft assembly	Dan Howey	D2944	3/Oct/21	
Install new camshaft bshngs, Brakes and drums	Dan Howey	D2945	4/Oct/21	
Pull all wheels and change rear axle , s-cams bshngs,	Dan Howey	D2946	7/Oct/21	
Install right front Axle	Dan Howey	D2948	10/Oct/21	
Purchase & Install Tires	Mallaig Tire	5226	15/Oct/21	

Bonnie's Equip Serv

INV-159

27/Oct/21



Make / Model: Arnes Side Lead Trailer

Year: 2011

Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Grease Unit	Bonnie's Equip Serv	INV-246	5/Nov/21	



Make / Model: Arnes Side Lead Trailer

Year: 2011 Plate Number: 5CC570

VIN: 2A920312XBA003655

Maintenance Record				
Work Completed	By Whom	Invoice / Daily Ticket / Service Report	Date	Driver Log Generated Y/N
Fix wiring & change valve	Lee Godin		18/Dec/17	
FIX WITHING & CHAINGE VALVE	Lee Godiii		10/Dec/1/	