


CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:		
GVW:	kg	Brake Type:	Air	
Owner Name:	Answer Trailer Rentals & Leasing LTD			
Address:	PO Box 3693 STN Main			
City:	Spruce Grove	Province:	AB	Postal Code: T7X3A9
Telephone Number:	(780) 960-8818			
Vehicle Identification Number:	5V8VC5327BM100841			
Make:	Vanguard	Model:	Tandem Van	
Year:	2011	Unit Number:	VN1877	
Odometer:	KM	Licence Plate Number:	6WA715	Province: AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Answer Trailer Rentals & Leasing Ltd.	18213
Inspection Technician Name:	Technician Number:
Paul Usher	C9875
Inspection Technician Signature:	
Inspection Date:	2025/05/28

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle		Gross Vehicle Weight registered																																																																																																																			
Trailer		kg																																																																																																																			
Vehicle Information																																																																																																																					
VIN	5	V	8																																																																																																																		
V	8	V	8																																																																																																																		
C	5	3	2																																																																																																																		
7	B	M	1																																																																																																																		
0	0	8	4																																																																																																																		
1																																																																																																																					
Unit Number	Year	Make	Model																																																																																																																		
VN1877	2011	Vanguard	Tandem Van																																																																																																																		
Registered Owner's Name		Plate Number																																																																																																																			
Answer Trailer Rentals & Leasing LTD		6WA715																																																																																																																			
Address		Postal Code	Phone Number																																																																																																																		
PO Box 3693 STN Main		T7X3A9	(780) 960-8818																																																																																																																		
Drum Brakes:		Disc Brakes:																																																																																																																			
B-Wheel-on Full Inspection																																																																																																																					
<table border="1"> <thead> <tr> <th colspan="2">LEFT</th> <th colspan="2">FRONT</th> <th colspan="2">RIGHT</th> </tr> </thead> <tbody> <tr> <td>100 psi</td> <td>419.47 mm</td> <td>Drums/Rotors</td> <td>419.66 mm</td> <td>100 psi</td> <td>419.66 mm</td> </tr> <tr> <td>13 mm</td> <td>14 mm</td> <td>Linings/Pads</td> <td>11 mm</td> <td>100 psi</td> <td>419.66 mm</td> </tr> <tr> <td>12 mm</td> <td>38 mm</td> <td>Push Rod Travel</td> <td>38 mm</td> <td>100 psi</td> <td>419.66 mm</td> </tr> <tr> <td>100 psi</td> <td>419.39 mm</td> <td>Drums/Rotors</td> <td>419.70 mm</td> <td>100 psi</td> <td>419.70 mm</td> </tr> <tr> <td>8 mm</td> <td>14 mm</td> <td>Linings/Pads</td> <td>15 mm</td> <td>100 psi</td> <td>419.70 mm</td> </tr> <tr> <td>6 mm</td> <td>38 mm</td> <td>Push Rod Travel</td> <td>38 mm</td> <td>100 psi</td> <td>419.70 mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>psi</td> <td>mm</td> <td>Drums/Rotors</td> <td>mm</td> <td>psi</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Linings/Pads</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> <tr> <td>mm</td> <td>mm</td> <td>Push Rod Travel</td> <td>mm</td> <td>mm</td> <td>mm</td> </tr> </tbody> </table>				LEFT		FRONT		RIGHT		100 psi	419.47 mm	Drums/Rotors	419.66 mm	100 psi	419.66 mm	13 mm	14 mm	Linings/Pads	11 mm	100 psi	419.66 mm	12 mm	38 mm	Push Rod Travel	38 mm	100 psi	419.66 mm	100 psi	419.39 mm	Drums/Rotors	419.70 mm	100 psi	419.70 mm	8 mm	14 mm	Linings/Pads	15 mm	100 psi	419.70 mm	6 mm	38 mm	Push Rod Travel	38 mm	100 psi	419.70 mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm	mm	mm	Push Rod Travel	mm	mm	mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm	mm	mm	Push Rod Travel	mm	mm	mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm	mm	mm	Push Rod Travel	mm	mm	mm	psi	mm	Drums/Rotors	mm	psi	mm	mm	mm	Linings/Pads	mm	mm	mm	mm	mm	Push Rod Travel	mm	mm	mm
LEFT		FRONT		RIGHT																																																																																																																	
100 psi	419.47 mm	Drums/Rotors	419.66 mm	100 psi	419.66 mm																																																																																																																
13 mm	14 mm	Linings/Pads	11 mm	100 psi	419.66 mm																																																																																																																
12 mm	38 mm	Push Rod Travel	38 mm	100 psi	419.66 mm																																																																																																																
100 psi	419.39 mm	Drums/Rotors	419.70 mm	100 psi	419.70 mm																																																																																																																
8 mm	14 mm	Linings/Pads	15 mm	100 psi	419.70 mm																																																																																																																
6 mm	38 mm	Push Rod Travel	38 mm	100 psi	419.70 mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
mm	mm	Push Rod Travel	mm	mm	mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
mm	mm	Push Rod Travel	mm	mm	mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
mm	mm	Push Rod Travel	mm	mm	mm																																																																																																																
psi	mm	Drums/Rotors	mm	psi	mm																																																																																																																
mm	mm	Linings/Pads	mm	mm	mm																																																																																																																
mm	mm	Push Rod Travel	mm	mm	mm																																																																																																																
Park Brake Lining Left NA mm Right NA mm Trans NA mm																																																																																																																					
Wheel Torque Checked ☒ Inner NA ft lbs Outer 500 ft lbs																																																																																																																					

V55R012018

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

Section 1 - Power Train			
Component	P	F	NA
1.2. Exhaust System			
1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			
NOTES:			
APPENDIX "A"			
Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			
A.2. Compressed Natural Gas (CNG) Fuel System			
NOTES:			
Section 2 - Suspension			
Component	P	F	NA
2.1. Suspension & Frame Attachments			
2.2. Axle Attaching & Tracking Components			
2.3. Axle & Axle Assembly			
2.4. Spring & Spring Attachment			
NOTES:			
Section 3H - Hydraulic Brakes			
Component	P	F	NA
3H.1. Hydraulic System Components			
3H.5. Air-Over-Hydraulic Brake System			
3H.7. Surge Brake Controller			
3H.8. Vacuum System			
3H.9. Air-Boosted Trailer Brake System			
NOTES:			
Section 3A - Air Brakes			
Component	P	F	NA
3A.3. Air System Leakage			
3A.4. Air Tank			
3A.5. Brake Valves & Controls			
3A.12. Parking Brake & Emergency Application			
3A.13. Air System Components			
3A.14. Brake Chamber			
3A.15. Drum Brake System Components			
NOTES:			
Section 4 - Steering			
Component	P	F	NA
4.1. Steering Control & Linkage			
4.5. Knap			
NOTES:			

V55R012018

P=PASS F=FAIL NA=Not Applicable

Page 2 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment			
Component	P	F	NA
5.1. Fire Extinguisher			
NOTES:			
Section 6 - Lamps			
Component	P	F	NA
6.1. Required Lamps			
6.2. Reflex Reflector			
NOTES:			
Section 7 - Electrical System			
Component	P	F	NA
7.1. Wiring			
7.2. Battery			
NOTES:			
Section 8 - Body			
Component	P	F	NA
8.5. Cargo Body			
8.6. Frame Rails & Mounts			
8.7. Utilized Body Elements			
8.8. Cab or Cargo Door			
8.9. Cargo Tank or Vessel			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			
NOTES:			
LR BOTTOM NEEDS REPAIR/repaid			
Section 9 - Tires and Wheels			
Component	P	F	NA
9.1. Tire Tread Depth			
9.2. Tire Tread Condition			
9.3. Tire Sidewall & Manufacturer Markings			
9.4. Tire Inflation Pressure			
9.5. Wheel Hub			
9.6. Wheel Bearing			
NOTES:			
Section 10 - Couplers and Hitches			
Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components			
10.2. Secondary Attachment (Safety Chain or Cable)			
10.3. Pinch Hook, Pin Hitch, or Coupler Hitch			
10.4. Ball Type Hitch			
10.5. Roll-Coupling Hitch			

V55R012018

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:			
Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8375388) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection	Technician Number	Facility Number	Signature
2025/05/28	C9875	18213	
Customer Acknowledgment			
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			
Date (Year/Month/Day)			Customer Signature
2025/05/28			

V55R012018

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4