

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass								
Component	P	F	NA	Component	P	F	NA	
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓			
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint			✓	
4.1e. Windshield Tinting / Decals			✓	4.2d. Side Window Visibility (general)	✓			
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓			
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓			

NOTES:

Section 5 - Lamps								
Component	P	F	NA	Component	P	F	NA	
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓			
5.2. Daytime Running Lamps			✓	5.8. Rear Side Marker Lamps	✓			
5.3. High Mount Brake Lamp			✓	5.9. Rear Side Reflectors	✓			
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓			
5.5. Auxiliary Lamps			✓	5.11. Emergency Lighting			✓	
5.6. Front Side Marker Lamps	✓							

NOTES:

Section 6 - Exterior, General								
Component	P	F	NA	Component	P	F	NA	
6.1. Fuel Cap	✓			6.3. Bumpers	✓			
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation			✓	

NOTES:

Section 7 - Under Hood								
Component	P	F	NA	Component	P	F	NA	
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder			✓	
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓			
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓			
7.4. Battery	✓			7.10. Oil Leaks	✓			
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓			
7.6. Brake Master Cylinder	✓							

NOTES:

Section 8 - Steering and Suspension								
Component	P	F	NA	Component	P	F	NA	
8.1. Wheel Bearings	✓			8.8. Steering Gear	✓			
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion			✓	
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System			✓	
8.4. Pitman Arm	✓			8.11. Control Arms	✓			
8.5. Idler Arm	✓			8.12. Struts and Shocks	✓			
8.6. Steering Stabilizer / Damper	✓			8.13. Springs	✓			
8.7. Steering Shaft Assembly	✓							

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels								
Component	P	F	NA	Component	P	F	NA	
9.1. Tread Depth- LF:8 mm,RF:8 mm,LR:8 mm,RR:8 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓			
9.2. Tire Condition (general)	✓			9.5. Wheels	✓			
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓			

NOTES:

Section 10 - Brakes								
Component	P	F	NA	Component	P	F	NA	
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:248.7 mm,RR:248.08 mm	✓			
10.2. Park Brake Lining- LR:4 mm,RR:4 mm	✓			10.6. Brake Rotor Thickness- LF:10.21 mm,RF:10.15 mm	✓			
10.2. Brake Lining- LF:8 mm,RF:8 mm,LR:4 mm,RR:4 mm	✓			10.7. Brake Drum Condition (general)	✓			
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Drum- LR:248.7 mm,RR:248.08 mm	✓			
10.4. Brake System Wiring	✓			10.9. Park Brake	✓			
10.5. Brake Rotor Condition (general)	✓							


NOTES:

Section 11 - Under Vehicle								
Component	P	F	NA	Component	P	F	NA	
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓			
11.2. Engine	✓			11.6. Floor Pan	✓			
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓			
11.4. Differential(s)	✓			11.8. Exhaust System	✓			

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #5833539)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/04/03	Technician Number A3153	Facility Number 18045	Signature 
Customer Acknowledgment I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2025/04/03 Customer Signature 