



RECEIVED
JUL 28 2015

GRANDE PRAIRIE
8601 - 102 STREET
CLAIRMONT, AB T0H 0W0-
(780)532-3175

INVOICE NO

108-4432

REMIT TO: PO BOX 2521 STN M,
CALGARY AB T2P 0T6

GST-SEE BELOW

BILL TO

TRICAN WELL SERVICE *
PO BOX 4001
9701 99 ST
CLAIRMONT, AB T0H 0W0-
T>348

ELMER CLARK - 780 8315744

PAGE 1 OF 4

*** CHARGE ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
22-JUL-2015	WOI#365708/PO545402	04-OCT-2011	XTA15-E10		KENWORTH
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
5133433		19-JUL-2015	79471505	CPL349100	T800
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
30758	60080		357577		510525

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
------------------	--------------	------------------	-------------	-------------	--------------	------------	--------

OSN/MSN/VIN 1XKDD40X7CJ951485

COMPLAINT

SYMPTOMS:
CHECK ENGINE LIGHT IS ON
CUSTOMER SAID CODE 3582 IS ON

CAUSE

C1638: ISX15 CM 2250 LUBRICATING OIL FILTER BYPASS VALVE
DSID#DSBHS1325(CLOSED)
CAMPAGIN C1638 BYPASS VALVE
DEF DOSER INJECTOR LEAKING.

CORRECTION

PERFORM JOB SAFETY ASSESSMENT (JSA)
STEAM CLEAN - COMPLETE ENGINE
INSITE - USE DURING TROUBLESHOOTING SIGNATURE ENGINES
LUBRICATING OIL FILTER BYPASS VALVE - REMOVE AND INSTALL - ISX15
CM2250
AFTERTREATMENT DIESEL EXHAUST FLUID SYSTEM LEAK TEST
AFTERTREATMENT DIESEL EXHAUST FLUID DOSING UNIT FILTER - REPLACE
AFTERTREATMENT DIESEL EXHAUST FLUID DOSING VALVE - REMOVE AND
INSTALL
AFTERTREATMENT DIESEL PARTICULATE FILTER RESTRICTION TEST
PERFORM JOB SAFETY ASSESSMENT (JSA)
STEAM CLEAN - COMPLETE ENGINE
INSITE - USE DURING TROUBLESHOOTING SIGNATURE ENGINES
LUBRICATING OIL FILTER BYPASS VALVE - REMOVE AND INSTALL - ISX15
CM2250
AFTERTREATMENT DIESEL EXHAUST FLUID SYSTEM LEAK TEST
AFTERTREATMENT DIESEL EXHAUST FLUID DOSING UNIT FILTER - REPLACE
AFTERTREATMENT DIESEL EXHAUST FLUID DOSING VALVE - REMOVE AND
INSTALL
REPLACED DEF LINE ENDS(BROKEN/LEAKING)
AFTERTREATMENT DIESEL PARTICULATE FILTER RESTRICTION TEST
PERFORM JOB SAFETY ASSESSMENT (JSA)
STEAM CLEAN - COMPLETE ENGINE
INSITE - USE DURING TROUBLESHOOTING SIGNATURE ENGINES

AVANTIS	
Alt Code:	2002-00-GPT-00
Subtotal:	2830.22
Approval:	
P.O. #:	545402

WIT 510525 Am8
W/O 365708

GST NUMBER - 83888 2256 RT

TERMS: FOB Point of Origin, NET 30 DAYS FROM DATE OF PURCHASE. I/we hereby agree to accept title and risk of loss at the time of the shipment and acknowledge the indebtedness of this invoice. If the balance due isn't paid within credit terms, I agree to pay interest at 1.5%/month (19.6%/annum) both before and after judgement plus all cost incurred in the collection of the balance owing; including legal fees and disbursements on a solicitor/client basis.

AUTHORIZED BY (print name)

SIGNATURE

DATE



GRANDE PRAIRIE
8601 - 102 STREET
CLAIRMONT, AB T0H 0W0-
(780)532-3175

INVOICE NO

108-4432

REMIT TO: PO BOX 2521 STN M,
CALGARY AB T2P 0T6

GST-SEE BELOW

BILL TO

TRICAN WELL SERVICE *
PO BOX 4001
9701 99 ST
CLAIRMONT, AB T0H 0W0-
T>348

ELMER CLARK - 780 8315744

PAGE 2 OF 4

*** CHARGE ***

DATE		CUSTOMER ORDER NO.		DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE	
22-JUL-2015		WOI#365708/PO545402		04-OCT-2011	XTA15-E10		KENWORTH	
CUSTOMER NO.		SHIP VIA		FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL	
5133433				19-JUL-2015	79471505	CPL349100	T800	
REF. NO.		SALESPERSON		PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.	
30758		60080			357577		510525	
QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION		PRODUCT CODE	UNIT PRICE	AMOUNT

OSN/MSN/VIN 1XKDD40X7CJ951485

LUBRICATING OIL FILTER BYPASS VALVE - REMOVE AND INSTALL - ISX15
CM2250

AFTERTREATMENT DIESEL EXHAUST FLUID SYSTEM LEAK TEST

AFTERTREATMENT DIESEL EXHAUST FLUID DOSING UNIT FILTER - REPLACE

AFTERTREATMENT DIESEL EXHAUST FLUID DOSING VALVE - REMOVE AND
INSTALL

REPLACED DEF LINE ENDS(BROKEN/LEAKING)

AFTERTREATMENT DIESEL PARTICULATE FILTER RESTRICTION TEST

VEHICLE STEPS - REMOVE AND INSTALL

BULL BAR - REMOVE AND INSTALL

EXHAUST HEAT SHIELD (OEM INSTALLED) - REMOVE AND INSTALL

AFTERTREATMENT DIESEL OXIDATION CATALYST - REMOVE AND INSTALL

AFTERTREATMENT DIESEL PARTICULATE FILTER - REMOVE AND INSTALL

AFTERTREATMENT SCR CATALYST - REMOVE AND INSTALL

REGEN UNIT TO CONFIRM REPAIR

COVERAGE

PRODUCT COVERAGE EXPIRED

CAMPAGIN C1638 FACTORY WARRANTY

DOSING INJECTOR CUSTOMER BILLABLE

REMARK

BASE WARRANTY DETAILS

MONTHS :24 ,MILES :250000 ,KILOMETERS :402336 ,HOURS :6250

-SEE CAMPAIGN DETAILS FOR SPECIFIC INSTRUCTIONS AND ESN LISTINGS

-SRTS TO GAIN ACCESS MAY BE CLAIMED WITH SUFFICIENT DETAIL IN CLAIM
NARRATIVE

-CAMPAIGN WILL BE COVERED DURING THE BASE WARRANTY PERIOD

-TRAVEL IS COVERED UNDER THIS CAMPAIGN. TOWING IS NOT.

-CONSUMABLES ARE NOT COVERED UNDER THIS CAMPAIGN.

NOTE: WHEN TRAVEL IS NEEDED, PLEASE PLAN AHEAD TO PERFORM THE
CAMPAIGN ON MULTIPLE UNITS WHENEVER POSSIBLE AND FILE MULTI-ESN
CLAIMS ACCORDINGLY. WHEN FILING CLAIMS FOR MULTIPLE ESNs, WHERE

GST NUMBER - 83888 2256 RT

TERMS: FOB Point of Origin, NET 30 DAYS FROM DATE OF PURCHASE. I/we hereby agree to
accept title and risk of loss at the time of the shipment and acknowledge the indebtedness of this
invoice. If the balance due isn't paid within credit terms, I agree to pay interest at 1.5%/month
(19.6%/annum) both before and after judgement plus all cost incurred in the collection of the
balance owing; including legal fees and disbursements on a solicitor/client basis.

AUTHORIZED BY (print name) _____ SIGNATURE _____ DATE _____



GRANDE PRAIRIE
8601 - 102 STREET
CLAIRMONT, AB T0H 0W0-
(780)532-3175

INVOICE NO

108-4432

REMIT TO: PO BOX 2521 STN M,
CALGARY AB T2P 0T6

GST-SEE BELOW

BILL TO

TRICAN WELL SERVICE *
PO BOX 4001
9701 99 ST
CLAIRMONT, AB T0H 0W0-
T>348

ELMER CLARK - 780 8315744

PAGE 4 OF 4

*** CHARGE ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
22-JUL-2015	WOI#365708/PO545402	04-OCT-2011	XTA15-E10		KENWORTH
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
5133433		19-JUL-2015	79471505	CPL349100	T800
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
30758	60080		357577		510525

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
			1XKDD40X7CJ951485	OSN/MSN/VIN			

TOTAL LABOR: 1,836.00
MISC.: 146.88
MISC. COVERAGE CREDIT: 0.00CR
TOTAL MISC.: 146.88
CWC ENVIRO FEES 36.72
CWC SHOP SUPPLIES 110.16

WARRANTIES APPLIED: FACTORY

GST 141.51

GST NUMBER - 83888 2256 RT

TERMS: FOB Point of Origin, NET 30 DAYS FROM DATE OF PURCHASE. I/we hereby agree to accept title and risk of loss at the time of the shipment and acknowledge the indebtedness of this invoice. If the balance due isn't paid within credit terms, I agree to pay interest at 1.5%/month (19.6%/annum) both before and after judgement plus all cost incurred in the collection of the balance owing; including legal fees and disbursements on a solicitor/client basis.

SUB TOTAL: 2,830.22
TOTAL TAX: 141.51

TOTAL AMOUNT: CA \$ 2,971.73

AUTHORIZED BY (print name) _____ SIGNATURE _____ DATE _____

Trican Goods Receipt

Vendor Name : CUMMINS WESTERN CANADA

Received by : Snyder, Anne

PO # : 545402

Received on	PCI Desc.				PCI #	Vendor part number
Qty ordered	Qty Recieved	Unit Cost	Extended Cost	Unit #	G/L Account	Base

Packing slip # : 1084432

PO Line # : 1

8/14/2015 15:26	ENGINE / AIR CONDITIONER SERVICE & LABOUR		SERVICE - ENGINE/AC			
1 each	1 each	C\$2,830.220 each	C\$2,830.22	510525	6020-WS-EDT-NI	GP2

Packing Slip Total : \$2,830.22

PO Total : \$2,830.22