

APPRAISAL

CONCORDE SPECIALTY VEHICLE SERVICES

P. O. Box 189
Stettler, Alberta
T0C-2L0
E-mail: conapp@telus.net
Phone (780) 387-6351
Fax (403) 742- 0850

To whom it may concern:

This is to certify that on October 23, 2016 that I have carefully examined the following listed and described Vehicle, for the purpose of an appraisal, the said property of and at the request of:

Name
Street
City
Province
Postal



Vehicle Description Year: 1973
Manufacturer: FORD MOTOR COMPANY
Model: FORD MUSTANG MACH 1
Body Type: 2 DOOR SPORTSROOF
V.I.N.: 3F05H130309
Odometer Reading: 35,550 MILES
License Plate Number: BRK-3396

To the best of my knowledge and ability I hereby state the value of the aforementioned vehicle in Canadian currency to be:

Appraised Value **\$41,900.00**

The foregoing appraised value is made with the understanding that the Appraiser assumes no liability whatsoever with respect to any action that may be taken on the basis of this appraisal. The onus is on the client, if said client has misrepresented the above described vehicle either by negligence or intentional means to Concorde Specialty Vehicle Services. No mechanical inspection is included with the appraisal; and no warranties or guarantees stated or implied.

I hereby do certify that I or Concorde Specialty Vehicle Services have no interest in the vehicle being appraised and that the fee or the employment to make this appraisal is not contingent upon the vehicle valuation.

Please find (20) photographs attached.

Appraiser:

ALBERT MIKULECKY

Date:

Oct 23 / 2016

Member Of Specialty Vehicle Appraisal Institute Of Alberta

VEHICLE INFORMATION

General

Type Of Vehicle : Antique (X) Classic () Custom () Special interest () Modified () Race ()

Restoration: Yes (X) No () In process () Year restored: 2008

Restoration Work : Personally () Professionally (X) Percent professionally restored 100 %

Repair Invoices: Shown () Not shown () Available as per owner (X) Not available as per owner ()

Storage: Open Area () Enclosed area () Garage () Other building (X) Car cover utilized (X)

Engine

Manufacturer: FORD

Original (X) Correct replacement () Replacement () Aftermarket () Modified (X) Year Installed:
Year rebuilt: 2008

Engine Paint Condition: VERY GOOD

Engine Size: 351 V8 Horsepower rating: 157 PLUS Fuel: Gas (X) Diesel () Propane ()

Carburetion: Original () Replacement (X) 1 bbl () 3 x 2 bbl () 4 bbl (X) 6 bbl () 8 bbl () Fuel injected ()

Exhaust Manifolds: Original () Aftermarket () Headers (X)

Engine Wiring: Original () Aftermarket (X) Correct () Date coded () Condition: VERY GOOD

Ignition: Original (X) Aftermarket () Correct () Electronic ()

Fuel Lines: Original () Aftermarket (X) Correct () Condition: VERY GOOD

Vacuum Lines: Original (X) Aftermarket () NA () Condition: VERY GOOD

Engine Modification: CAMSHAFT. INTAKE MANIFOLD

Engine Dress Up Features: VALVE COVERS , AIR CLEANER , OIL BREATHER CAP

Engine Compartment

Cleanliness Condition: VERY GOOD

Battery: Original () Aftermarket (X) Year installed: 2008

Battery Cables: Original () Aftermarket (X) Correct () Condition: VERY GOOD

Hoses: Original () Aftermarket (X) Correct (X) Condition: VERY GOOD
Hose Clamps: Original () Aftermarket (X) Correct () Condition: VERY GOOD
Radiator: Original (X) Replacement () Correct () Condition: VERY GOOD
Overflow Tank: Original () Aftermarket (X) Correct () Missing () NA () Condition: VERY GOOD
Wiring: Original (X) Aftermarket () Correct tie downs & Tape () Condition: GOOD
Hood Insulation: Original () Aftermarket () Correct () Missing () NA (X) Condition:
Hood: Original (X) Aftermarket () Fresh air () Shaker () Cowl Ind. ()
Brake Reservoir: Original (X) Aftermarket () Correct () Single reservoir () Dual reservoir (X)

Transmission

Manufacturer: FORD

Original (X) Replacement () Modified () Year replaced: Year rebuilt: 2008

Type: Automatic (X) Standard () No. of Speeds (2) (3) X (4) (5) (6)

Body

Original (X) Modified ()

Overall Condition: Excellent () Very good (X) Good () Fair () Poor ()

Observations: Visible rust () Scratches () Rock marks () Dents () Visible repairs ()
Orange peel ()

Colour Style: Solid (X) Two tone () Special Effect ()

Paint Colour: MED. BLUE Original paint () Original color (X) Year painted: 2008

Paint Condition: Excellent () Very good (X) Good () Fair () Poor ()

Bright Work/Chrome

Front Bumper: Original (X) Rechromed () Replacement () Condition: VERY GOOD

Grille: Original (X) Aftermarket () Condition: VERY GOOD

Front Bezels: Original (X) Aftermarket () Missing () Condition: GOOD

Rear Bumper: Original (X) Rechromed () NA () Condition: VERY GOOD

Rear Bezels: Original (X) Rechromed () Condition: VERY GOOD

Side Bezels: Original (X) Rechromed () NA () Condition: VERY GOOD

Mirrors: Original (X) Rechromed () Single () Dual (X) Power () Custom () Condition: VERY GOOD

TOP

Convertible Top Type: Manual () Power () Glass () Plastic () Original fabric () Other fabric ()

Convertible Top condition: Clean () Soiled () Tears ()

Vinyl Roof: Yes () No (X) Colour: Condition:

Sun Roof: Yes () No (X) Factory () Manual () Power ()

Opera Windows: Yes () No (X) Condition:

Lights

Standard (head/turn/brake): Original (X) NA () Custom () Condition: VERY GOOD

Fog/Spot Lights: Original () NA (X) Custom () Condition:

Engine Compartment: Original () NA (X) Custom () Missing () Works ()

Trunk Light: Original () NA (X) Custom () Missing () Works ()

Underside

Original (X) Undercoated () Correct () Painted () Condition: GOOD

Rear Axle & Differential

Original (X) Aftermarket () Limited slip (X)

Glass

Windshield: Original () Aftermarket (X) Standard () Tinted (X) Cracked () Chipped () Pitted ()
Scratched () Condition: VERY GOOD

Rear: Original (X) Aftermarket () Standard () Tinted (X) Cracked () Chipped () Pitted ()
Scratched () Condition: VERY GOOD

Other Glass: Original (X) Aftermarket () Standard () Tinted (X) Cracked () Chipped () Pitted ()
Scratched () Condition: VERY GOOD

Trunk

Original (X) Painted () Condition: GOOD

Trunk Mat: Original () Replacement (X) Missing () NA () Condition: VERY GOOD

Spare Wheel Cover: Original () Replacement (X) NA () Missing () Condition: VERY GOOD

Jack: Original (X) Replacement () NA () Missing () Condition: VERY GOOD

Exhaust

Exhaust: Original () Aftermarket (X) Single () Dual (X) Standard () Aluminized (X) Stainless steel ()

Exhaust Condition: VERY GOOD

Exhaust Extensions: Original () Aftermarket (X) Correct (X) NA () Condition: VERY GOOD

Wheels

Wheel Type: Original () Optional () Aftermarket (X) Wheel Covers () Rally () Aluminum (X)

Wheel Condition: VERY GOOD

Tires

Tire Type: Radials (X) Bias ply () Black wall () Whitewall () Redline () Raised lettering (X)

Tire Condition: Excellent () Very Good (X) Good () Fair () Poor ()

Front Tire Make & Size: BF GOODRICH P215/60 R14 5 % Wear

Rear Tire Make & Size: BF GOODRICH P235/60 R15 5 % Wear

Spare Tire : YES

Interior

Interior Type: Original (X) Modified ()

Rt Door Panel: Original () Reproduction (X) Reupholstered () Condition: VERY GOOD

Lt Door Panel: Original () Reproduction (X) Reupholstered () Condition: VERY GOOD

Rt Rear Panel: Original () Reproduction (X) Upholstered () Condition: VERY GOOD

Lt Rear Panel: Original () Reproduction (X) Upholstered () Condition: VERY GOOD

Front Seats: Original () Reproduction (X) Reupholstered () Condition: VERY GOOD

Rear Seat: Original () Reproduction (X) Reupholstered () Condition: VERY GOOD

Headliner: Original (X) Reproduction () Reupholstered () Condition: VERY GOOD

Floor Covering: Original () Reproduction (X) Reupholstered () Condition: VERY GOOD

Seat Belts: Original (X) Reproduction () None () Condition: VERY GOOD

Dash Pad: Original (X) Reproduction () Reupholstered () Condition: VERY GOOD

Weather-stripping

Door opening Condition: Excellent () Very Good (X) Good () Fair () Poor () NA ()

Trunk opening Condition: Excellent () Very Good (X) Good () Fair () Poor () NA ()

Vent window & glass-run channel: Excellent () Very Good () Good () Fair () Poor () NA (X)

Side glass sealing Condition: Excellent () Very Good (X) Good () Fair () Poor () NA ()

Roofrail Condition: Excellent () Very Good (X) Good () Fair () Poor () NA ()

Instrumentation/Options

Air Conditioning: Yes () No (X) Original () Reproduction () Works ()

Clock: Yes (X) No () Original (X) Reproduction () Works ()

Radio: Yes (X) No () Original () Replacement (X) Works (X)

Radio Type: AM () AM/FM (X) Cassette (X) 8-Track () CD ()

Tachometer: Yes (X) No () Original (X) Reproduction () Works (X)

Cruise: Yes () No (X) Original () Reproduction () Works ()

Tilt: Yes () No (X) Original () Aftermarket () Works ()

Bucket Seats: Yes (X) No () Original (X) Replacement ()

Floor Shift: Yes (X) No () Original (X) Reproduction ()

Power Brakes: Yes () No (X) Original () Reproduction ()

Power Steering: Yes () No (X) Original () Reproduction ()

Power Seat: Yes () No (X) Original () Reproduction () Works ()

Power Windows: Yes () No (X) Original () Reproduction () Works ()

Power Locks: Yes () No (X) Original () Reproduction () Works ()

Power Trunk: Yes () No (X) Original () Reproduction () Works ()

R. Window Def: Yes () No (X) Original () Replacement () Works ()

Theft Deterrent: Yes () No (X) Original () Aftermarket () Works ()

Aftermarket Gauges: Temp () Oil () Volts () Tach ()

Safety Systems

Driver Air Bag () Pass. Air Bag () Side Impact Bags () Roll Bar () Fire Extinguisher ()

SUMMARY : VERY FEW MILES HAVE BEEN DRIVEN ON THIS OLDER PROFESSIONAL RESTORATION THAT STILL SHOWS VERY WELL. THE OVER ALL STOCK APPEARANCE HAS BEEN RETAINED IN ALL AREAS. AFTERMARKET WHEELS, TIRES, POLISHED VALVE COVERS AND A CHROME AIR CLEANER HAVE BEEN ADDED TO HI-LIGHT THE TOTAL PACKAGE.

THE HIGH PERFORMANCE ENGINE STARTS IMMEDIATELY, RUNS AS A NORMAL HIGH PERFORMANCE ENGINE WITH NO ABNORMAL NOISE AND SHOWS NO SIGNS OF BURNING OIL.

NUMBER OF UNIT BUILT : 35,440

SERIAL NUMBER BRAKE DOWN : 3F05H130309

3 = 1973

F = DEARBORN ASSEMBLY PLANT

05 = MUSTANG MACH 1

H = 351 V8 2BBL.

130309 = SEQUENTIAL PRODUCTION NUMBER

VALUE CHECK: NATIONAL AUTOMOBILE DEALERS ASSOCIATION

CARSFORSLE.COM SW DYNAMIC MOTORSPORTS GARLAN, TEXAS

CLASSICCARS.COM TUPELO, MISSISSIPPI

CARSONLINE.COM DALLAS, TEXAS

CARSONLINE.COM RICHMOND, VIRGINIA

TOTAL VALUE IN UNITED STATES DOLLARS \$31,300.00

CONVERSION RATE FROM US DOLLARS TO CANADIAN 1.33946

TOTAL VALUE IN CANADIAN DOLLARS \$41,900.00 ROUND TO NEAREST 100

CONDITION RATING

EXCELLENT: Restored to current professional standards of quality in every area; or original with all components operating and appearing as new. This vehicle is true show car quality and is never driven and is transported in a closed trailer.

VERY GOOD: Well restored or combination of superior restoration and excellent original (showing minimal wear).

GOOD: Completely operable original or older restoration showing some wear or amateur restoration. Also referred to as average condition. Known as a 20 footer. From 20 feet away it may look perfect.

FAIR: Deteriorated restoration or a very poor amateur restoration. All components may need restoration.

POOR: Needs complete restoration.

PARTS CAR: Useful primarily for parts.







