

Sale Name: September 26, 2025 - Friday Major Automotive & Recreational Live & Timed Auction

LOT 163 - 2015 Honda Civic LX



VIN 2HGFB2E57FH015895

Year 2015

Make Honda

Model Civic

Trim Level LX

Engine 1.8

Transmission 5 SPEED

Odometer 181,065 KM

Odo Type KM

Color Grey

Comments Drivetrain - FWD - MVI - 5/27 - Warning lights - Low fuel, check airbag system, low washer fluid - Oil level - Low - Tire comments - Front 3/32, 205/55R16, rear 2/32, T135/60R15, spare tire rear left - Features - Pwr windows, pwr locks, pwr mirrors, manual seats, cruise control, infotainment system, tilt, sunroof, heated seats, heated mirrors - Technology - CD player, bluetooth, backup camera - AC & Heat functioning - Standard seating, 4 door - Odor - Musty, animal - Interior condition - Good - Trim - Cloth - Comments - Headliner/seats/carpet stains, seats burn holes, headliner tears, trim pieces/battery stay bracket in trunk, cluster clear screen cover cracks - Exterior condition - Good - Comments - Front left fender scratches/paint chips, front left door scratches/dents/paint peeling/rust/missing trim piece/foot sill dents/scratches, rear left door residue/scratches/paint chips/door sill scratches/door doesn't stay open, left C pillar dents, rear left fender dents/scuffs/scratches, left rocker paint bubbling/rust, rear bumper gouges/scratches/scuffs/dents, trunk scrapes/paint chips/aftermarket badges placed, right rear fender scuffs/scratches/dents, right rocker dents/rust, right rear door scratches/paint chips/dents/door sill dents/scuffs/scratches, front right door dents/scratches/paint chips/door sill rust, front right fender scratches/paint chips/rust/dents, front bumper scratches/paint chips, hood dents/scratches/paint chips, headlights fogged, windshield chips, roof dents/scratches.

Location Fredericton NB - Jardine

Unit No. 31100430

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) 05/27

Description

****Vehicle starts with boost, vehicle on dummy tire**

BANK REPOSSESSION

[CARFAX - Misc. claim \\$0, Vandalism claim \\$0, Collision claim \\$6,313](#)

VIN 2HGFB2E57FH015895

Year 2015

Make Honda

Model Civic

Trim LX

Engine 1.8

Transmission 5 SPEED

Odometer: 181,065 KM, KM

Color Grey

Comments Drivetrain - FWD - MVI - 5/27 - Warning lights - Low fuel, check airbag system, low washer fluid - Oil level - Low - Tire comments - Front 3/32, 205/55R16, rear 2/32, T135/60R15, spare tire rear left - Features - Pwr windows, pwr locks, pwr mirrors, manual seats, cruise control, infotainment system, tilt, sunroof, heated seats, heated mirrors - Technology - CD player, bluetooth, backup camera - AC & Heat functioning - Standard seating, 4 door - Odor - Musty, animal - Interior condition - Good - Trim - Cloth - Comments - Headliner/seats/carpet stains, seats burn holes, headliner tears, trim pieces/battery stay bracket in trunk, cluster clear screen cover cracks - Exterior condition - Good - Comments - Front left fender scratches/paint chips, front left door scratches/dents/paint peeling/rust/missing trim piece/foot sill dents/scratches, rear left door residue/scratches/paint chips/door sill scratches/door doesn't stay open, left C pillar dents, rear left fender dents/scuffs/scratches, left rocker paint bubbling/rust, rear bumper gouges/scratches/scuffs/dents, trunk scrapes/paint chips/aftermarket badges placed, right rear fender scuffs/scratches/dents, right rocker dents/rust, right rear door scratches/paint chips/dents/door sill dents/scuffs/scratches, front right door dents/scratches/paint chips/door sill rust, front right fender scratches/paint chips/rust/dents, front bumper scratches/paint chips, hood dents/scratches/paint chips, headlights fogged, windshield chips, roof dents/scratches.

Location Fredericton NB - Jardine

In Yard Yes

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI 05/27

Quantity: 1



<https://www.maauctions.com/>