

**Sale Name:** September 26, 2025 - Friday Major Automotive & Recreational Live & Timed Auction

**LOT 82 - 2016 Chevrolet Express 2500**



**VIN** 1GCWGAFF2G1216413

**Year** 2016

**Make** Chevrolet

**Model** Express

**Trim Level** 2500

**Engine** Vortec 4.8L V8 285hp 295ft. lbs.

**Transmission** 6-Speed Shiftable Automatic

**Odometer** 476 193

**Odo Type** KM

**Color** White

**Comments** Warning lights - Traction control, ABS - Features - Pwr locks, pwr windows, hitch, tilt, manual seats - AC & Heat functioning - Exterior comments - Multiple scratches/paint chips, front left door rust/inner door rust/doorsill rust, left panel dents/rust, rear left fender rust, rear bumper rust, rear doors rust, right rear panel dents, right rear fender rust/taillight missing, right side doors dents/rust, front right door rust/inner door/doorsill rust, front bumper dents/rust, hood rust, windshield crack chips.

**Location** Fredericton NB - Jardine

**Tires** Front 9/32, LT245/75R16E, scalloped, rear 8/32, LT245/75R16E

**Sales Status** Red Light - Sold AS IS

**Plate Date (Jardine)** None

**Plate Number (Jardine)** None

**MVI (Jardine)** None

**Description**

**\*Vehicle loud possible exhaust leak, tick coming from engine bay under acceleration, left rear door does not open, passenger side mirror broken**

FLEET VEHICLE

**Vin** 1GCWGAFF2G1216413

**Year** 2016

**Make** Chevrolet

**Model** Express

**Trim** 2500

**Engine** Vortec 4.8L V8 285hp 295ft. lbs.

**Transmission** 6-Speed Shiftable Automatic

**Odometer** 476 193, KM

**Color** White

**Comments** Warning lights - Traction control, ABS - Features - Pwr locks, pwr windows, hitch, tilt, manual seats - AC & Heat functioning - Exterior comments - Multiple scratches/paint chips, front left door rust/inner door rust/doorsill rust, left panel dents/rust, rear left fender rust, rear bumper rust, rear doors rust, right rear panel dents, right rear fender rust/taillight missing, right side doors dents/rust, front right door rust/inner door/doorsill rust, front bumper dents/rust, hood rust, windshield crack chips.

**Location** Fredericton NB - Jardine

**In Yard** Yes

**Tires** Front 9/32, LT245/75R16E, scalloped, rear 8/32, LT245/75R16E

**Sales Status** Red Light - Sold AS IS

**Plate Date** None

**Plate Number** None

**MVI** None

**Quantity:** 1



<https://www.maauctions.com/>